

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

113

S.W. Corner DLC No. 42

and S.E. Corner DLC No. 43.

Found - $\frac{1}{2}$ " Pipe set by Cole in 1915, See Ren. #4, a new, galv. $\frac{1}{2}$ "
Pipe & a $1\frac{1}{2}$ " galv. Pipe alongside, Ren. #37.

Fir, uprooted & down, N. $87\frac{1}{2}$ °W. 19.7 ft., lying face down.
No trace of S.E. BT.

New BT's: 5" D. Fir N. 85 °W. 12.5 ft. Mkd: DLC 43 CS BT.
6" D. Fir N. 65 °W. 27.5 ft. Mkd: DLC 43 CS BT.

No trees large enough to mark east of line.

Note - Corner is on nose of small spur, sloping very steeply to
the north, approximately 150 ft. south of foot of hill
and directly in line with a new fence line extending
from foot of hill north to the river.

FD OK PER DOLAN
M 109 - 6 SEPT. 1989

114

N.W. Corner D. L. C. No. 42 & N. E. Cor. DLC No. 43.

Found - $\frac{1}{2}$ " I. Pipe set by Irving, 1945, See Ren. #5 & #38. Pipe
buried approximately 1 foot deep in sand.

Stump of W. Oak S. 59 °W. 42.3 ft., shows very plain "BT"
scar, did not open. Stump recently cut.

Stump hole & rotted remains of Ash N. 87 °W. 65.3 ft. Trunk
buried in sand.

New BT's: 13" Maple N. 47 °W. 4.5 ft. Mkd: NE DLC 43 CS BT.

14" Maple S. 5 °W. 30.8 ft. Mkd: NE DLC 43 CS BT.

No trees near east of line.

Note - Iron Pipe is at North end of N. & S. fence line.

Milo E. Godfrey, Deputy
Wm. Stoffel & Mike Stone
September 1964
C. S. File No. 52/14.

115

Interior "L" Corner D. L. C. No. 44.

Found - 18" D. Fir N. 38 °E. 13.0 ft., scribing visible on not
completely healed over scars.

Brass cap, not found, A slide has covered portion of road
at this point, Brass Cap probably buried under logs,
rocks and dirt. See Ren. #46.

No trace of N.W. Tree mkd. in 1955, probably buried in slide.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T22S R8W Int. "L" DLC 44

New BT: 15" D. Fir N. 45 °W. 17.3 ft. Mkd: Int. L DLC 44 CS BT.

7/12/73 Fd. O.K. V.R.T. C.S. 56/34

116

Wit. Cor. N.E. N.W.

DLC 44 / DLC 43

Found - Old, Cottonwood, down & dead, S. 6 °E. 44.9 ft., cut open
& found good scribing "43" & "S". See Ren. #6.

No trace of any other BT's.

Note - Corner position falls on steep bank, sloping down to river,
subject to washing during high water.

Set - Wit. Cor. 55 ft. south - Iron Pipe with Brass Cap Mkd:
County Surveyor's Office, 1964 T22S R8W W.C. DLC

55' N. to Corner. 44 / 43

New BT's: 42" W. Oak S. $33\frac{1}{2}$ °E. 409.8 ft. Mkd: W C NW DLC 43 CS BT.

23" W. Oak S. $27\frac{1}{2}$ °E. 389.1 ft. Mkd: NS DLC 43 CS BT.

Note - Corner is in remains of old N. & S. Fence Line.

No suitable trees available nearby.

FD BT'S PER WEATHERLY
CS. 63/43 10/86

RECORDED & INDEXED
CORNER NO. #191

117

N. W. Cor. DLC #44 and N. E. Cor. DLC #45.

Found - "T" Iron set by Haines, 1955, buried about 12" in sand
along river bank. Ren. #11 & #111.

42" W. Oak N. $88\frac{1}{2}$ °E. 458.7 ft., shows good scars, good cond.

W. Oak Stump S. $3\frac{1}{2}$ °W. 60.4 ft., shows good scar.

Set - Wit. Cor. 65 ft. south of DLC Cor. Set Brass Cap Mkd:

County Surveyor's Office, 1964 W.C. 65 ft. North to Corner.

T22S R8W N.E. N.W. W.C. is on top of high bank of river.

DLC 45 | DLC 44

New BT: 22" W. Oak S. 1 °W. 93.9 ft. Mkd: WC NE DLC 45 CS BT.

Note - A power line pole mkd. "6-306 307" bears N. 80 °E. 22.3 ft.

Fd OK, 1194, M120-49A & B