

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 T. S. R. 8 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 91881

177

John Minor  
For: Menasha Corporation  
May, 1994  
M 118 - 72

1/4 Corner for Sections 6 & 7.  
Found - 3" 1963 BLM BC/IP under root wad of G.L.O. cor. tree.  
Fd. BT's (G.L.O.) -  
32" D.Fir stump, N.7°E., 13.2 ft. rotten face.  
26" D.Fir stump, S.20°E., 25.1 ft. rotten face.  
Fd. BT's (B.L.M.) -  
23" D.Fir, N.19 $\frac{1}{2}$ °W., 56.1 ft. healed face.  
New BT -  
10" D.Fir, N.84°W., 14.0 ft. scribed " $\frac{1}{4}$  S5 BT"

178

Ken Hoffine  
For: Lone Rock Timber  
Oct. 1994  
C.S. File 63/154

S.W. Corner DLC 54  
Found - BLM 2 $\frac{1}{2}$ " brass cap on 1" iron pipe buried in mud of the washed  
bank on the stream, rotten hemlock stump remains (orig. corner)  
washed out down stream. See Renewal # 127.  
Set - We reset monument by distances given in the 1964 corner notes of  
the bearing trees for the corner.  
BTs Fd- 46" Western R.Cedar bears N.10°E., 93.7 ft. (rec. N.9°E., 93.72 ft.)  
25" D.Fir bears S.74°30'E., 52.1 ft. BLM tag, healed scar.  
28" Western R.Cedar bears N.49°30'E., 74.3 ft. (rec. N.48°E., 74.58  
ft.) BLM tag, healed scar.  
New Accessories -  
We tagged 46" Western Red Cedar. We painted faces and painted "BT"  
on trees.  
Note - Corner lies in the bottom of a small creek bed. The creek lies in  
a steep North-South ravine.