

Douglas County Surveyor's Record of  
Government Corners Renewed

22 T. S. 9 R. W. W. M.

100% CHAPMAN CO., EUGENE, ORE. 91002

Section corner 4 & 9.

Find C.C. S 4 & 9 at which point I set a 3 inch Fir Post marked CC S 4 & 9 <sup>SEE #72</sup>

#17-Section corner West  $\frac{1}{4}$  Section 4. At this corner set a 4 inch Fir limb post  
Marked  $\frac{1}{4}$  S 4, P.S. 253, for which: A fir 24Inch bears N 46° E. 56.9 feet.  
A root of a 60 inch fir bears S 35° E 4.1 ft.

#18-Section corner North  $\frac{1}{4}$  Sec. 4. At this corner set a 4 inch fir post marked  
 $\frac{1}{4}$  S 4 from which: A fir 40 inch diam. bears S 57° E, 87.0 feet.

#19-Center  $\frac{1}{4}$  corner of Section 4. At this corner I set a 1 $\frac{1}{2}$  inch iron pipe & a  
4 inch hemlock post marked  $\frac{1}{4}$  S 4 from which: A dead fir 24 inch diam.  
bears N72°E 55.6 feet: A fir stump 48 inch diam. bears S.29 $\frac{1}{2}$ ° W. 26.8 feet

SEE CORNERS NUMBER 17 - 18 - 19

10

$\frac{1}{4}$  Section Corner to Sections 11 & 14.

Found - Orig. 30", now 42" Fir Stump N.30°W. 75.2 ft. Old bark  
describing "S" near Top of Stump.

No trace of Orig. S.W. BT. Found.

Corner checks call to Creek. Corner in Weatherly Creek Road. I set  
Witness Corner 20 ft. West.

Set Brass Cap at Witness Corner Mkd: Wit. Cor.  $\frac{1}{4}$  S11 T22S R9W  
 $\frac{1}{4}$  Cor. 20' East. County Surveyor's office, 1958

New BT's: 24" R. Fir bears N.6 $\frac{1}{2}$ °E. 40.5 ft. scribed WC  $\frac{1}{4}$  S11 CS BT.  
30" R. Fir bears N.55°E. 159.5 ft. scribed WC  $\frac{1}{4}$  S11 CS BT.  
No suitable trees near to South. FOUND O.K. 12/27/67 V.R.T.

V. W. Hesford  
August 10, 1954  
C.S. File No. 41/292  
  
James W. Byron, Deputy  
M. Godfrey  
S. Blow  
July 25, 1958  
C.S. File No. 49/103

11

$\frac{1}{4}$  Section Corner to Sections 19 & 20.

Found - 1 $\frac{1}{2}$ " Iron Pipe at Corner.

Orig. 48", now 60" Cedar, old face not grown over, scribed  
" $\frac{1}{4}$ S".

No trace of Orig. N.E. BT., would be in old roadway.  
I do not Set Brass Cap at Corner.

New BT's: 12" Cedar bears N.70°W. 9.3 ft. scribed  $\frac{1}{4}$  S19 CS BT.  
and Bearing Object:

I chisel 4" + and B. O. on Sandstone outcrop 4' above  
Creek Bed, N.56 $\frac{1}{2}$ °E. 45.9 ft.

Note: Corner in Creek Bed near South Bank.

Sept. 1958  
C. S. File No. 49/103

12

Section Corner to Sections 17, 18, 19, & 20.

Corner Set by Wilford N. Haines - Searched for by Byron, Sept. 1958.

Found - Orig. 31", now 44" Fir Stump previously opened, shows  
good scribing "W".

Clump of Maples checks bearing & distance for N. E. BT,  
No other BT's found. 14 & 20

I find Haines 1"  $\angle$  Iron at Corner with 1" Stamped Cap #239.

Find recently scribed BT's. by Haines:

16" Maple bears N.59°E. 24.3 ft. T22S R9W S17 B.T.

10" R. Fir bears N.75°W. 42.3 ft. T22S R9W S18 B.T.

Wilford N. Haines  
Sept. 1958  
C.S. File No. 49/103

13

$\frac{1}{4}$  Section Corner to Sections 9 & 4.

Found - 1 $\frac{1}{2}$ " Iron Pipe With Cap Mkd.  $\frac{1}{4}$  S4 At Corner.  
 $\frac{1}{4}$  S9

Orig. 6", now 9" down & partly rotted Fir N.37°E. 11.9 ft.  
I find good scribing "BT  $\frac{1}{4}$ S".

Base of burned Fir Tree that checks bearing & distance for  
Orig. S. W. BT.

Note: - Marked Corner Cap is 12" below surface.

I Set Brass Cap alongside & above Corner Cap. Mkd. Brass Cap S4  $\frac{1}{4}$   
1958 County Surveyor's Office T.22S R.9W. S9

New BT's: 62" Cedar Stump bears N.35°E. 87.6 ft. scribed  $\frac{1}{4}$  S4 CS BT.

60" Cedar Stump bears S.34°W. 91.5 ft. scribed  $\frac{1}{4}$  S9 CS BT.

James W. Byron  
M. Godfrey  
S. A. Blow  
Oct. 22, 1958  
C.S. File No. 49/103