

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

20

Section Corner to Sections 17 - 18 - 19 - 20.

Found - "T" Iron & Cap at Corner. Both trees mkd. by Haines & found by Byron, 1958. Still in good condition:

16" Maple N.58°E. 24.3 ft.

10" D.Fir N.77½°W. 42.3 ft.

REN'S #12 + 14

New BT's: 13" Alder S.31°E. 57.8 ft. Mkd: S20 CS BT.

12" Alder S.53°W. 18.2 ft. Mkd: S19 CS BT.

¼ Corner to Sections 17 and 20.

21

Renewed from Maple BT. (now 33") N.88°E. 6.6 ft. Did not open for scribing, new growth on tree all on W. side, Dead on E. Side-Tree would have been demolished. Available trees for new BT's. very scarce. Location identified by running East from corner Sections 17-18-19-20 and from calls on Creeks East and West of ¼ Corner which checked calls in Orig. Gov't field notes. Tree showed scar on South Side where other fork of tree Orig. stood.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W. ¼ S17
Office, 1962 S20

New BT's: 16" Hemlock N.56°W. 95.4 ft. Mkd: ¼ S17 CS BT.

8" Maple N.88°E. 4.4 ft. Mkd: ¼ S17 CS BT. (new fork of old BT.)

3" D.Fir S.12°E. 18.4 ft. Mkd: ¼ BT (no other trees available south of line)

22

Section Corner to Sections 16 - 17 - 20 - 21.

Found - 4" squared Stake at Corner & Fir, now 40", N.14°W. 30.0 ft.

2 scars very plain. Tree in good condition (Lewis, 1939) - REN #7
Hemlock, now 18", S.50°E. 7.0 ft. Scars plain. Tree in good condition (Lewis, 1939)

Maple, now 22", N.E. 33.0 ft., very plain scars, tree in good condition (Lewis, 1939)

Rotted remains of Fir Snag N.40°W. 36.3 ft. No scars or scribing found (O. BT.)

Fir Stump, now 64", S.45°W. 22.4 ft., good bark scribing visible, T22S R9W S20 (O.B.T.)

No trace of other Original BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W S17 | S16
Office, 1962 S20 | S21

New BT: 10" Hemlock S.32°W. 42.8 ft. Mkd: T22S R9W S20 CS BT.

23

Section Corner to Sections 8 - 9 - 16 - 17.

Found - Oak Tree S.73°W. 134.0 ft. Tree dead & broken off just above

BT. scar. Top portion badly burned. Found good reverse scribing "BT" just below where tree was broken.

No trace of any other BT's. found.

1½" Iron Pipe (9" above ground) N.73°E. 2.5 ft. from corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W S 8 | S 9
Office, 1962 S17 | S16

New BT's: 13" Fir S.56°W. 134.1 ft. Mkd: T22S R9W S17 CS BT.

17" Fir N.67°E. 24.7 ft. Mkd: T22SR9W S9 CS BT.

11" Fir N.35°W. 106.0 ft. Mkd: T22SR9W S8 CS BT.

15" Fir N.86°W. 35.0 ft. Mkd: T22S R9W S8 CS BT.

No trees available to S. E.

24

Closing Corner to Sections 25 and 36, T22-9W.

Found - 52" Fir S.68°E. 44.9 ft., chopped open & fd. gd. rev. scrbing.

28" Fir S.25°W. 40.9 ft, shows good axe scar. (Rescribe, "T22S R9W S36 CS BT".

48" Fir N.67°W. 43.6 ft., shows good axe scar, botting in center. (All distances on Old BT's. are slope dist. from center of trunk.)

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W CC S25 | RSW
Office, 1963 S36

New BT's: 11" D.Fir N.66°E. 22.3 ft. Mkd: "CC S25 S36 CS BT".

8" D.Fir N.38°W. 16.7 ft. Mkd: "T22S R9W S25 CS BT.

Corner lies nearly at foot of steep south slope, in upper edge of cut bank on old logging road.

Cor. Set Jan. 18, 1963

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy
June 19 thru 26, 1962
C. S. File No. 49/103

Fd. B.C. 2/85
R. HINTZ
M 98-37

Fd. by: OK
Luckman
1-13-83
93-41
M