

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 9 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

52

FD. OK.
by: Roberts
3/83
M 90-52

Section Corner to Sections 14 - 15 - 22 - 23.
Found - 5/8" Iron Rod at corner, See Ren. #38.
Orig. 12", now 36" Fir, alive, N.65°E. 21.1 ft., shows scar,
(Rescribed in bark by Haines "S14 T22S R9W BT")
Orig. 16", now 40" Fir, alive, S.22°W. 66.0 ft., shows good scar.
Orig. 16", now 24" Fir, N.19°W. 49.5 ft., down, scribe visible.
No trace S. E. Bearing Tree.

Haines' BT.-4" Fir N.51°W. 23.0 ft., blaze pitched over,
scribe visible, Haines button above blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 22 S R 9 W
(Reset I.R. alongside) Office S 15 | S 14
1968 S 22 | S 23

New BT: 8" D.Fir S.75°E. 59.8 ft. mkd. T22S R9W S23 CS BT.

Note - This corner lies on very steep, south slope approx. 180 ft. N.
of creek, course W.

53

FD by:
R. HUCKMAN
1-13-83
M 93-41

1/4 Corner to Sections 25 and 26.

Found - Unrecorded 1 1/2" I.P. & brazed cap mkd "1/4 25/1/4 26".

Orig. 30", now 36" Fir, N.88°E. 17.2 ft., now down, laying
face down.

Orig. 12", now 30" Fir west 44.9 ft., now badly decayed stump,
open from center of stump & find "4S" scribe & reverse.

Set - Brass Cap at exact point mkd: County Surveyor's T 22 S R 9 W
(Deposit I.P. alongside) Office, 1968 1/4 S 26 | S 25

New BT's: 8" D.Fir S.51°E. 49.2 ft. mkd. 1/4 S25 CS BT.

9" D.Fir S.11°W. 64.4 ft. mkd. 1/4 S26 CS BT.

Note - This corner lies on flat bench on ridge top, course N. & S.

54

S.W. Section Corner of Section 26 only.

Found - 16"?, now 42" Fir Stump, N.73°W. 88.4 ft., Open & find scribe.
No trace of other Orig. BT's. or Corner Stone.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 22 S R 9 W
Office, 1968 S 26

New BT's: 9" Alder N.54°W. 49.6 ft. mkd. T22S R9W S35 CS BT.

6" D.Fir N.14°E. 81.6 ft. mkd. T22S R9W S26 CS BT.

Note - This corner lies 90 ft. E. of rock bluff 25 ft. high on
steep N.E. slope.

55

S. E. Corner Section 27 only.

Found - Orig. 12" Fir, now down & badly decayed, N.55°E. 48.8 ft.,
find old axe marks, no scribe.

Orig. 30", now 48" Fir, alive, S.62°W. 60.1 ft., open & find
axe notch.

Orig. 16", now 40" Fir, alive, N.66°W. 13.9 ft., shows good
scar, do not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 22 S R 9 W
Office, 1968 S 27

New BT's: 8" Hemlock N.52°W. 39.5 ft. mkd. T22S R9W S27 CS BT.

11" Hemlock S.77°W. 80.9 ft. mkd. T22S R9W S35 CS BT.

10" Hemlock N.35°E. 35.1 ft. mkd. T22S R9W CS BT.

Note - This corner lies on S. edge of bench approx. 100 ft. N. of
creek, course E.

56

East 1/4 Corner to Section 34 only.

Found - Unrecorded 1 1/2" I.Pipe & brazed Cap mkd. "1/4 S34".

Orig. 40", now 52" Fir, alive, S.20°W. 16.5 ft., "1/4 B", bark
scribe in poor condition.

No trace other Original BT.

40" Fir Snag bears N.57°E. 34.0 ft., could not make this
Snag fit for other BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 22 S R 9 W
Office, 1968 1/4 S 34

New BT's: 13" D.Fir S.16°E. 30.2 ft. mkd. "1/4 S CS BT".

14" D.Fir N.19°W. 47.9 ft. mkd. 1/4 S34 CS BT.

Rescribe Orig. BT S.20°W. 16.5 ft. "1/4 S34 CS BT in bark along side scribe.

Note - This corner lies on change from moderate to steep easterly slope.
Deposit old pipe alongside brass cap.

FD by:
L. P. HUNT
M 97-6

2/6/68

Vernon "Ray" Tracy
Jack Heritage & V. Perron
January, 1968 - February, 1968
C. S. File No. 54/60