

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T.S. R. 9 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Secs. 5 and 8 only. SEE C.S. 41/292

73

Found - Squared Stake, down, near corner.

10" D.Fir, now stump, S.31°W. 21.8 ft., scribe mks. vis.

8" D.Fir, now down, S.27 1/2°E. 8.6 ft., scribe vis.

12" D.Fir, now stump, N.86°W. 19.1 ft., scribe vis.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W

Office S 5
1971 S 8 S 4

New BT's: 6" D.Fir S.69°E. 12.8 ft. scribed "S4 CS BT".

6" D.Fir S.86°W. 8.5 ft. scribed "S8 CS BT".

6" D.Fir N. 61°E. 6.1 ft. scribed "S4 CS BT".

10/18/71

74

N.E. D. L. C. No 39.

Found - Orig. 12", now 38" Fir, S.89°W. 23.1 ft., no orig. scribe.

(Recent Scribe DLC 39 BT)

36", now 46" Fir Stump, N.5°E. 75.9 ft., show part of old face.

New Tree: (No record) 16" D.Fir Snag, N.19°E. 21.4 ft., scribe N.E. DLC 39 BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W

Office NE
1971 DLC 39

New BT's: 6" D.Fir N.75°W. 33.2 ft. scribed "DLC 39 CS BT".

9" D.Fir N.62°E. 34.3 ft. scribed "NE DLC 39 CS BT".

This corner lays near top of ridge slightly on S. Side.

10/18/71

JAN 1972

1/4 Corner for Secs. 8 and 5.

Found - Remains of both original bearing trees.

At the corner point as determined from the remains of the orig. BT's:

An Orig. 48" Fir, now a 50" rotten stump which shows a good scar on the bark, bearing N.52°E., 40.9 ft.

A orig. 32" Fir, now a 36" rotten stump, previously opened but scribing visible then has now deteriorated. We open higher and find good scribing "1/4", bearing S.9°W., 15.2 ft. (record S.1°W., 15.2 ft.)

We set - A 1" x 30" Iron pipe with brass cap attached marked:

COUNTY SURVEYORS T 22 S
OFFICE S 5
1975 S 8 1/4
R 9 W

New BT's - An 8" D.Fir, bears N.45°W., 34.4 ft. scribed "1/4 S5 CS BT"

An 18" D.Fir bears S.74°W., 23.4 ft. scribed "1/4 S8 CS BT".

Compass declination setting: 20° East.

2/6/75

75

Closing Corner to Sec. 5 and 4 SEE C.S. 41/292

76

Found - 14 X 12 X 6" sand stone, CC marked on one side, 2 grooves on one side, stone badly weathered and laying on surface.

BT's - A fir, 26 (now 39) inches dia. bears N 20 1/2°E, 27.7 ft. Scribed "CC T 22S R 9W S" Blaze partially opened and burned.

A fir stump, 28 (now 39) inches dia. bears S 71 1/2°E., 69.7 ft. (rec. 68° ft) partial blaze below cutting line scribed "BT" (blaze not original as face of blaze falls well outside of record dia.)

A fir 8 (now 35) inch dia. bears S 53 1/2°W., 115.5 ft. (rec. S 52°W) Tree has good blaze

Set - Brass cap at closing corner stamped

"COUNTY SURVEYORS OFFICE" T 21 R9W
1975 S 32

S 5 S 4
C C

T-22 S R 9 W

Orig. corner stone on north side of cap with C C on south face.

Note: Corner lies on top of Ridge running west. 11/20/75

L.E. Monrean
P.L.E.
11/20/75
C.S. 57/39

Gary L. Langlitz, Surveyors Off.
Vic Cangile
Feb. 6, 1975
C.S. 57/17

James W. Byron, Co. Surv.
John M. Powell & Crew
Oct. 1971 C.S. File 53/66

RE-RENEWED SEE COUNTY RECORD NO. #109

JAN 78
1-79

176