

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 10 R. W. W. M.

KORP-CHAPMAN CO., EUGENE, ORE. 91028

H. J. Eppsteff
Wagner
R. C. Lane
Chapman
Tolletson
June 4, 1937
C.S. 15/3

MEANDER COR. ON SOUTH SIDE OF RIVER ON LINE BET. SECS. 23-24
Found one old bearing tree, namely the 8" Maple S. 63° E. 10 lks. dist. with scribe marks badly decayed. Set post from which
A 18" Maple, bears S. 27° 02' E. 16.8 ft. in dist. Marked
A 24" Maple, bears S. 79° 22' W. 40.5 ft. in dist. Marked
S. 23 M.C. C.S. P.T.

RE-RENEWED, SEE CORNER NO. 20

3-11-46. Reported by Mr. Mundack (Cousins) corner as described except that trees & post were not scribed although blazed for scribing

This corner reported found (June 19, 1956) by road department (County) with trees scribed as originally reported. The 18" Maple, however, has been chopped out and scribe is gone. The 24" Maple is partly grown over.

QUARTER CORNER SECTIONS 6 and 7:
1/2" Iron Bolt for Corner in Highway right-of-way and Centerline driveway leading to stables
20" Maple which bears N. 8 degrees East, 112.6 ft.
Marked S. 6 B. T. on tree R. E. 2741

RE-RENEWED, SEE CORNER NO. 80

Meander Cor. on Left Bank of Umpqua River Bet. Secs 17 & 16
Set 1/2" Iron Rod from O. B. T. stump, from which
A 16" Fir Bears N 86° E 13 lks. Scribe Plain

C.S. 43/187 4

Section Corner common to Secs. 35 & 36 (South Side)
Original: Post (found rotted & down scribing visible), from which:
36" Fir bears N. 75° W. 52 lks.; now 54" stump, scribed 2 S 35 visible, also (not orig.) scribed T22S R10W BT & portion of 35 visible on down log.
36" Fir bears S. 82° W. 114 lks.; now 63" stump, face unexposed.
36" Fir bears N. 82° E. 175 lks.; now 56" uproot snag, face unexposed.
Restored: Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap mkd. "ORE. ST. BD. OF FORESTRY T22S R10W S35 S36 T23S R10W S2 1958 RS 359," 33 inches in ground, and from which a:
19" Hemlock bears N. 45° E. 8.0 ft. scribed T22S R10W B36 BT.
20" Hemlock bears N. 87° W. 40.2 ft. scribed T22S R10W S35 BT RS 359
Ore. St. Bd. of Forestry metal location poster on 19" Hemlock BT.

RE-RENEWED, SEE CORNER NO. 98

1/4 Corner to Section 35 (South Side)
Original: Post (now missing) from which a:
10" Fir bears N. 80° E. 21 lks. now 23", scribed 1/4 S visible, also scribed 1/4 S 35 T22S RW visible above orig. face.
16" Maple bears S. 71° E. 13 lks.; now 28", face unexposed.
Restored by Levi Walker, August 6, 1906.
Post (found rotted & down, position of scribed R10W visible).
Restored - Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "Ore. St. Bd. of Forestry 1/4 S35 1958 RS 359," 33 inches in ground, in mound of stone, and from which a:
34" Fir bears N. 2 1/2° W. 67.0 ft.; scribed 1/4 S 35 BT RS 359.
Oregon State Board of Forestry metal location poster on Orig. 10" Fir BT.

RE-RENEWED, SEE CORNER NO. 87

1/4 Section Corner Common to Sections 27 and 34.
Original - Sandstone bluff 5' x 10' (found in place, x 1/4 S on SE face) from which:
4" Fir bears S. 5° E. 6 lks.; now missing.
36" Fir bears N. 64° E. 26 lks.; now 49" snag, scribed 1/4 S visible on upper face.
Restored - 20" Fir bears S. 28 1/2° W. 19.6 ft.; scribed 1/4 S 34 BT.
24" Fir bears N. 40° W. 23.3 ft.; scribed 1/4 S 27 BT RS 359.
Oregon State Board of Forestry metal location poster on 20" Fir BT.

March 7, 1958

A. R. Evans
12 / 1949
B. Mathews
B. B. I. chg.

Art Evans
April 1952
C.S. 41-29

Filed Feb. 24, 1958

OREGON STATE BOARD OF FORESTRY
Arnold G. Gibson
Elbert Driver
Wit: Dennis Bagger
Derald Timmons
Ron Witham
C. S. File No. 42/341

Same as