

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 10 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

41

$\frac{1}{4}$  Corner to Section 32, T21-10W.  
Found - I.P., filled with concrete with brass cap, broken off and found in duff when excavating for new monument.  
10", now 16" Alder, badly decayed, N.35°E. 13.9 ft. (Rec. 10.6')  
We open & find edge of axe blaze.  
Only hole where N.W. BT probably stood, fits record bearing and distance.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T21S R10W  $\frac{1}{4}$  S 32  
T22S  
(Deposit old corner material alongside)  
New BT's: 12" D. Fir N.45°E. 26.0 ft. mkd. " $\frac{1}{4}$  S32 CS BT".  
7" D. Fir N.11°W. 13.9 ft. mkd. " $\frac{1}{4}$  S32 CS BT".  
Note - This corner lies on steep N.W. slope 50 ft. W. of spur.

42

North  $\frac{1}{4}$  Corner Section 5, T22-10W.  
Found - 1919 GLO Brass Cap, buried & broken off, concrete-filled Iron Pipe in place.  
6", now 8" Cherry, down & decayed, laying across I.P., S.83°E. 15.8 ft., no scribe found.  
8", now 18" Alder, alive, S.25°W. (Rec. S.20°W.) 16.5 ft., shows scar, do not open. Rescribed in bark: " $\frac{1}{4}$  S5 CS BT".  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T21S R10W  $\frac{1}{4}$  S 5  
T22S  
(Deposit old corner material alongside)  
New BT's: 26" D. Fir S.21°W. 39.7 ft. mkd. " $\frac{1}{4}$  S5 CSBT".  
14" D. Fir S.42°W. 58.5 ft. mkd. " $\frac{1}{4}$  S5 CS BT".  
Note - This corner lies 297 ft. W. of U.S.F.S. line, tag on top of ridge, sloping N.W.

43

Section Corner to Sections 2 and 1, T22-10W.  
Found - 1963 Cad. Brass Cap & BT's., as follows:  
26" Sawed Fir Stump, S.51 $\frac{1}{2}$ °W. 25.7 ft., scribe visible.  
1919 Bearing Trees down. 1919 Brass Cap gone.  
Set - 6 ft. steel fence post alongside brass cap.  
New BT's: 18" Alder S.72°E. 41.0 ft. mkd. T22S R10W S1 CS BT.  
16" Alder S.51°E. 36.1 ft. mkd. T22S R10W S1 CS BT.  
Note - This corner lies on very steep, N.W. slope near NE corner of clear cut unit & approx. 100' W. & 75' south of solid rock ravine, course N.W.

44

$\frac{1}{4}$  Corner to Section <sup>35 1/15/65 r.l.</sup> 36, T21-10W.  
Found - 1919 Brass Cap, broken off, concrete filled I.P. in place.  
6", now 7" Fir, decayed stub, N.21°E. 10.6 ft., shows fragmentary scribe.  
16", now 22" Fir, N.79°W. 4.0 ft. alive, shows good scar.  
We do not open.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T21S R10W  $\frac{1}{4}$  S 35  
T22S  
(Deposit old corner material alongside)  
New BT's: 10" D. Fir N. 76° E. 13.7 ft. mkd. " $\frac{1}{4}$  S35 CS BT".  
22" D. Fir N.79°W. 4.0 ft. mkd. Rescribed: " $\frac{1}{4}$  S35 CS BT".  
Note - This corner lies on steep S.W. slope approx. 85 ft. W. of top of spur, ridge sloping south.

45

North  $\frac{1}{4}$  Corner to Section 1 only, T22-10W.  
Found - 1919 GLO Brass Cap, in place. Pipe badly rusted.  
Orig. 8", now 22" Fir, alive, S.11°E. 29.0 ft., shows good scar.  
Orig. 8", now 10" Fir, decayed remains of stump only, S.35°W. 26.4 ft., find partial old blaze & reverse scribe in stump.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 21 S R10W  $\frac{1}{4}$  S 1  
T 22 S  
New BT's: 18" D. Fir S. 60° E. 25.8 ft. mkd. " $\frac{1}{4}$  S1 CS BT".  
14" Alder S. 49° W. 18.1 ft. mkd. " $\frac{1}{4}$  S1 CS BT".  
Deposit old corner pipe & brass cap alongside. This corner lies on moderate S. slope approx. 348' N.88°E. of S $\frac{1}{2}$  Sec. 36, T21-10, see Ren.#47.  
6/10/68

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
May, 1968  
C. S. File No. 54/1