

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 10 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy
Jack Heritage & V. Perron
June & July, 1968
C. S. File No. 54/1

Wit. Corner to Sec. Cor. to Sections 32 & 33 only, T21-10W. 46
Found - 1965 C.S. Brass Cap & sawed stumps of BT's., as follows: Ren. #37.
26" Fir Stump N. 17° E. 6.8 ft., scribe visible. Set 5/8"x30" I.R.
on bearing at 5.4 ft. from Wit. Cor. at base of BT.
24" Fir Stump S. 75° E. 16.9 ft. (not 15.4') scribe visible.
Set 5/8"x30" I.R. 15.6 ft. from Wit. Cor. at base of BT.
Set - 6 ft. steel fence post alongside Brass Cap.
No trees available for new BTs.
Wit. Cor. lies on top of cut bank 35 ft. south of U.S.F.S. Rd. #2138. At true
corner point, set 5/8" I.R. x 15". Sandstone in roadway flush with
surface 3.0 ft. W. of ditch line.
Wit. Cor. bears South 34 ft.
The 5/8"x30" I.Rod's set at base of Wit. Cor. BT's., as follows, from
5/8"x15" I.R. set at true corner point on edge of roadway:
5/8"x30" I.R. bears S. 19° E. 58.3 ft. This rod is 6" above ground at
base of Wit. Cor. BT. to SE.
5/8"x30" I.R. bears S. 3° E. 28.0 ft. This rod is 6" above ground at
base of Wit. Cor. BT. to NE.

South 1/4 Corner to Section 36 only, T21-10W. 47
Found - 1919 GLO Brass Cap, laying on ground, pipe broken off 10" below surface.
Orig. 8", now 9" Fir Snag, N. 24° E. 25.1 ft., "36" scribe
visible on open blaze, badly decayed.
Orig. 6", now 24" Fir, Alive, N. 55° W. (Rec. N65W) 13.9 ft., shows
fair scar. We do not open, Rescribed 1/4 S36 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R10W 1/4 S 36
Office, 1968 T 22 S
Deposit old corner material alongside brass cap.
New BT: 28" D. Fir N. 25° E. 45.3 ft. mkd. "1/4 S36 CS BT."
Note - This corner lies on moderate southerly slope in timber & brush,
approx. 348 ft. S. 88° W. of N 1/4 Sec. 1, T22-10W, Ren. #45.

1/4 Corner to Section 33 only, T21-10W. 48
Found - Concrete-filled I.P. at corner point, broken off and
Brass Cap on ground alongside. (Deposit alongside CS Brass)
Orig. 5", now 10" Fir, alive, N. 23° E. 18.5 ft., good scar.
We Rescribe above old scar, "1/4 S33 CS BT".
Orig. 8", now 14" Fir, alive, N. 76° W. 15.2 ft., good scar.
We Rescribe above old scar, "1/4 S33 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R10W 1/4 S 33
Office, 1968 T 22 S
This cor. lies 25 ft. W. of rock spur, sloping S. 40° W. on steep W. slope.

North 1/4 Corner to Section 4 only, T22-10W. 49
Found - Concrete-filled I. Pipe with Brass Cap broken off, Deposit alongside.
No trace of Cherrywood around location of SW Orig. BT.
Call on spur ridge to West fits good.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R10W 1/4 S 4
Office, 1968 T 22 S
New BT's: 15" D. Fir S. 87° E. 18.5 ft. mkd. "1/4 S4 CS BT".
32" D. Fir S. 22° W. 16.5 ft. mkd. "1/4 S4 CS BT".
This corner lies about 160 ft. E. of spur, ridge, sloping S.

SEPT. '68

NOT USED

50