

Douglas County Surveyor's Record of  
Government Corners Renewed

22

T. S.

10

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Oregon State Board of Forestry  
Arnold G. Gibson

Elbert Driver  
C.S. File 42/331

Elbert Driver  
CS File 42/353  
Map M 10 - 19

MARCH 71

Oregon State Board of Forestry - Arnold G. Gibson  
Charles W. Cook, Engineer  
C. S. File No. 55/233

Section Corner to Sections 1 and 2, T23-10W  
Found: Orig. Post (now missing) from which a:

FD OK PER BAKER  
APRIL -87 - M104-19  
CS. 63/50

56

8" Fir, now 29", S.25°E. 28 lks., exposed portion of scribe,  
"S" (bearing is S.38°E.)  
24" Fir bears S.88°W. 46 lks., now 40" , bark scribed T23SR10WS2BT  
visible.

Retracement by L. Walker, 1906, Post (found, rotted & down, scribed  
T23S R10W S1 & 2 visible)

Restored: Set-1 1/2"x36" galv. I.P. with 3" bronze cap mkd:"Ore.St.Bd.of  
Forestry T22S R10W S36 T23S R10W S1 S2 1957 RS359", 33" in  
ground & from which a:

16" Fir bears S.44°W. 13.5 ft., scribed "RS359".  
40" Fir (Orig.) bears S.88°W. 30.4 ft., scribed "BT" in wood.  
Ore.St.Bd.of Forestry metal location poster on 16" Fir BT.

9/9/57

Cl. Corner common to Sections 2 and 3, T23-10W.

57

Orig. Post (now missing) from which a:

20" Hemlock bears S.58°E. 64 lks. now missing, pieces of broken-up  
stump with back cast of scribe "2" visible, found nearby.  
24" Alder bears S.86°W. 23 lks. now missing, possible orig. log  
nearby, no markings found.

Set 1 1/2"x36" galv. I.P. with 3" bronze cap mkd:"Ore.St.Bd.of Forestry  
T22S R10W S35 T23S R10W S2 S3 CC 1958 RS359", 33" in ground, in  
mound of stone, & from which a:

FD  
OK  
1/18/82  
E. HINTZ  
M 91-1

24" Hemlock stump bears S.45°W. 92.5 ft., scribed T23S R10W S3 BT.  
18" Hemlock bears N.38 1/2°W. 58.5 ft., scribed "RS359".

Set - 4x4x72" white painted Cedar Post 1.0 ft. S.E. of pipe.  
Ore.St.Bd. of Forestry metal location poster on 18" Hemlock BT.  
South 1/4 Cor. fo Sec. 35 bears N.88° 50E. 88.3ft. (prop.dist.).  
Center of road bears S.39°E. 79.0 ft.

4/4/58

58

1/4 Corner for Section 36 (East Side), T22-11W.

Orig. Stone 20"x14"x10" (missing) from which a:

5" Fir bears N.87°W. 11 lks.; missing  
40" Burnt Fir bears N.81°E. 32 lks.; in place,  
scribes 1/4 S BT visible.

Set - 1-1/2"x36" I.P. with 3" Bronze Cap Mkd:"Ore.St.Bd.of  
Forestry 1/4 S36 1971 RS359", 34 inches in ground, from which

39" Fir bears N.53°W. 31.0 ft., to face; scribed 1/4 S36  
32" Fir bears S.54-1/2°W. 86.8 ft., to face; scribed 1/4 S36 BT.

Set 4"x4"x72" white painted cedar post 1.2 ft. N.55°W. of  
corner pipe. Ore.St.Forestry Dept. metal location poster on  
32" Fir BT.

10/12/71

Section Corner for Section 31 (SW).

59

Orig. 20"x12"x8" Stone (in place, no marks visible) from which a:  
36" Fir bears N.73°E. 44 lks; now 50" rotten snag 30' tall,  
in place; no marks visible.

30" Fir bears S.24°W. 12 lks.; now 28" rotten stub, in place,  
scribes S31 B visible

40" Fir bears N.55°W. 29 lks.; now missing.

Set-1-1/2"x36" I.P. with 3" Bronze Cap mkd:"Ore.St.Bd.of Frstry  
T22S R10W S31 T23S R11W S1 1971 RS359, 35" in ground, with  
orig. stone alongside, and from which a:

22" Fir bears N.42°E. 10.6 ft., to face; scribed T22S R10W  
S31 BT RS359.

33" Fir bears N.9°W. 10.6 ft., to face; scribed  
T22S R10W S31 BT.

Set 4"x4"x72" white painted Cedar post 2.7 ft. S.1°W. of  
corner pipe. Ore.St.Frstry.Dept. metal location poster on  
33" Fir BT.

11/22/71

RENEWED SET CORNER NO. # 113

668