

Douglas County Surveyor's Record of
Government Corners Renewed

T.22 S. T.S. R. 10 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

60

Section Corner common to Sections 7, 8, 17 and 18.
Orig. 6'x4'x2' Stone (in place, cross(x), 4 notches on S,
and 5 notches on the E sides) from which a:
8" Fir bears N.89°E. 225 lks.; missing
8" Fir bears S.85°E. 200 lks.; missing.
40" Fir bears S.44°W. 10 lks.; now 40"x14' high stub,
scribes R10W visible.
4" Fir bears N.26°W. 13 lks.; missing
Rewitnessed: 20" Fir bears N.70°E. 18.6 ft., to face;
scribed T22S R10W S8 BT.
20" Fir bears S.87 3/4°E. 27.3 ft., to face; scribed
T22S R10W S17 BT RS359.
9" Fir bears S.7°W. 21.7 ft., to face; scribed
T22W R10W S18 BT.
22" Fir bears N.19°W. 63.3 ft., to face, scribed
T22S R10W S7 BT.
Set 4"x4"x72" white painted Cedar post 4.7 ft. N.36°W. of
corner stone. Ore.St.Forestry Dept. metal location poster
on 20" Fir N.70°E. 18.6 ft.

12/23/71

61

Northwest Section Corner for Section 16.
Orig. 20"x16"x12" Sandstone (missing) from which a:
28" Fir bears N.10°E. 152 lks.; missing, in old burn & slide.
10" Fir bears S.37°E. 57 lks.; now 40", in place, exposed BT.
Set 1-1/2"x36" I.P. with 3" Bronze Cap mkd: "Ore.St.Bd.of Fstry.
S17 S8 T22S R10W S16 1971 RS359", 34" in ground, in mound
of rock, and from which a:
29" Fir bears N.66-1/2°E. 34.2 ft., to face; scribed
T22S R10W S16 BT.
40" (Orig.) Fir bears S.37°E. 37.6 ft.; scribed RS 359.
Set 4"x4"x72" white painted Cedar post 3.6 ft. S.6°E. of
corner pipe. Ore.St.Forestry Dept. metal location poster on
40" Fir BT.

FD OK 9/89
R. STUNTZNER
M 108-75

62

Closing Corner for Sections 9 and 10 only.
Found - Old BT, S.60°W., 90 lks. Scribes & tree in good condition.
Old BT, N.60°E., is broken snag and cannot verify. Bearing
is correct but distance is 30 lks too far.
Set - Brass Cap from the 3 good calls mkd: T 22 S R 10 W

S 9 | S 10
S 15
LS 418
1972

New Witness Trees: 43" D. Fir, bears N.27°30'W., 13.2 ft. Marked
T22S R10W S9 BT.
51" D. Fir bears S.26°E., 43.0 ft. marked S15 BT.
I bark scribed both trees and measurements were taken from the face of
scribing. Corner is on steep west face 260 ft. west of ridge top.

4/18/72

63

Section Corner for Section 17 (Northeast)
Original 20" x 16" x 8" Sandstone (missing) from which a:
28" Fir, bears N.10°E., 20 lks.; missing
20" Fir, bears S.31°E., 30 lks.; missing
36" Fir, bears N.89°W., 3 lks.; now missing
Ridgetop bears West 2.50 Ch.; in place
Northwest corner Section 16 bears S.00°03', 1.35 ch.; OSBF
Pipe and cap in place, 1 original BT, 1 new BT.
Set - 1 1/2" x 36" gal. iron pipe with 3" bronze cap marked "Oregon State
Board of Forestry T22S R10W S17 S8 S16 1971 RS359", 34" in ground,
and from which a:
18" Fir, bears N.79°W., 27.4 ft. to face; scribed T22S R10W S17 BT RS359
2' high x 8' long rock face bears S30 1/2°W., 3.5 ft. to face; scribed XBO
Set 4" x 4" x 72" white painted Cedar post 3.6 ft. S.12°E., of corner
pipe. Oregon State Forestry Department metal location poster on 18" Fir
BT N.79°W., 27.4 ft.

7/20/72

Oregon State Board of Forestry - Arnold G. Gibson
Charles W. Cook, Engineer
C. S. File No. 55/233

Burton W. Holt
Ted Hutchinson
April, 1972
C.S. File 55/249

FD OK 10/89
R. STUNTZNER
M 108-75

Oregon State Bd. of
Forestry.
Arnold Gibson
Charles Cook
Nicholson, Metcalf,
Hook
July 20, 1972
C.S. File 55/233