

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

69

Arnold G. Gibson
Oregon State Bd. Of Forestry
W. Metcalf
M. Reed
C.S. 55/304
May 3, 1973

1/4 Corner for Sections 17 and 20
Did not find orig. 4" Alder
Found - 4" Fir, bears South 3 lks.; now 13" x 9' tall stub, in place, scribes 1/8 expose.
6" Fir, bears N.15°E., 13 lks.; now 5" x 18" long rotted chunk, out of place, scribes BT remaining.
Set - 1 1/2" x 36" galvanized I.P. with 3" bronze cap marked "Oregon State Board of Forestry 1/4 S17 S20 1973 RS359", 35 inches in ground, and from which a
New BT's - 20" Fir, bears S.42 1/4°W., 12.0 ft. to face; scribed 1/4 S20 BT RS359.
34" Fir, bears N.46 1/2°E., 17.6 ft. to face; scribed 1/4 S17 BT.
Set - 4" x 4" x 72" white painted Cedar post 1.7 ft. East of corner pipe. Oregon State Forestry Department metal location poster on 34" Fir BT N.46 1/2°E., 17.6 ft.

70

Arnold G. Gibson
for: Oregon State Bd. of Forestry
M 55 - 13
Nov. 12, 1974

1/4 Corner for Secs. 8 and 17.
1/4 Corner established
Set - Oreg. St. Bd. of Forestry 1 1/2" Galv. I.P. and 3" Bronze cap.
New BT's - 21" Willow, S.31°E., 17.8 ft. with yellow metal location poster.
11" Willow, S.82°E., 13.3 ft. mkd. with RS 359.
4"x4"x72" White painted cedar post, S.22°E., 3.0 ft.

Ed. OK - Co. Surveyor - 7/21/76 c.s. 59/18

71

Center 1/4 Corner for Sec. 17.
Set - 3/4" x 18" Rebar in 22" in road bed of Highway #38, in 5 3/4" x 8" Valve box.
46" Fir, S.50 1/2°W., 40.00', RS 359, with Yellow metal location poster.
30" Fir, S.81 1/2°W., 85.9 ft.
4" x 4" x 72" White painted cedar post, West 27.6 ft.

72

1/4 Corner for Secs. 17 only. West side.
Set - Ore. ST. Bd. of Forestry 1 1/2" x 36" Galv. I. P. and 3" Bronze cap.
BT's - 18" Fir, S.10 1/2°E., 12.4 ft. mkd. RS 359 with yellow metal location poster.
15" Fir, N.67°E., 25.6 ft.
White painted cedar post, N.77 1/2°W., 3.7 ft.

JAN 75

73

Section Corner For Secs. 12 and 13 only, T.22-11.
Found - In an area approx. 50 ft. North of C.C. Secs. 7 and 18, T22-10, we find: A 4" now 14" orig. rotten alder snag with scar. Cut into tree. Found no trace of scribing. Bears S.58°W., 2.6 ft.
A 52' Burnt rotten snag bears South 27.0 ft. This tree was called as line tree in orig. GLO notes. Found no trace of the line blaze.

Found no trace of NW BT or orig. corner monument.
At true corner point as determined by the record bearing & dist. of the orig. SW BT: We set - A 1" x 36" I. Pipe with brass cap mkd.

"Douglas Co. Surveyor T22S
1976 S12 S7
S13

R11W R10W

New BT's - A 18" D. Fir bears N.61°W., 39.5 ft. scribed "T22S R11W S12 CS BT" in double blaze.
A 11" D. Fir bears S.24°W., 44.4 ft. scribed "T22S R11W S13 CS BT" in double blaze with lower blaze starting approx. 2 ft. from ground.

Compass declination setting: 20° East. 6/21/76

74

Closing corner for Secs. 7 and 18 only. West side.
Found - An orig. BT, a 16" now 54" D. Fir, in good condition with scribing "S7 visible on previously opened blaze.
We do not find any trace of the remaining orig. BT's or the orig. corner monument.

At the true corner point as determined at the record bearing & distance from

Gary L. Langlitz, Douglas Co. Surveyors Office
M. Lenora Ladig, P. Earle, K. Cheney
June 21, 1976
C.S. 59/15