

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T.

78

A 10" D. Fir, bears S.50°E., ^{28.1}~~18.1~~ ft. with scribing "CC T22S R10W S7 BT" visible on an unhealed single blaze.
A 24" D. Fir bears S.5°W., 29.3 ft. (Rec. per M56-56, 20" Fir, S10°W., 29.3 ft.) with scribing "CC T22S R11W S12 BT", visible on an unhealed single blaze.

We remove the iron rod and Set a 1" x 30" I.P. 27" in the ground with brass cap attached for the closing corner mkd:

Douglas Co. Surveyor	R	T 22 S	R
1976	11 S 12	$\left\{ \begin{array}{l} S 6 \\ S 7 \end{array} \right.$	CC 10
	W		W

We place the iron rod along the east side of the brass cap.

Note: This cor. is located approx. 20 ft. west of a ridge top running N.20°W. and S.20°E.

10/25/76

W. 1/16 Corner for Secs. 6 and 7.

Found - 5/8" I.R. set by Baughman (See M65-12 ~~M56-56~~). I. Rod is set in rock outcrop on steep west slope.

From which:

A 14" Fir, bears S.61°E., 5.4 ft. Tree blazed and scribed "W 1/16 S7 BT". This tree was SW BT for W. 1/16 cor. set by Hootman, 1961.
A 14" Fir, bears N.38°W., 16.1 ft. Tree blazed & scribed W 1/16 S6 BT".
A sandstone set by Hootman, bears S.78°E., 9.7 ft. Stone mkd. "W 1/16"

Renewal:

Place Douglas Co. Surveyor Aluminum cap on 5/8" Iron rod set by Baughman, cap stamped "W 1/16".

10/25/76

1/4 Corner for Secs. 6 and 7.

Found - A nail set in the southerly fog line of Hwy. #38 (See M ~~56-56~~ ^{M65-12})
From which bearing trees marked by Baughman are located as follows:

A 12" D. Fir, bears S.2°E., 68.0 ft. scribed "1/4 S 7 BT" on a single unhealed blaze.
A 14" Bigleaf Maple bears S.88°W., 93.3 ft. scribed "1/4 S7 BT" on an unhealed double blaze.
A bearing object located by Baughman, A bronze disc set in a drill hole in a sandstone boulder marked Douglas County Surveyor's Office U-84, 1973, bears N.34 1/2°W, 171.09 ft.

In the location of the found nail we drive a boat spike flush with the surface of the asphalt road surface.

Note: It appears this corner was located with reference to the remains of the bearing tree marked by Evans in 1952 (See Ren. #3) a 20" Maple, now 24", down and rotting with illegible scribe marks of an unhealed blaze and Forest Service location tag attached, bearing N.8°W., 142.6 ft. This down Maple BT is not an orig. BT as indicated by M56-56.

11/2/76

~~JAN 78 WREAG TOWNSHIP - SHOULD BE T.205. 9/80~~

~~1/4 Corner for 8 and 17.~~

~~Set - By apportionment - 5/8" Iron rod~~

~~From which:~~

~~BT's- 20" Hemlock bears N.43°15'E., 37.6 ft. scribed.
18" Hemlock bears N.24°30'W., 11.8 ft. scribed.~~

~~Note - Found corner from County Surveyor's file map # M 35- 80 bears N.45°13'E., 17.79 ft.~~

~~7/78~~

1-79
1/4 Corner for Sections 10 and 11.

Found - Orig. 15" D. fir now 5 ft. high snag bears S.88°E., 3.3 ft. Chopped into healed face, found blaze 2.7 ft. long, 0.2 ft. wide with scribing "1/4 S BT"

Set - Douglas County Brass cap on 3/4" I.P. 36" long with flanged bottom marked "T22S R10W S10 S11 1/4 1982".

New BT's- 22" D. fir bears N.9°30'W., 7.6 ft. scribed 1/4 S10 CS BT.
34" D. fir bears S.75°30'W., 11.8 ft. scribed 1/4 S10 CS BT.

Location: Go along Rd. #210 approx 1.7 miles to second large clearcut (south of road). Take main ridge west. Walk ridge staying west and south. Follow ridge approx. 5000 ft. to corner, which lies on east side of ridge near top.

81

Gary Langlitz
P. Earle
Oct. 25, 1976
C.S. 59/24

Douglas County Surveyors Office

L.E. Monrean
K. Cheney
Oct. 25, 1976
C.S. 59/24

Gary L. Langlitz
Karen Cheney
Doug. Co. Surveyor's
Office
Nov. 2, 1976
C.S. 59/26

Richard Hintz
For: International
Paper Co.
July 1978
M 74 - 3

Ernesto Alvarado,
U.S. Forest Service
Carol Dickison; Colin
Long.
April 4, 1982
C.S. 61/32