

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 11 R. W. W. M.

1/4 Corner to Secs. 8 & 17.

Find No trace of Orig. Stone but fine Orig. BT's.

30" Fir, now 60", N. 80°W. 33.0 ft. (mkd. 1/4 S8 BT) 128

12" Cedar, (18" x 30") S. 87°E., 73.0 ft. (mkd. 1/4 S17 BT)

Set Iron Pipe for Corner.

9

Section Corner to Secs. 7 & 8 only, on the North Line of Sec. 17.

Identify Cor. from one remaining Orig. BT:

14" Alder, now 36" S. 88°E., 52.8 ft.

The location of this corner as it bears from the above described BT. falls on a bed of smooth rock in a creek bottom. We make a diligent search for the Orig. chiseled X but conclude that due to the softness of the Stone & constant erosion by water, that it is washed away.

Mark a new X, 12" x 12" & drive an aluminum tack in the center, from which bears:

36" Alder, S. 88°E., 52.8 ft. (mkd. S17 BT)

3/4" Iron Pipe S. 55°W., 5.9 ft.

No other BT's. available.

10

Section Corner to Secs. 17 & 18 only, on the S. Line of Sec. 7.

Found Orig. BT's:

12" Cherry, S. 25°E., 38.9 ft. (Orig. BT. down & rotten)

16" Alder, S. 65°W., 29.0 ft. (Orig. BT. down & rotten)

16" Alder, N. 75°W., 48.2 ft. (Orig. BT. down & rotten)

Set an Iron Pipe for the Corner, from which:

18" Cherry S. 33°E., 28.5 ft. mkd. S17 BT. (new BT)

24" Alder S. 89°W., 36.8 ft. mkd. S18 BT. (new BT)

No other BT's available.

11

1/4 Corner to Secs. 6 & 7.

Set an Iron Pipe & Post from which bear the Orig. BT's:

24" Myrtle, now 36", 17.8 ft. (remark 1/4 S6 BT)

40" Fir, now 48", 4.6 ft. (chopped out - scribing visible)

12

Section Corner Common to Secs. 5, 6, 7, & 8.

Find all the Orig. BT's: BT. in Sec. 7 is down & badly burned, no scribing visible, but there has been a face on the tree. BT's in Secs. 5 & 6 are healed over, and the BT. in Sec. 8 is a stump with an obvious face scar on the Orig. bearing but 38.0 ft. dist. from the Cor. Point Set from the other three bearing trees.

Set a 1" X 36" Galvznd. Pipe at the Corner Point.

13

1/4 Section Corner to Sections 5 & 8.

4' North of a post set by S.O. Newhouse (prop. 1/4 Cor.), I make a careful search of the area for evidence of the Orig. Cor.

Find remains of a Cherry tree on which there has been a face, but I can discern no scribing. I set off from the position of the Cherry Tree, the record dist. & bear. & turn the bearing for the Orig. Maple. At the record dist. & bear., I find a 24" Maple tree which is a Newhouse BT; but has no visible scar.

Reset the 1/4 Corner at this Point & use the Newhouse BT.

which are now: R. Cedar 18" DBH bears S4°00'E. 28.6 ft.

Maple 24" DBH bears N. 57°00'W. 25.7 ft.

The Corner lays on a Steep West Slope.

14

Marked BT. for Corner to Secs. 8, 9, & 16.

Find 4" x 4" White Post - 4' North.

All Orig. BT's. The BT. listed as a 30" D. Fir S. 21°E.

25 lks. is presently a 50" D. Fir with no visible face. 83

20" D. Fir Snag with a grown over face sits on bearing at the base of the larger tree. BT. N. 54°W. 11 lks. is down & a tree has fallen over the Corner position.

Also find a tree with an obvious face scar healed over, S. 40°00'E. 15.2 ft. (continued next page)

15

S. O. & H. J. Newhouse
Survey for Cape Arago Lumber Co.
March, 1957
C. S. File No. 42/256
Map File M 1 - 54

Warren D. Hootman
For Cape Arago Lumber Co.
August 1958
C. S. File No. 42/386
Map File No. M 12 - 47

RENEWED, SEE CORNER NO. 128

RENEWED, SEE CORNER NO. 153