

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 11 R. W. W. M.

Closing Township Corner common to Sections 31 & 36, R.11 & 12 W. ²¹
Original: Stone 24" x 12" x 6" (found in place with 6 notches on the North) from which a:
20" Dead Cedar bears N54E 18 lks.; now 16" burnt & rotted uproot, faint scribe marks visible.
24" Cedar Stub bears N85½W 118 lks.; now missing.
36" Fir stub bears S71E 69 lks.; now rotted & burnt uproot.
Restored: Built mound of stone around original stone, from which a:
25" Fir bears N17E 19.4 ft.; scribed T22S R11W S31 CC BT.
29" Fir bears W90W 103.6 ft.; scribed T22S R12W S36 CC BT.
31" Fir bears S20E 25.8 ft.; scribed RS 359.
Oregon State Board of Forestry metal location poster on 25" Fir BT.
Set 4 x 4 x 72" White painted Cedar post 1.0 ft. SE of Stone.

Arnold G. Gibson
Elbert Driver, Trustman
Wit: R. Banks - D. Timmons
November, 1958
C. S. File No. 42/403

See Cors. 31-32

Section Corner common to Secs. 17 - 18 - 19 and 20. ²²
Orig.: 5" Fir (missing; point falls in old landing) from which a:
10" Fir bears N.50°E. 25 lks.; missing, rotted stub at 35 lks.
6" Fir bears S.45°W. 22 lks.; missing; point falls in old landing.
10" Hemlock bears S.50°E. 19 lks.; missing.
10" Fir bears N.35°W. 40 lks.; missing, landing area.
Retracement by Wm. R. Whipple, 1893, ½" x 4' I.R., missing, from which:
36" Burnt Fir bears N.1°E. 134 lks.; burnt & rotted stub.
8" Cedar bears S.38°E. 94 lks.; down & rotted uproot.
30" Cedar stub bears S.46°W. 66 lks.; missing.
30" Burnt Cedar bears N.41°W. 210 lks.; point falls in cat road.
Restoration by Elliott State Forest Survey, 1939
4" x 4" x 4' Hemlock post (found, down & partially decayed, scribes visible)
18" Alder S.64°W. 46 ft.; missing, landing area.
Note: Old line blazes found South, East, and West.
Restored: Set 1½" x 36" I.P. with bronze cap, from which a:
48" Hemlock stump bears S.42°W. 109.2 ft.; scribed T22S R11W S19 B.T.
12" Cedar bears S.14½°E. 136.1 ft.; scribed T22S R11W S20 BT.
12" Alder bears N.74°E. 64.9 ft.; scribed T22S R11W S17 BT.
28" Fir bears N.43°W. 196.1 ft.; scribed T22S R11W S18 BT. RS359.
Oregon St. Bd. of Forestry metal location poster on 14" Alder S.49°E.
18.0 ft. Set 4"x4"x72" Wh. painted Cedar Post 2' SW of pipe.

Arnold G. Gibson
Elbert Driver, Trustman.
Wit: R. Schulsen
J. Hellingwerth
May 24, 1960
C.S. 42/403

Sec Cor 18, 19 (WEST BODY) ²³
Orig: 16" x 20" Fir stub (missing) from which a:
12" Fir bears N.60°W. 24 lks., now 50", evidence of Orig. face showing in bark.
6" Willow bears S.2°W. 22 lks.; missing.
5" Cherry bears N.5°E. 24 lks. missing.
10" Fir bears S.85°E. 45 lks.; now 42"; face grown over.
Rest. by C. A. Slang, 1910
Sandstone 20" x 10" x 8" (fd. badly weathered with 3 notches on N and S sides from which a:
12" Hemlock bears N.72°E. 7 lks.; now 14" Fir scribe S visible
12" Hemlock bears S.79°E. 45 lks.; now 42" Fir, face grown over.
Restored: Set 1½" x 36" gal. Iron Pipe with 3" br. cap mkd: "Ore St. Bd. of Forestry" T22S R11W R12W S18S19S19S24 1960 RS359
20" in gr, with Orig. Stone along N. edge of pipe from which:
23" Fir bears S. 9°E. 11.5 ft.; scribed T22S R11W S19 BT.
31" Fir bears N.88°W. 10.5 ft.; scribed T22S R12W S24 BT.
10" Spruce " N.75°E. 19.9 ft.; scribed T22S R11W S18 BT.
42" Orig. Fir BT bears S.85°E. 29.7 ft.; scribed BT.
50" Orig. Fir N.60°W. 15.8 ft.; scribed BT RS359.

Filed January 1961
C. S. File No. 42/403

Line Tree common to Secs. 19 & 24, T22S, R11 & 12W. ²⁴
Orig. 30" Fir Line tree at 73.84 ch. S. on the E. boundary of Sec. 24 with 2 notches on N. & S. sides (now 48", in place, exposed one notch on S. side, 67 years. old.
Restored - Scribed Line Tree as Witness Point, WP S19 on E. side & W.P. S24 RS359 on W. side, from which a:
60" Fir bears S.31½°W. 31.0 ft.; scribed WP S24 BT.
52" Fir bears N.66½°E. 39.4 ft.; scribed WP S19 BT.
Oregon St. Bd. of Forestry metal location poster on 60" Fir BT.

SEE CORNER No. 37 for cors.
SET AT SAME TIME

File ok
197 New
changes
M 112-29