

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 11 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Meander Corner to North Bank of River in Section 1. 48

Set: 5/8" x 44" Rod
50" Fir S.68°E. 46.0 ft.
40" Cedar N.88°W. 61.0 ft.

By G. Robert
Lecklider
Oct. 1961
C.S. File
No. 51/215

For Reedsport Milling

1/4 Corner West Side Section 11. 49

Set - G. I. P. 32" in ground.
18" Fir S. 3° E. 42.2 ft. - 13" Fir N.64°E. 11.7 ft. YMLP
White Painted Cedar Post S. E. 1.0 ft.

East 1/4 Corner Section 10 only. 50

1/4 corner reestablished.
Set - 1 1/2" x 36" Gal. Iron Pipe with 3" Bronze Cap.
26" Fir S.10°W. 53.8 ft.
14" Maple N.77°W. 26.7 ft. YMLP
Wh. Pntd. Cedar Post N.W. 1.5 feet.
Elliott Survey Post 1941, East 20.0 feet.

1/4 Corner to Sections 11 and 12. 51

Set - G. I. P. 30" in ground.
22" Fir N.44°E. 9.6 ft. - 24" Fir S.14°W. 28.4 feet.
YMLP on 12" Madrone S.30 1/2°E. 8.2 feet.
ESP S.80°E. 82.0 ft. - WPCP NE. 1.5 feet.

Center 1/4 Section Corner to Section 11. 52

Set - G.I.P. 30" in ground.
26" Fir STP. N.3°E. 4.5 feet. - 10" Fir S.42 1/2°E. 150.2 feet.
YMLP on 24" Fir Stp. N.89°E. 30.7 ft. on Ridge Top
WPCP S. E. 1.5 feet. - ESP East 78.1 feet.

North 1/4 Corner for Section 11. 53

Orig. - Stone 10' x 5' x 1' above ground (found in place but composed of several smaller segments to make the above size, X & musical 1/4 note visible on segment of stone) from which a: Stone 24x14x18" above ground bears S.14 lks.; found in place, split in half and badly sluffed, chisel marks visible.
Restored - Scribed a new 1/4 on North side of stone from which a:
34" Fir bears S.48 1/2°E. 48.9 ft.; scribed 1/4 S11 BT.
26" Fir bears N.31°E. 19.5 ft.; scribed RS359
Ore.St. Frstry Dept. metal location poster on 26" Fir BT.
Set 4x4x72" Wh. Pntd. Cedar Post 1.5 ft. SE. of Corner Stone.

Meander Corner common to Secs. land 2. 54

Found - Orig. Post (found 1" pipe in place & end of old post) from which:
20" Spruce bears S.42°E. 57 lks.; rotted 40" Stump in place, old axe work visible.
30" Spruce bears S.70°W. 68 lks.; now missing - point falls under edge of highway fill.

Line blazes due South on hillside.

Restored - ~~SS25~~ - 1 1/2" x 36" Gal. I.P. with 3" br. cap mkd: "Ore.St. Bd. of Forestry MC S2 S1 T22S R11W 1963 RS359", 30" in ground, over top of above 1" pipe, in mound of sandstone & from which:
Rock face bears S.51°W. 98.7 ft.; scribed X BO
8' up from ditch line of highway.
Rock face bears S.7°E 99.3 ft.; scribed X BO 12" up from ditch line of highway.

Ore.St. Frstry Dept. metal location poster on 20" Spruce S.62 1/2°E. 123.1 ft.
Set - 4"x4"x5' plain Cedar Post 1 ft. SE of corner pipe.

State of Oregon - Dept. of Forestry
Arnold Go Gibson - Wlt: J. Hollingsworth - D. Bagger - H. Baughn
June 1963
C. S. File No. 51/260
Map File M 26 - 25

Fd. 8/65
BY JAMES P. MACHINIA
M 99-21 A-B