

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 11 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

State of Ore.
June 1963
C.S. File No.
51/260
Map File
M 26 - 25

Witness Point (common to) Sections 11 and 12. 55
Found - Orig. 12" Fir Line Tree at 77.14 chains (now 20" uproot, 2 notches on the N. and 2 on the S. sides.
Restored - Set $\frac{3}{4}$ " x 25" Gal. I.P. 18" in ground, in large mound of Rock, and from which a:
13" Fir bears S. 35° E. 20.6 ft.; scribed WP S12 BT.
26" Fir bears N. 72° W. 24.6 ft.; scribed WP S11 BT.
10" Cedar bears N. 84° E. 12.4 ft.; scribed RS 359.
Oregon State Forestry Dept. Metal location poster on 10" Cedar.

$\frac{1}{4}$ Corner common to Sections 14 and 23. 56
Orig: Stone 20" x 12" x 8" (fd. in place $\frac{1}{4}$ on N. side) from which:
24" Cedar Stub bears N. 10, W. 90 lks., missing (this area heavily burned since original survey).
24" Fir Stub bears S. 68, W. 190 lks.; missing (burned out).

Restoration by 1941 Elliott Survey
2"x2" Cedar Stake (found on West side of corner stone).
Restored - Set 4x4x72" white painted Cedar Post 1.0 ft. W. of corner stone, in mound of rock & from which a:
30" Fir bears S. 59, E. 32.5 ft.; scribed $\frac{1}{4}$ S23 BT RS359
Rock bluff 8' x 10' x 4' High facing west bears S. 8, E. 38.4 ft.; scribed XBO.

Sec. Cor. common to Secs. 14, 15, 22 & 23. 57
Orig: Stone 20"x20"x10" (fd. in place, mkd. X, 3 notches S. and 2 notches E.) from which a:
12" Alder bears N. 51 E 34 lks.; now missing.
10" Alder bears S. 8 E. 28 lks.; now missing.
10" Fir bears S 31 W 71 lks.; now rotted 3 ft. high stump, portion of scribe remaining.
8" Fir bears N. 36 W. 26 lks.; now rotted 1 ft. high stump, portion of scribe T remaining.
Restoration by 1941 Elliott Survey:
Cedar Post (fd. 4' x 4' x 8", on N. side of corner stone) from which:
8" Alder bears N. 83 E. 6 lks.; found, now 12", overgrown.
Restored - 36" Fir bears S. 36 E. 73.7 ft.; scribed T22S R11W S23 BT.
12" Alder bears N. 80 E. 4.0 ft.; scribed T22S R11W S14 BT.
19" Fir bears S. 88 W. 97.0 ft.; scribed T22S R11W S22 BT.
24" Fir bears N. 78 W 99.0 ft.; scribed T22S R11W S15 BT RS 359.
Ore. St. Forestry Dept. metal location poster on 28" Cedar W. 62.6 ft.

Sec. Cor. common to Secs. 14 & 15 (North end). 58
Orig. - Stone 16"x12"x10" in stone mound (fd. in place on top of ridge, notches weathered & indistinct, 3.93 ch. E. of Sec. Cor. 10 & 11).
Restoration by 1941 Elliott Survey.
14" Fir bears S. 55 W. 18 lks.; now 20", blaze grown over, uprooted to north.
Restored - Set: 4x4x72" white painted Cedar Post 2.0 ft. SW. of corner stone, from which a:
17" Fir bears S 37 $\frac{1}{2}$ W. 20.0 ft.; scribed T22S R11W S15 BT.
14" Fir bears S 82 $\frac{1}{2}$ E. 48.7 ft.; scribed T22S R11W S14 BT RS359.

$\frac{1}{4}$ Corner common to Sections 15 and 22. 59
Orig. - Post (now missing) from which a:
50" Burnt Fir bears S 87 W 192 lks.; now 50" rotted, burnt, 15 ft. high stub, orig. scribe S & more recent knife scribes BT.
Restored - Set: 1 $\frac{1}{2}$ " x 36" gal. iron pipe with 3" br. cap mkd: "Ore. St. Bd. of Forstry $\frac{1}{4}$ S15 S22 1963 RS359, from which a:
34" Fir bears N. 32 W. 21.6 ft.; scribed $\frac{1}{4}$ S15 BT RS359
24" Fir bears S. 46 $\frac{1}{2}$ W. 29.7 ft.; scribed $\frac{1}{4}$ S22 BT.
Set 4x4x72" White painted Cedar post 2 ft. south of corner pipe.
Ore. St. Forestry Dept. metal location poster on 14" Fir N. 79 W 5.8 ft.

Arnold G. Gibson
Ore. State Board of Forestry
R. Schulson & T. South
November 1963
C. S. File No. 51/260