

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 11 W. R. W. W. M.

KOKS-CHAPMAN CO., EUGENE, ORE. 97101

Ore. St. Bd. Forestry.
Arnold G. Gibson
(E. D. Kucera)
11/6/68
C.S. File
No. 55/101

Ore. St. Bd. of Forestry
Arnold G. Gibson
(E. D. Kucera)
12/16/68 C.S. 55/101

Arnold G. Gibson, Bd. of
Forestry
E. D. Kucera
Map File M 38 - 53

Arnold G. Gibson
C. S. File No. 55/154

1/4 Corner to Section 16 (West Side)
Orig. - 24x16x16" Sandstone (in place, good condition, X and 1/4 on W. Face)
36" Fir bears S. 80° E. 135 lks.; now 60" Stump, in place, used
for guyline stump, notched and spikes remain, no face visible.
4" Alder bears S. 49° W. 89 lks.; now missing.
Set - 4 x 4 x 72" white painted Cedar post 1.0 ft. SW of corner stone:
23" Fir bears S. 12° E. 16.8 ft., to face, scribed 1/4 S16 BT.
17" Fir bears S. 59° E. 9.4 ft., to face, scribed 1/4 S16 BT RS359.
Ore. St. Forestry Dept. metal location poster on 17" Fir BT S. 59° E. 9.4 ft.
Nov. 6, 1968

Northwest Corner for Section 16.
Orig. - Stone 10x8x7", now missing, logged area, from which a:
30" Fir bears S. 21° E. 25 lks.; now missing.
16" Fir bears S. 52° W. 6 lks.; now a 16"x10" stub that was
growing from a root on the N. side of a 50" Fir stump,
bearing S. 30° W. 6.5 ft.; exposed scribes 2S.
20" Fir bears N. 54° W. 11 lks.; now missing.
Restoration by Warren D. Hootman, 1958, See Ren. #15.
Set - 1 1/2"x36" galv. iron pipe with 3" bronze cap mkd: "Ore. St. Bd. of
Forestry S9 S8 T22S R11W S16 1968 RS 359", 34" in ground,
and from which a:
48" Fir Stump bears N. 12° W. 35.6 ft.; scribed T22S R11W S9 BT.
44" Fir Stump bears S. 69° W. 15.7 ft.; scribed T22S R11W S8 BT.
No trees available for BT's. in section 16.
Found - 4"x4" white post (missing) 4 ft., N. and all Orig. BT's.
Mkd. 60" D. Fir N. 8 1/2° W. 34.0 ft.; now missing, edge of slideout.
Set - 4x4x72" white painted Cedar post 1.0 ft. S.E. of corner pipe.
Ore. St. Forestry Dept. metal location poster on 48" Fir stump
BT N 12° W. 35.6 ft.
Also BLM poster on the orig. 16" Fir S. 52° W. 6 lks.

Closing Corner to Sections 32 & 33, T22-11W.
Reestablished - Set - Ore. St. Bd. of Forestry 1 1/2"x36" Galv. I. Pipe
with 3" Br. Cap 34" in ground.
25" Maple, in clump N. 14 1/4° W. 47.5 ft. with yellow metal location poster.
26" Alder N. 9° E. 173.0 ft. (RS 359)
4x4x72" white painted cedar post east 1.0 ft.
10' Creek, course W., N. 19.0 ft.

1/4 Corner Section 5 only, T23-11W.
Reestablished - Set - Ore. St. Bd. of Forestry 1 1/2"x36" Galv. I.P. with
3" Brass Cap 34" in ground.
34" Fir S. 9 1/2° E. 36.4 ft. YMLP (RS359)
33" Fir S. 59° W. 33.1 ft.
4x4x72" White painted cedar post North 1.5 ft.
9/11/69

1/4 Corner for Section 13, East Side, T22S, R12W.
Orig. - Post, missing, reported destroyed by Slang in 1910, from which:
28" Fir bears N. 86° E. 12 lks.; now 36" windfall, axe work visible.
24" Fir bears S. 5° W. 36 lks.; now missing.
35" Fir Snag 75' tall, bears S. 65 1/2° E. 40.1 ft., to face; scribes "1/4"
visible in open face, no record of restoration.
Restoration by Slang, 1910: Post, missing, from which a:
42" Fir bears S. 80° W. 44 lks.; now 44" stump, in place, scribes visible.
36" Fir bears N. 49 1/2° W. 185 lks.; now 42", 56.1 ft., "X" above grown
over face.
Set - 1 1/2"x36" galv. I.P. with 3" br. cap mkd: "Ore. St. Bd. of For. 1/4 S13
1970 Rs 359", 34" in ground, and from which a:
45" Fir (Slang's) bears N 49 1/2° W 55.7 ft. to face; scribed RS 359.
37" Fir bears S 49° W 85.5 ft. to face; scribed 1/4 S13 BT.
Set 4x4x72" white painted Cedar post 1.0 ft. NE of corner pipe. Ore. St.
For. Dept. metal location poster on 45" Fir BT N 49 1/2° W. 55.7 ft.
6/18/70

82

83

84

85

86