

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 11 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

87

$\frac{1}{4}$ Corner common to Sections 14 and 15.

Found - Orig., Post(missing, found cedar post 1' S.W.) from which a:
6" Fir bears S.65°E. 35 lks., now 38", exposted scribes S1.
8" Fir bears S.23°W. 83 lks., now 34" Snag 50' tall, center
18", rotted out.

Restoration by Elliott State Forest survey, 1941.

Cedar post (see above)

Set - $1\frac{1}{2}$ "x36" galv. I.P. with 3" Br. Cap mkd:"Ore.St.Bd.of Forestry
 $\frac{1}{4}$ S15 S14 1970 RS359", 34" in ground, Elliott post alongside,
in mound of rock, & from which a:

11" Fir bears S.38 $\frac{1}{2}$ °W. 27.7 ft., to face; scribed $\frac{1}{4}$ S15 BT RS359.

3"x3' point of Sandstone Bedrock bears S.77 $\frac{1}{2}$ °E. 7.9 ft., to face;
chisled 6" X B0.

Set 4"x4"x72" white painted cedar post 3.8 ft. NW of corner pipe.

Ore.St.Forestry Dept. metal location poster on 38" Orig.Fir BT.S65E 21.6'.

8/10/70

88

Section Corner to Sections 15 - 16 - 21 - 22.

Found - Orig.12"x10"x8" Stone(in place,badly decomposed) from which a:

4" Fir bears N.25°E. 26 lks.; now 17" stp., chopped into,
no scribed visible.

6" Fir bears S.60°E. 4 lks.; now 21"x12 ft. stub, with 12"x6"x10'
section split out from base of chopping to top of stub.

8" Fir bears S.69°W. 15 lks.; now 21", face grown over.

7" Fir bears N.25°W. 11 lks.; now 19"x 11 ft. stump,
scribe "B" visible.

Restored: Set $1\frac{1}{2}$ "x36" galv. I.P. with 3" bronze cap mkd: "Ore.St.

Bd. of Forestry T22S R11W S15 S16 S21 S22 1970 RS 359",

24" in ground with orig. stone alongside, in mound of rock,
and from which a:

17" Fir(Orig) bears S.69°W. 9.9 ft. scribed "RS 359".

10" Fir bears S. 3°E. 48.8 ft., to face; scribed T22SR11WS15 BT.

24" Fir bears S.62°E. 43.3 ft., to face; scribed T22S R11W S22BT.

Set 4"x4"x72" white painted cedar post 2.8 ft. N28E of corner pipe.

Ore.St.Forestry Dept. metal location poster on 17" Fir S69°W. 9.9 ft.

7/15/70

89

Section Corner to Sections 4 - 5 - 8 - 9 .

Orig.- Post, missing, found Elliott 4"x4"x4' white post in mound
of rock, in place, from which a:

36" Fir bears N.48°E. 66 lks.; missing

36" Fir bears S.58°E. 20 lks.; now 20" x 12' rotted windfall.

24" Fir bears S.57°W. 45 lks.; now 31" windfall, downhill, out
of place, exposed scribes T2 11 (face N.83°W. 24.6 ft.)

24" Cedar bears N.36°W. 23 lks.; now 30" windfall, exposed,
orig. axe work, face rotted out, no scribes found.

Restoration by Elliott State Forest Survey, 1941, Cedar Post, See above.

Set - $1\frac{1}{2}$ " x36" galv. iron pipe with 3" br. cap mkd: "Ore.St.Bd. of
Forestry T22S R11W S4 S5 S8 S9 1970 RS359" 32" in ground, in
Elliott post hole, with Elliott post laying alongside, in
mound of rock, and from which a:

24" Fir bear N. 6° W. 116.5 ft., to face; scribed T22SR11W
S5 BT RS359.

42" Fir bears S.80°E. 38.7 ft., to face, scribed T22S R11WS9 BT.

43" Fir bears N.32°E. 41.6 ft., to face, scribed T22S R11W S4 BT.

Set - 4"x4"x72" white painted Cedar post 2.0 ft. S.45°W. of corner
pipe. Ore.St.Forestry Dept. metal location poster on 24" Fir
BT. N. 6° W.

9/29/70

90

$\frac{1}{4}$ Corner common to Sections 4 and 5.

Orig.Bluff of rock 15'x4' with cross(X) at exact corner point (Bluff
in place $\frac{1}{4}$ S visible) from which a:

8" Spruce bears S.88°W. 27 lks.;now 24" rotted stump, backcast S4 S vis.

24" Fir bears S. 1° E. 46 lks.;now 56", face grown over, in place .

Rewitnessed: Chiseled 4" X on Orig. Rock Bluff at exact cor. point, from which:

15" Fir bears S. 2 $\frac{1}{4}$ °W. 25.0 ft., to face; scribed " S 5 BT.

20" Fir bears N.17 $\frac{1}{2}$ °E. 49.9 ft., to face; scribed $\frac{1}{4}$ S 4 BT RS 359.

Set 4"x4"x72" white pained cedar post 2.2 ft. W. of corner stone.

Ore.St.Forestry Dept. metal location poster on 15" Fir S.2 $\frac{1}{4}$ °W. 25.0 ft.

12/18/70

Arnold G. Gibson, Ore. St. Bd. of Forestry
Lloyd D. Smith & David R. Brown
C.S. File No. 55/154

Arnold G. Gibson
Lloyd D. Smith
C.S. File No. 55/154

MARCH 71