

Douglas County Surveyor's Record of
Government Corners Renewed

T.22 T. S. R.11 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

(Continued)

Lloyd D. Smith L.S. 1101
For: State of Oregon Dept. of Forestry
May 1, 1991
M 112 - 29

New Accessories - 171
34" cedar (1961) rescribed "1/4 S19 BT" & bearing tree tag.
7" fir S.60°W., 5.4 ft. scribed "1/4 S30BT" & bearing tree tag.
6" fir N.48°W., 16.4 ft. scribed "1/4 S19 BT" & bearing tree tag
White painted 4 x 4 cedar post N.24°E., 2.0 ft.

6/91

Section corner for sections 17, 18, 19, and 20. 172

Found - Oregon State Board of Forestry 3" bronze cap dated 1960 on
1 1/2" x 36" I.P. in place. See renewal # 22
BTs - 48" hemlock stump S.42°W., 109.2 ft. in place.
12" cedar S.14 1/2°E., 136.1 ft.- now 23" face closed, in place.
and bearing tree tag.
12" alder N.74°E., 64.9 ft.- now 16" bark scribes visible,
in place, and bearing tree tag.
28" fir N.43°W., 196.1 ft. - now 27" x 3' high stump, axe work
visible, face rotted, in place, and bearing tree tag.

New Accessories -
11" fir S.69°W., 42.6 ft. scribed "T22SR11W S19 BT" & brng tree tag.
10" fir N.2°W., 47.6 ft. scribed "T22SR11W S18 BT" & brng. tree tag.
White painted 4 x 4 cedar post S.29°W., 2.4 ft.

6/91

1/4 Corner for sections 19 and 20. 173

Found - Oregon State Board of Forestry, 3" bronze cap dated 1961 on
1 1/2" x 36" I.P., in place. See renewal # 46
BTs - 24" cedar N.82°E., 63.9 ft.- now 32" x 4' high stump, in place
with bearing tree tag.
New Accessories -
7" fir N.4°E., 33.2 ft. scribed "1/4 S20 BT" with bearing tree tag.
10" fir N.70°E., 57.8 ft. scribed "1/4 S20 BT" with bearing tree tag.
5" fir S.79°W., 1.5 ft. scribed "1/4 S19 BT" with bearing tree tag.
Orange carsonite marker, S.29°W., 5.7 ft. to base.
White painted 4 x 4 cedar post S.29°W., 5.7 ft.
1' wide creek north 1.0 ft. course, southeast.

6/91

East 1/4 Corner for Section 36 174

Found - 3" OSBF brass cap on an Iron pipe, found 5" below ground.
Ren. No. 117
Orig. NE BT is gone.
39" now 36" dia. 1 1/2 ft. high D.Fir stump with a fully healed
single blaze, bears N.53°W. 31.7 ft. (Rec. N.53°W., 31.0 ft.
dist. is a face measurement. Ren. No. 117
32" now 36" dia. 5 ft. high D.Fir stump with a fully healed
single blaze bears S.54 1/2°W., 87.8 ft. (Rec. S.54 1/2°W., 86.8 ft.
dist. is a face measurement. Ren. No. 117
New BTs - 30" dia. 4 ft. high D.Fir stump with boat spike through BT tag
set on top of stump near center, Boat spike stumped
"BO 1". Spike bears N.34°E., 23.0 ft.
32" 5 ft. high D.Fir stump with boat spike through BT tag
set on top of stump near center, Boat spike stamped
"BO 2". Spike bears S.74°E., 32.0ft.

3/3/92

175

Meander Corner, Section 1; and Sec. 6 of T.22-10

Found - 2 1/2" DCSO brass cap on an iron pipe 3" below ground. Ren. #146
18" now 58" dia. broken top Spruce, with a rotted center,
partially healed, pitched over blaze, with illegible scribing
from M 56-56 visible. BT bears s.8°E., 111.5 ft. (agrees
with record) Orig. BT.

New BT - 9" dia. Alder bark scribed "MC S1 CS BT" bears S.9 1/2°W., 104.4 ft.
3/5/92

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
March 3, 1992
C.S. File 64/24

Douglas County
Surveyors Office
Randall Smith
March 5, 1992
C.S. File 64/24