

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 S T. S. R 12 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

50

Center of Section 11.

Set - 3/4" Iron Pipe, from which:

Bearing Trees: 8" Alder bears S.22°W. 9.2 ft. mkd. CS 1/4 S11 BT.
36" Cedar bears N.63°W. 74.8 ft.mkd. CS 1/4 S11 BT.

Jan. 1968

Richard J.
Hintz
M 33 - 29

51

Section Corner to Sections 14 - 15 - 22 - 23.

At the point 99' E. of the sharp spur & on E. slope:

Drove - 3/4" Copper Pipe 4' long 3 1/2' in the ground and a red cedar limb alongside of it for section corner, from which:

A D.Fir, 40" diam., bears N.20°W. 18.5 ft.
A D.Fir, 40" diam., bears S.31°E. 18.0 ft. (loc. tag on face)
Both trees scribed.

201

52

Section Corner to Sections 13 - 14 - 23 - 24.

At the point 66' North of the creek, I drove:

Drove - 3/4" copper pipe, 4' long, 3 1/2' into the ground for section corner. (The ground being soft, I found a piece of old 1" water pipe 7' long which drive alongside the copper pipe.) from which:

Bearing Trees: An Alder 10" diam., bears N.28°E. 22.3 ft.
A Spruce 9" diam., bears N.59°W. 38.5 ft.
An Alder 10" diam., bears S.5°W. 34.2 ft.

(The alders are bark-scribed, Loc.Tag on face)

Corner is located on the right side of a narrow draw bearing N-S at this point, and 348' south of the edge of the timber.

205

Clifford A. Stephens
For O.B. Walker
July 14, 1966 - Filed June, 1968
C.S. 55/80 Map File M 33 - 35

53

1/2 Corner between Sections 14 and 23.

Search for 1/2 section corner and find nothing.

Re-establish by driving a 4' long, 3/4" copper pipe, 3 1/2' in the ground for the corner, from which:

A D.Fir, 22" diam., bears N. 39° W. 45.3 ft.
A R.Cedar 10" in daim., bears S.62°W. 48.7 ft. (loc. tag on face)

The corner is east of a high spur bearing NE and SW, a dist. of 50 ft. The 10" Red Cedar BT is on the top of the spur. It is also at the foot of a rock face on SE slope.

FIN. OK 5/31
M 113-35 A&B

54

Section Corner common to Sections 26 and 35, (East end).

Found - Orig. 12"x12"x3' Fir Post (fd. orig. point with axe work).

32" Fir bears S.57°W. 17 lks.; now 44", face closed.

28" Fir bears N.67°W. 33 lks.; now 34", face partially rotted, exposed scribe 2.

Set - 1 1/2"x36" galv. iron pipe with 3" bronze cap mkd: "Ore.St.Bd. of Forestry T22S R12W S26 S35 S25 1968 RS 359", 34" in ground, in orig. post hole, in mound of rock, and from which a:

44" Fir (Orig) bears S.57°W. 11.2 ft.; scribed BT.

34" Fir (Orig) bears N.67°W. 21.8 ft.; scribed RS 359.

Set 4"x4"x72" white painted Cedar post 1.0 ft. S. of corner pipe.

Ore.St.Forestry Dept.metal location poster on 34" Fir BT N.67°W.

Also BLM poster on 44" Fir BT S.57°W.

Jan.1,1969

#142

Arnold G. Gibson, Ore.St.Bd. of Forestry
Wit: Geo. Gresham & Dave Brown - Roy Ball
C. S. File No. 55/101

55

Section Corner common to Sections 27 - 28 - 33 - 34.

Found - Orig. 4"x4"x4' Maple post (missing, fd. 1/2" iron pipe in place, Ren. #21.

6" Elder bears N.40°E. 48 lks.; missing

6" Elder bears S.46 1/2°E. 35 lks.; missing.

8" Maple bears S61 1/2°W. 29 lks.; missing, Maple rootsystem in place.

36" Cedar bears N.42°W. 24 lks.; now 70" in place, scribes visible.

Canyon, crs. SW, bears south 50 lks.; in place, creek in bottom.

Set - 1 1/2"x36" galv. iron pipe with 3" br. cap. mkd: "Ore.St.Bd. of Forestry, T22S R12W S27 S28 S33 S34 1969 RS359", 34" in gr, over 1/2" iron pipe: 70" Cedar (Orig.) bears N.42°W. 15.8 ft.; scribed RS 359.

20" Maple bears S.20°W. 50.2 ft., to face, scribed T22S R12W S33 BT.

59" Maple bears N.75°E. 74.6 ft. to face; scribed T22S R12W S27 BT.

37: Hemlock bears S.82°E. 110.1 ft. to face; scribed T22S R12W S34 BT.

Set-4"x4"x72" white painted cedar post 1.2 ft. NW of corner pipe.

Ore.St.Forestry Dept. metal location poster on 70" Cedar BT N.42°W.

FD. OK 7/25
D. K. W. 11/11/69

2/11/69