

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 12 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

60

Section Corner common to Sections 24 and 25 (West End)
Orig.-20"x16"x12" Sandstone, 15" in ground (missing, from which a:
8" Cedar bears N.45 $\frac{1}{4}$ °E. 53 lks.; now 17", in place, partially
closed face, scribes $\frac{1}{4}$ S2 visible.
16" Spruce bears S.77°E. 50 lks.; missing.
Set - 1 $\frac{1}{2}$ "x36" galv. Iron Pipe with 3" Bronze Cap mkd: "Ore.St.Bd.of
Forestry S26 T22S S24 S25 R12W 1969 RS359", 34" in ground, from which:
17" Cedar(Orig.) bears N.45 $\frac{1}{4}$ °E. 34.98 ft.; scribed RS359.
6' x 15' Rockface bears S.75 $\frac{1}{2}$ °E. 28.9 ft. to 6" X; scribed XBO.
Top of Spur Ridge, course N. & S., bears S.75 $\frac{1}{2}$ °E. 38.9 ft.
Set 4"x4"x72" white painted Cedar post 1.0 ft. SE of corner pipe.
Ore.St.Forestry Dept. metal location poster on orig. cedar N.45 $\frac{1}{4}$ °E.

$\frac{1}{4}$ Corner for Section 25 (West Side)
Orig.-12x12"x3' Cedar Post (missing) from which a:
15" Alder bears N.74°E.39 lks.; missing
24" Maple bears S.52°E. 40 lks; now 32" windfall, exposed scribe 5.
Ridge, course S.E. & N.W., bears North 89 lks.; in place.
Set - 1 $\frac{1}{2}$ "x36" Galv. iron pipe with 3" bronze cap mkd: "Ore.St.Bd.of
Forestry $\frac{1}{4}$ S25 1969 RS359", 34" in ground, and from which a:
17" Cedar bears S.60°E. 15.0 ft., to face; scribed " $\frac{1}{4}$ S25 BT RS359.
24" Cedar bears S.41°E. 44.6 ft., to face; scribed " $\frac{1}{4}$ S25 BT.
Set - 4"x4"x72" white painted cedar post 2.0 ft. N.W. of corner pipe.
Ore.St.Forestry Dept. metal location poster on 17" Cedar S.60°E. 15!
7/16/69

$\frac{1}{4}$ Corner for Section 26 (East Side)
Orig.-Hemlock Post (missing) from which a:
36" Fir bears N.50°E. 10 lks.; missing.
36" Fir bears N.05°W. 11 lks.; now 43", in place.
Restoration by Charles A. Slang, April 28, 1910.
Orig. Hemlock post, destroyed marks on E. side (now missing) from which a:
60" Fir bears N.23°W. 11 lks.; now 63" in place.
10" Cedar bears S.21°W. 26 lks.; now 12" in place, face partially
closed, scribed $\frac{1}{4}$ visible.
Set - 1 $\frac{1}{2}$ "x36" galv. iron pipe with 3" bronze cap mkd: "Ore.St.Bd.of
Forestry $\frac{1}{4}$ S26 1969 RS359", 34" in ground, and from which a:
11" Cedar bears S.66 $\frac{1}{2}$ °E. 14.6 ft., to face; scribed $\frac{1}{4}$ S26 BT RS359.
12" Cedar(Orig.) bears S.21°W. 17.1 ft., to face, scribed BT.
Set 4x4x72" white painted Cedar post 1.6 ft. S. of corner pipe.
Ore.St.Forestry Dept. metal location poster on 11" Cedar S.66 $\frac{1}{2}$ °E. 14.6 ft.
7/16/69

$\frac{1}{4}$ Corner to Sections 2 and 11.
Found - $\frac{1}{2}$ " Iron Pipe at $\frac{1}{4}$ Corner, See Ren. #42.
12", now 13" Hemlock, N.76 $\frac{1}{2}$ °W. 19.3 ft., scribe visible.
40", now 40" Hemlock N.65°E. 47.1 ft., scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 22 S R 12 W
Office $\frac{1}{4}$ S 2
1969 S 11
Tagged Bearing Trees. No good trees close to south.
This corner lies in bottom of ravine running S. Orig. call places
this corner 7 ch. from stream, not where this corner is set.
9/16/69

Section Corner to Sections 1 - 2 - 11 - 12.
Found - "T" Iron at Corner, See Ren. #27.
10" Hemlock, now stob, S.64°E. 14.3 ft., scribe visible.
22" Hemlock, now stob, N.25°W. 20.4 ft., scribe visible.
24" Cedar, now snag, S.52°W. 14.5 ft., scribe visible, "BT".
Tree downhill. All trees & stobs have Haines' tags on them.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 22 S R 12 W
Office S 2 | S 1
1969 S 11 | S 12
New BT's: 8" Cedar S.81°E. 15.2 ft. mkd: T22S R12W S12 CS BT.
14" Hemlock N.68°W. 6.5 ft. mkd: T22SR12W S 2 CS BT.
9/15/69

ORE. ST. BD. OF FORESTRY - ARNOLD G. GIBSON
WIT: Lloyd D. Smith, transitman
July and August, 1969 - C. S. File No. 55/101

John M.
Powell &
Crew
C.S. File
No.
54/46