

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 12 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

70

1/4 Corner to Sections 23 and 26.
1/4 Corner Reestablished by Proportionate Measurement.
Set - Ore. St. Bd. of Forestry 1 1/2"x36" Galv. Iron Pipe with 3" Bronze Cap,
in Mound of Rock.
"X" on Sandstone Rock Face N. 18° E. 8.7 feet, Bearing Object.
8" Alder S. 9° W. 38.0 ft., Yellow Metal Location Poster (RS359)
1.0 ft. Creek, South 12.5 ft., course N. 80° W.
4"x4"x72" White Painted Cedar Post bears S. E. 2.0 ft.

Arnold G.
Gibson
M 33 - 79

Mar. 20, 1970

71

Center 1/4 Corner of Section 26.
Established - Set - O.S.B.F. P/C 32" Galv. I.P. with 3" Bronze Cap.
32" Cedar S. 2° E. 111.7 ft. YMLP.
28" Hemlock N. 52° W. 42.3 ft. (RS 359)
4"x4"x72" White Painted Cedar Post bears S. 35° E. 2.6 feet.

Ore. St. Bd.
of Forestry
M 33 - 79

72

Section Corner to Sections 2 and 3 only, T23-12W. (Witness Corner)
Beginning at the Sec. Cor. to 2 & 3 only, we found the corner as
established by Stephens, referenced by a witness corner which is
167.5 feet S. along the section line of the true corner point. At
witness corner, we found a 3/4" iron pipe from which:
24" Cedar S. 70° E. 61.4 feet
18" Fir S. 39° W. 28.7 feet.
I scribe a 12" Maple S. 42° E. 6.2 feet.

1/4 Corner to Section 3 only, T23-12W.
Thence from the true corner point S. 89° 49' 50" W. on the true
north line of Sec. 3. Set 1/4 Corner proportionate distance, 2,717.66 ft.
Set - 1" Iron Pipe, from which:
8" Chittum S. 82° E. 2.4 feet
18" Fir S. 14° W. 60.2 feet
24" Fir S. 23 1/2° E. 64.3 feet.

Section Corner to Sections 3 and 4 only, T23-12W.
Found - 3/4" Iron Pipe for section corner, from which:
30" White Fir Stump with Tag N. 41° E. 33.0 feet.
Myrtle Clump S. 35° W. 17.8 feet.
I scribed: 26" Fir N. 80° W. 14.9 feet.
50" White Fir N. 50° W. 20.6 feet.

Sec. corner to Secs. 31 & 32, T21-11W & Secs. 5 & 6, T22-11W.
This corner set from survey & lies in large field S. of Hwy. #38.
Set - Brass Cap at Cor. Mkd: County Surveyor's T21S R11W S 31 S 32
Office, 1971 T22S S 6 S 5
Also Set Steel Fence Post alongside Brass Cap.

Reference Monument 1 for Sec. Cor. 31 & 32, T21-11W.
and Secs. 5 & 6, T22-11W.
Set - Brass Cap on Township Line, 44.35 ft. W. of sec. cor.,
said cap is flush with ground on highway shoulder mkd:
County Surveyor's T21S R11W RM 1 S 31
office, 1971 T22S S 6
This cap lies on S. edge of Hwy. 7.0 ft. S. and 9.0 ft. E. of pavement edge.
Bearing Objects: 5/8" Iron Rod West 70.0 feet
5/8" Iron Rod North 50.7 feet.

Witness Corner to 1/4 Corner to Sec. 36 only, T21-12W.
This cor. set from survey & lies about 6 ft. S. of driveway.
Wit. Cor. 250.24 feet N. of 1/4 Corner
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 21 S R
Office 12 S 36 1/4 11
1971 W W
Bearing Tree & Bearing Objects: 17" Maple N. 82° E. 67' mkd: "W.C. SS BT".
5/8" I. Rod N. 78 1/2° W. 68.5 ft. - 5/8" I. Rod S. 89° W. 34.7 feet.

73

74

75

Ronald E. Stuntzner
Nov. 14, 1970
C. S. File No. 55/172

RE-RENEWED
#220
Fd. OK 1/8/6
M100-37
By Lloyd Smith

RE-RENEWED
#178
Fd. OK 1/8/6
M100-37
By Lloyd Smith

RE-RENEWED
#221
Fd. OK 1/8/6
M100-37
By Lloyd Smith

SEE ALSO C.S. 58/31 - BY EWEN. SURVEY 11/14/70

MARCH 71