

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 12 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

J.W. Byron, Co.
Surv.
Feb-June 1971
C.S. 56/5
M 42 - 27

South 1/16 Corner btwn. Sections 1 and 2. 88
Corner set from survey, & lies about 25 ft. N. of ridge top, runs E-W.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office T 22 S R 12 W
1971 S 1/16 S 2 | S 1
New BT's: 8" Hemlock S.19°E. 11.2 ft. scribed "S1/16 S1 CSBT".
10" Hemlock S.50°W. 13.2 ft. scribed "S1/16 S2 CSBT".

5/4/71

1/4 Corner to Sec. 36, T21-12W. & Section 1, T22-12W. 89
Corner set from survey & lies on top of very steep drop-off to
the westerly bank of the Umpqua River.

Set = Brass Cap at Cor. Mkd: County Surveyor's Office, 1971 T21S R12W 1/4 S 36
T22S S 1

Set Steel Fence Post alongside Brass Cap.

Bearing Tree: 18" Hemlock S.76°W. 81.8 ft. scribed "1/4 S 1 CS BT".

6/10/71

Sec. Cor Secs. 18 & 19, T22-12, & Sec. 13 & 24, T22-13. 90
Set Post from old BT's.

Marking Witness Trees, as follows:

30" Spruce N.15°W. 16 lks., Orig. BT.

10" Spruce S.32°W. 41 lks., Orig. BT.

30" Spruce S.72°E. 68 lks., Orig. BT.

30" Spruce S.62°37'W. 49 lks., New Witness Tree.

8-13-73 - FOUND? - V.R.T. C.S. 56/35

H. L.
Eppstein,
Co. Surv.
C.S. 18/20A
& B
Map File

M 1 - 74

1/4 Corner betwn. Secs. 13, T22-13 & Sec. 18, T22-12.
Set Post from Orig. BT.

Marking Witness Trees, as follows:

40" Spruce N.50°E. 22 feet, Orig. BT.

New Witness Trees: 40" Spruce S.55°E. 37.7 ft.

50" Spruce N.85°W. 28.0 feet.

Jan 1992

Oct. 1931

Closing Corner reestablished for Secs. 13 & 24 only. 92
Set-Ore.St.Bd. of Forestry I.P. with 3" Bronze Cap, 34" I.G.

6" Alder N.45-1/4°W. 20.2 ft. (RS359)

4" Alder S.58°W. 19.9 ft., YMLP

4"x4"x72" White painted Cedar Post N.W. 2.2 ft.

AP Corner Section 24, reestablished 93
(Orig. Cor. 13 & 24 by Whipple 1893)

Set-Ore.St.Bd. of Forestry I.P. with 3" Bronze Cap, 34" IG

9" Alder S.89-3/4°W. 14.2 ft. YMLP

11" Cedar S.29-1/2°W. 50.8 ft. (RS359)

WPCP N.W. 1.5 feet

1/4 Corner to Sec. 24 (East Side) 94

Set - 1-1/2"x24" OSBF I.P. with Bronze Cap 20" in concrete in Sandstone.

23" Burnt Fir Stump S.79-1/2°W. 99.22 ft. (RS359)

37" Hemlock Stump N.8°W. 98.10 ft.

4"x4"x72" White Painted Cedar Post North 4.0 ft., YMLP

A.P. Corner Section 24, reestablished. 95
(Orig. 1/4 corner 24 by Whipple 1893)

Set-OSBF 1-1/2"x36" I.P. with 3" Bronze Cap 52" in ground, on South Edge of Scholfield Ridge Road.

4"x4"x72" White Painted Cedar Post S.21-3/4°W. 27.5 ft., YMLP

1/4 Corner reestablished for Sections 13 and 24. 96

Set-OSBF 1-1/2"x36" I.P. with Bronze Cap 32" in ground.

11" Alder S.24°W. 41.0 ft.

37" Hemlock N.15°E. 13.5 ft. (RS359) YMLP

4"x4"x72" white painted cedar post N.50°E. 2.8 feet.

Oregon State Dept. of Forestry - Arnold G. Gibson
June 23, 1971 Map File M 44 - 33

RE-RENEWED CORNER NO. #152
RE-RENEWED CORNER NO. #136
RE-RENEWED CORNER NO. #239

PO. OK 2/20/75
SURV. OFFICE
CO. L.E.M. 5/1/46
C.S. 56/46

FND OK 5/91
M 112-29