

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T.S. R. 12 W. R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner Section 23 only (East Bdry.)
Set- OSBF 1-1/2"x36" I.P. with 3" Bronze Cap, 34" in ground.
9" Cedar N.68-1/2°W. 19.1 ft., YMLP
18" Cedar S.30°W. 33.6 ft. (RS359)
4"x4"x72" white painted cedar post N.60°W. 2.0 feet.

97

1/4 Corner Section 24 only (West Bdry)
Set-1-1/2x13" OSBF I.P. with 3" Bronze Cap ,9" in concrete
in Sandstone Bedrock.
6" Alder S.54°E. 30.1 ft. (RS359) YMLP
"X" on 4' x 4' Bedrock Face S.26°E. 68.8 ft., 6" (X BO)
4"x4"x72" white painted cedar post S.15°E. 3.5 feet.

98

Center 1/4 Corner Established, Section 24.
Chiselled 8" X in Sandstone Bedrock Face in slide out in
draw, crs. North.
56" Fir N.53-1/2°W. 23.8 ft. (RS359) YMLP
X on 4'x5' Sandstone Point S.64°E. 52.6 ft., 6" (X BO)
1-1/2"x14" OSBF I.P. with Bronze Cap 8" in concrete in
Sandstone Ledge S.001/2°E. 11.7 feet.
4"x4"x72" white painted cedar post S.31°W. 13.0 feet.

99

1/4 Corner for Section 25 (West side)
Original 12" x 12" x 3' Cedar post (missing) from which a:
15" Alder, bears N.74°E., 39 lks.; missing.
24" Maple, bears S.52°E., 40 lks.; missing.
Ridge, course SE & NW, bears North 89 lks.; in place.
1969 Restoration, 1 1/2" x 36" galv. iron pipe with 3" bronze cap (found
out of place) from which a: Ren. No. 61
17" Cedar, bears S.60°E., 15.0 ft.; now 20" stump, scribes 1/4 S25 BT
RS 359 visible in partially closed face.
24" Cedar bears S.41°E., 44.6 ft.; now missing, in road construction.
4" x 4" x 72" white painted cedar post bears Northwest 2.0 ft.; now
missing, in road construction.
Set - 1 1/2" x 36" galv. iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S25 1969 RS 359", 35" in ground, and from which a:
17" Cedar bears N.66°E., 52.1 ft. to face; scribed 1/4 S25 BT.
50" Fir, bears N.10°E., 58.9 ft. to face; scribed 1/4 S25 BT RS 359.
Center Wilkins Ridge Road (course NW & SE) bears North 23.0 ft.
Set - 4" x 4" x 72" white painted Cedar post 6.0 ft. N.37°E., of corner
pipe. Oregon State Forestry Department metal location poster on
17" Cedar BT N.66°E., 52.1 ft.

100

May 30, 1972

Section Corner to Sections 26 - 27 - 34 - 35
Section Corner reestablished. (See Cor. No.69)
Set-OSBF 1 1/2"x36" G.I.P. with B.Cap, 34" in ground.
15" Fir N. 2 1/2°W. 29.4 ft. (RS359)
23" Fir S.15 1/2°W. 8.3 ft, YMLP
14" Myrtle (in clump of three) S.84°E. 41.3 ft.
11" Fir N.87 3/4°E. 60.9 ft.
4"x4"x72" White painted Cedar Post West 1.4 ft.

101

1/4 Corner to Sections 27 and 34.
1/4 Corner Reestablished. (See Cor. No. 68)
Set OSBF 1-1/2"x36" B.I.P. with Bronze Cap, 34" in ground.
37" Spruce N.73°W. 3.8 ft., YMLP
16" Fir S.28°E. 19.2 ft. (RS359)
4"x4"x72" White Painted Cedar Post N.65°E. 1.6 feet.

102

FD. # 4500 5/87
M 44-31
M. 1244

Oregon State Board of Forestry
Arnold G. Gibson
June 23, 1971
C. S. File No. M 44 - 33

Oregon State Board of Forestry
Arnold Gibson
Rodney T. Shepard
May 30, 1972
C.S. File 55/233

Oregon St.
Board of
Forestry
By-Arnold
B.Gibson

March, 1970
Correction
Filed
11/10/72

Map File
M 42 - 76

JAN 1973

FIND OK 5/91
M113-35A#B