

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 12 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

118

Closing Corner common to Sections 30 and 31 only, T.22-11.  
Found - Orig. 18"x12"x8" Stone (found in place, 5 notches  
on North side) from which a:  
36" Fir stub bears N.65°E., 45 lks.; now 20"x24"  
high stub in place, burnt and badly decayed, no  
scribes visible.  
40" Fir stub bears S.45°E., 192 lks. missing, in  
new slide out draw.  
36" burnt Fir bears S.43°W., 193 lks.; missing.  
Spur Ridge bears East 131 lks.; in place.  
Rewitnessed: 45" Fir bears N.67°E., 5.3 ft. to face; scribed  
T22S R11W S30 CC BT.  
27" Fir bears S.48°E., 49.1 ft. to face; scribed  
T22S R11W S31 CC BT RS359.  
Set - 4"x4"x72" WPCP s.8 ft. N.33°W., of cornerstone.  
OSFD metal location poster on 20" Fir north 20.0 ft.

Oregon State Board  
of Forestry - Arnold Gibson  
Restored by William E. Metcalf  
Witnesses - A.J. Klosterman  
& J.L. Shumway  
CS 57/4  
June, 1974

6/17/74

119

1/4 Corner for Sec. 26. (East side)

Original

Hemlock post (missing) from which a:

36" fir, bears N.50°E., 10 lks.; missing.

36" Fir, bears N.05°W., 11 lks.; uprooted windfall.

Restoration, 1910

Orig. Hemlock post, destroyed marks on E. side (now missing) from which a:

60" Fir, bears N.23°W., 11 lks. uprooted windfall.

10" Cedar, bears N.21°W., 26 lks.; now 13" by 3 ft. high stub, in  
place, scribes 1/4 visible.

Restoration, 1969

Ren. #62

1 1/2"x36" galv. I.P. with 3" bronze cap (found out of place in root  
wad of uprooted BT, 25 ft. downhill), from which a:

11" Cedar bears S.66 12/°E., 14.6 ft.; uprooted windfall.

4"x4"x72" WPCP bears South 1.6 ft.; found lying on ground knocked  
out of place by uprooted BT

Restored

Re-set above Gal. I.P. with 3" bronze cap and re-marked " OREGON STATE  
BOARD OF FORESTRY T22S R12W 1/4 S26 1974 RS 359," 35" in ground  
and from which:

68" Fir, bears N.22 1/2°W., 35.1 ft. to face; scribed 1/4 S26 BT.

59" Fir, bears N.73°W., 32.6 ft. to face; scribed 1/4 S26 BT RS 359.

Set - 4"x4"x72" white painted cedar post S.02°E., 4.8 ft. from corner  
pipe. Oregon State Forestry Department metal location poster on  
68" Fir BT N.22 1/2°W., 35.1 ft.

1/7/75

1/4 Corner for Section 36 only. West boundary (wit. cor.)

Found - 2 BT's (Stephens 1952)

Set - To witness corner, Set S.04°52'37"E., 54.5 ft. a  
Oregon State Board of Forestry 1 1/2"x36" Galv. I.P. & 3" bronze cap,  
42" in the ground.

21" Alder, N.38°E., 71.4', RS 359

12" Alder, S.34°E., 168.8 ft.

4"x4"x72" White painted cedar post, S.15°E., 2.7 ft. with yellow  
metal location poster.

4/75

121

Center 1/4 Corner for Section 25.

Set - Oregon State Board of Forestry 1 1/2"x36" Galv. I.P. and 3" Bronze  
cap 35" in the ground.

BT's - 33" Fir, stump, S.14°E., 59.7 ft.

35" Cedar, N.30°W., 29.2 ft. RS 359, with yellow metal location  
poster.

White painted cedar post, N.76°W., 5.3 ft.

4/75

Oregon State Board of Forestry  
Aronold G. Gibson  
Restored by William E. Metcalf  
Jan. 7, 1975  
C.S. 58/31

Oregon State Board of Forestry  
Arnold G. Gibson  
Restored by William Metcalf  
April, 1975  
M 55 - 73

*Fd OK 1186 by Lloyd Sumner with witness 1100-38 1/21/89 C.S. 63/91 M 107-66*