

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 12 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

State of Oregon Department of Forestry
Arnold G. Gibson
Restored by William Metcalf
April, 1975
M 55 - 73

1/4 Corner for Sections 25 and 36. 122
Set - 1 1/2" x 6" OSBF pipe and cap 6" in concrete, in sandstone bedrock.
BT's - 30" Cedar, N.47°E., 44.4 ft.
19" Cedar, S.32°W., 63.6 ft. RS 359, with yellow metal location
poster.
White painted cedar post, S.22°E., 8.0 ft.
- - - - - 4/75

1/4 Corner for Section 25 only. East boundary Ren. #26 123
Set - Oregon State Board of Forestry pipe and cap 3/4" in the ground.
BT's - 22" Cedar, S.53 1/2°W., 53.0 ft. RS 359 with yellow metal location poster
18" Myrtle, N.80°W., 78.2 ft.
White painted cedar post, S.49°E., 5.9 ft.
- - - - - 4/75

Closing corner for Sections 25 and 36 only. Ren. #25 124
Set - 1 1/2" x 10" OSBF pipe and cap 10" in concrete.
BT's - 11" Myrtle, S.32°W., 45.3 ft.
36" Fir, N.79°W., 124.2 ft. RS 359 with yellow metal location poster.
- - - - - 4/75

1/4 Corner for Section 36 only. East boundary 125
Set - OSBF pipe and cap 3/5" in the ground.
BT's - 23" Maple, N.13°W., 74.60 ft. RS 359, with yellow metal location
poster.
6" x on 5' x 4' rock face, S.85°E., 7.4 ft.
White painted cedar post, S.70°E., 3.5 ft.
- - - - - 4/75

1/4 Corner for Secs. 21 and 28 126
Found - 24" now 21" Alder (?) scribe illegible. Bears S.79°W., 49.5 ft.
Ren. #20
18" now 16" Alder snag 13 ft. high. No scribe visible. Tagged
"Moore Lo. Co. S 21 Twp 22 R 12 S 1/4 Cor"
Did not find 1" I. Pipe.
Set - Brass cap 3" dia. at 1/4 cor. stamped "T22S R12W 1/4 S21 S28 1976,
Douglas County Surveyors Office. Position of cap determined
by County Surveyor Project #6004-16. Brass cap set in drill
hole in rock. See C.S. 59/15 attached pages for computations.
New BT's - An Alder 15" bears S.48°09'E., 32.0 ft. Tree double blazed and
scribed "1/4 S28 CS BT".
An Alder 16" bears N.26°40'E., 34.0 ft. Tree double blazed and
scribed "1/4 S21 CS BT".
Set steel fence post and witness sign S.60°W., 2.5 ft. from cor.
Note - Corner falls on a steep rock face sloping NE.
- - - - - 5/4/76

West 1/4 Corner of Section 13. 127
Found - A cedar post set by Clifford A. Stephens in 1965. Ren. #38
Orig. BT, now a 40" Fir stump, bears N.62°00'W., 23.1 ft.
The Hemlock is gone.
Set - From the above mentioned BT, I Set a 3/4" x 36" Gal. I.P. with
brass cap.
A 14" Hemlock, bears N.35°00'W., 19.4 ft.
A 6" Hemlock bears N.50°30'E., 39.6 ft.
I replaced the post set by Stephens with a 4"x4"x6' cedar post. This post
bears S.72°00'E., 2.2 ft. from my brass cap iron pipe.
- - - - -

North 1/4 Corner for Sec. 13. 128
Found - Cedar post set by Clifford A. Stephens in 1965. Ren. #36
Orig. BT now stump, A 50" Fir bears S.61°30'W., 72.6 ft.
Orig. BT now stump, a 50" Fir bears N.86°00'W., 31.6 ft.
Set - From the above mentioned BT's I Set a 3/4" x 36" Gal. I.P. with
brass cap.
A 20" Alder bears S.22°00'E., 22.2 ft.
A 18" Cedar bears N.61°00'W., 51.6 ft. (this is cedar set by
Stephens, bearing and distance are to my brass cap)
The Cedar post set by Stephens bears N.29°00'E., 3.1 ft. from by brass cap.
- - - - - 2.24.77

L.E. Monrean
P. Earle; M. Ladig;
K. Cheney
Doug. Co. Surveyors
Office
May 4, 1976
C.S. 59/15

FD OK
BY J. MINOR
11-94 M 121-32

Robert B. Ward Jr.
For: Champion International Corp.
Feb. 24, 1977
M 65 - 4
C.S. 58/139