

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 22 T. S. R 12 R.W.W.M.

FOXE-CHAPMAN CO. EUGENE, ORE. 97401

FDOK BY JOHN MINOR
For: Menasha &
Margaret Coffey
5/94 M20-10

*See Also
Notes in
C.S. 62/85*

Thomas J. Hoesly
For: Menasha Corp.
Dec. 20, 1978
M 74 - 64

Center 1/4 Corner for Section 33. 143
Set - A 5/8" Iron rod
From which:
A 34" Spruce bears N.32°E., 39.9 ft. scribed.
A 6" W.R.C., bears S.25°W., 43.6 ft. scribed.
A 16" Alder, bears N.52°W., 42.6 ft. scribed.
- - - - - 12/20/78

*See Also
Notes in
C.S. 62/85*

Thomas J. Hoesly
For: Menasha Corp.
Dec. 20, 1978
M 74 - 64

South 1/4 Corner for Sec. 33 144
Set - A 1" x 36" I.P. from which
A 30" Fir, bears N.40°E., 19.2 ft. scribed
A 10" W.R.C. Bears S.48°E., 9.5 ft. scribed
A 12" W.R.C. bears S.40°W., 13.3 ft. scribed.
A 20" Fir bears N.73°W., 4.3 ft. scribed.
- - - - - 12/20/78

RE-RENEWED, SEE CORNER NO. #154

Southeast Section corner for Sec. 33. 145
Set - A 2" x 36" Galv. I.P.
From Which:
A 20" Cherry bears N.33°E., 18.4 ft. scribed.
A 70" Hemlock bears S.53°E., 75.4 ft. scribed.
A 34" Hemlock bears S.79°30'W., 38.0 ft. scribed.
A 4" Hemlock bears N.49°30'W., 25.3 ft. blazed.
- - - - - 12/20/78

Ronald E. Stuntzner
For: Elmer & Wanda
Honn
Jan. 4, 1979
M 74-78 A & B
FND (BLM BC.) 8/92
R. DODGE C.S. 63/120

East 1/4 Corner for Sec. 36 of T.22-13 146
Found - Orig. pipe end broken off 10 ft. pipe, staight in ground.
Set - 5/8" Iron rod on west side. See also Ren. #5
Marked "X" on 20" D. Fir, N.5°E., 38.10 ft..
Nailed 1" Diam., round alum. tag in tree base.
Found - Remaining 10 ft. x 3/4" pipe bent and loose S.74°36'10"W.,
8.53 ft.
Recent logging may have caused displaced pipe.
- - - - - 1/4/79

1-79

Larry E. Monrean
K. Reed
S.J. Flause
F. Silagy; V. Woodral
Doug. Co. Surveyors
Office
June 25, 1979
C.S. 60/34

Section corner for Secs. 20, 21, 29 and 28 147
Found - A 48" Spruce now a 60" diam. stump, bears N.70°E., ^{3.3} 33 ft. dist. wit
scribing "12 W S 21" visible. (orig.)
A Hemlock stump, badly rotted bears S.35 1/2°E., 27.3 ft. visible
scribe "S 28". (orig.) (Rec. dist. 29.0 ft.)
A 40" Fir, now a 42" diam. stump bears S.21 1/2°W., 20.5 ft. (Rec.
brg. S. 18 1/2°W. visible scribing. "2 W 29" on 42" stump. (orig)
Set - A 1" x 36" I. Pipe with brass cap marked "Douglas County Surveyor
T22S S20 S21 S29 S28 R12W 1979" at proper position.
New BT's- A 14" D. Fir bears S.62°W., 11.8 ft. dist. scribed "S29 T22S R12W
CS BT" in a double blaze.
A 15" Hemlock scribed "S20 T22S R12W CS BT" in a double blaze
N.37 1/2°W., 16.8 ft..
A 16" D. Fir scribed "T22S R12W S21 CS BT" in a double blaze
bears N.12°E., 27.1 ft.
A 16" Spruce bears S.19°E., 6.1 ft. scribed "T22S R12W S28 CS
BT" in a double blaze.
- - - - - 6/25/79

Douglas Co. Surveyors Office
S. Flause - L. E. Monrean
March 3, 1980
C.S. 61/6

Section corner for Secs. 11, 12, 14 and 13. 148
Found - 3/4" x 34" I. Pipe firmly set and protruding 10" above ground.
Ren. #40
Orig. 24" Hemlock, now a badly rotted 14" DBH 10 ft. tall snag,
N.68°E., 28.4 ft. (Orig. N.70°E., 28.4 ft.), no blaze or scribe
marks found.
Orig. 28" Cedar, now 40" down and somewhat rotted near base,
Good re-ord bearing and distance to site of uproot, (Rec. S.5°E.,
52.14 ft.) no blaze or scribe marks found.
Orig. 36" Fir, now a 40" DBH 6 ft. tall rotted stump S.68°W., 21.3
19.8 ft. face measurement (Rec. S.68°W., 19.8 ft.) evidence of a
double blaze. We open lower blaze and find good BT scribe.
Orig. 50" Fir, now a 56" DBH 7 ft. tall stump, N.79°W., 40.0 ft.
(Rec. N.77°W., 40.9 ft.)

The following 4 trees were marked by Champion International: