

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 22 T. S. R 12 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91891

207

Section Corner for Sections 16, 17, 20 and 21.
 Found - 40" spruce, now 45" stump, 8 ft. high bears S.38°W., 19.5 ft.
 (Rec. S.38°W., 17.8 ft. face meas.) No scribing found.
 36" Spruce, now a 44" stump 5 ft. high bears N.33°W., 20.0 ft.
 (Rec. N.33°W., 18.5 ft. face meas.) No scribing found.
 Set - 1" (s 3/8" O.D.) x 32" pipe with 2 3/8" brass cap marked:
 Douglas County Surveyors

FOOK 3/92
 WILCOX M115-4

T 22 S	
S 17	S 16
S 20	S 21
R 12 W	
1986	

Cap protrudes 4" above mound of sandstone.
 New BTs - 6" Redcedar bears S.20¼°W., 5.9 ft. double blazed and
 scribed "T22S R12W S20 CS BT".
 30" D. fir bears N.56°W., 11.1 ft. double blazed and scribed
 "T22S R12W S17 CS BT".
 12" Redcedar bears S.54¼°E., 27.0 ft. double blazed and scribed
 "T22S R12W S21 CS BT".
 17" hemlock bears N.68°E., 21.4 ft. double blazed and scribed
 "T22S R12W S16 CS BT".

See CS 62/43 for further procedure notes and topog calls.

4/29/86
 208

1/4 Corner for Sections 17 and 20
 Found - Orig. 40" cedar now 46" diam. cedar snag bears N.77°W., 16.5 ft.
 (Rec.) We open and find scribing "1/4".
 Orig. 48" Spruce now tipped out, badly rotted stump bears
 S.70°E., 7.3 ft. (Rec.)
 Set - At record bearing and distance from Orig. 40" cedar, set a
 2 3/8" brass cap on a 1¼" (I.D.) x 32" iron pipe with cap
 stamped: Douglas County Surveyor Office

T 22 S	
1/4 S 17	
S 20	
R 12 W	
1986	

Cap protrudes 9" from ground with mound of stones around cap.
 New BTs - 15" spruce bears N.84¼°W., 16.4 ft. double blazed and scribed
 "1/4 S17 CS BT".
 15" Spruce bears S.19½°W., 26.7 ft. double blazed and scribed
 "1/4 S20 CS BT"
 10" redcedar, pistol butted, bears S.40°E., 28.1 ft. double
 blazed and scribed "1/4 S20 CS BT".

Located on south side of creek.

7/9/86

209

Section Corner for Sections 17, 18, 19 and 20.
 Found - 48" Spruce now 58" stump 7 ft. high with scribing "S 2" bears
 S.11°W., 101.6 ft. (also record).
 24" hemlock, now a 36" badly rotted stump 2 ft. high bears
 N.23½°E., 39.6 ft. (Rec. N.19°E., 39.6 ft.)
 No trace of 24" alder at S.60°E., 6.6 ft.
 Depression at N.59°W., 17.2 ft. possible stump hole of Orig.
 NW alder.
 Set - Corner set at record bearing and distance from the 58" spruce
 stump. This position agreed with record bearing and distance
 to the 36" badly rotted stump whose center could not easily be
 determined. Set 2½" brass cap on 1 3/8" O.D. x 32" pipe.
 Cap marked: Douglas County Surveyors Office

T 22 S	
S 18	S 17
S 19	S 20
R 12 W	
1986	

New BTs - 19" spruce, double blazed and scribed "T22S R12W S20 CS BT" bears
 S.21°E., 19.3 ft.
 24" spruce, double blazed and scribed "T22S R12W S18 CSBT" bears
 N.25½°W., 20.6 ft.
 20" D. fir, double blazed and scribed T22S R12W S19 CS BT" bears
 S.78°W., 32.0 ft.
 28" spruce, double blazed and scribed 'T22S R12W S17 CS BT"
 bears N.10½°E., 22.1 ft.

5/12/86

Douglas County Surveyors Office
 Janet Lundeen
 R. Smith - S. Flause
 April - July 1986
 C..S. 62/43 M 101 - 18