

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T.22    T. S.    R.12    R.W.W.M.

FOX-CHAPMAN CO., EUGENE, ORE. 97401

Harvey Wilcox  
For: I.P. Timberlands  
March 1992  
M 115 - 4

Douglas County Surveyors Office  
Randall Smith, Stephen Flause  
June 1, 1992  
C.S. File 64/26

John Minor  
For: Menasha Corp.  
Nov. 1992  
M 116 - 11

1/4 Corner for Sections 16 and 21. 247  
Set - 3 1/4" alum. cap on 3/4" x 36" alum. rod. Cap is marked "I.P. Timberlands Operating Co. RLS 2244 T.22SR.12W 1/4 S16 S21 1992"  
Cap is set in shallow gulch. # 255  
Fd. BTs - Rotten spruce stump bears S.20°E., 40.9 ft. to face. (orig. tree)  
Rotten spruce stump bears N.15°E., 27.7 ft. to face (orig. tree)  
Mkd BTs - 35" cedar face scribed '1/4 S16 BT' with 'x' and tags bears  
N.01°E., 35.8 ft.  
16" Fir face scribed '1/4 S16 BT' with 'x' and tags brs. N.61°E. 48.3'  
10" Alder bark scribed '1/4 S21 BT' with 'x' and tags brs. S.50°E. 22.3'  
12" Spruce face scribed '1/4 S21 BT' with 'x' and tags brs. S.39°W. 6.2'  
5/11/92

1/4 Corner for Sections 15 and 16. 248  
Fd. - 2 1/2" Brass cap on 2" ODIP (Ward) stamped with LS # 1091. with  
aluminum post alongside. See renewal # 166.  
Fd. BTs - 12" Fir with healed face and tags brs. N.20°E., 10.9 ft. (Ward)  
18" Hemlock with vis. scribe and tags brs. S.46°W., 7.3ft. (Ward)  
Mkd. BTs- 8" Fir face scribed '1/4 S16 BT' with 'x' and tags brs. N.51°W. 3.1'  
10" Fir face scribed '1/4 S15 BT' with 'x' and tags brs. S.60°E. 27.8'  
5/11/92

Center 1/4 Corner for Section 12. 249  
Found - 1" i.d. iron pipe in 5" dia concrete post, flush with ground.  
source unknown. See Renewal 137  
1" i.d. by 16" long rusted iron pipe is found loose in ground along  
south edge of I.P. in concrete, protruding 12" above ground.  
source unknown.  
Accessories Fd. -  
12" now 14" dia 6' high alder stump with a partially healed blaze,  
no scribing visible, bears S.15°E., 27.9 ft. (agrees with rec.  
marked by R.L.S. 399?)  
18" now 24" dia. 1 1/2' high D. fir stump, with a healed lower blaze  
bears S.25°W., 22.0 ft. (agrees with record, marked by RLS 399?)  
New Accessories -  
Northwest corner of two car garage an Catholic Church,  
bears N.58 1/2°E., 72.5 ft.  
Southwest corner of chapel, 0.3 ft. west of double doors,  
bears N.53 1/4°W., 124.2 ft.  
Power pole "AG 043 4" bears N.72°W., 20.0 ft.  
Note - Monument is approx. 100 ft south of Catholic Church.  
B.T. stumps to be removed for cemetery expansion.  
See C.S. file 59/46. and renewal 137. Monument is a survey poent,  
unsure how location derived. 6/4/92

1/4 Corner for sections 19 & 30. 250  
Set - 1"x36" I.P. with 2" brass cap stamped T22SR12W 1/4 S19 | S30 1992  
LS 2052. (Set by proportion)  
New Accessories -  
18" Alder N.77°W., 14.7' bark scribed 1/4 S19 BT  
30" Spruce S83°W., 43.1' scribed 1/4 S30 BT  
19" Alder S.17°E., 35.4' bark scribed 1/4 S30 BT  
29" Spruce N.22°E., 40.3' scribed 1/4 S19 BT  
Note - A creek S.17°E., 28.0' flows S.73°W.  
12/92

Section Corner for sections 19,20,29 & 30. 251  
Found - Down 36" D.Fir snag with orig. scribe visible.  
Set - 1"x36" I.P. with 2" brass cap stamped T22SR12W S19 S20 S29 S30 1992  
LS2052. BCIP set at record S.70°E., 19.8' from face where it  
would have been if it were still standing.  
New Accessories -  
15" Alder N.60°E., 21.3' bark scribed T22S R12WS20 BT.  
30" Spruce S39°W., 26.8' scribed T22SR12W S30 BT.  
31" Spruce S48°E., 56.3' scribed T22SR12W S29 BT.  
18" Alder N.29°W., 5.6' bark scribed T22SR12W S19 BT.  
12/92