

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 13 R.W.W.M.

KOKÉ-CHAPMAN CO., EUGENE, ORE. 21881

18

1/4 Corner for Secs. 13 and 14.

Set - 3/4" x 5 ft. iron pipe.

Steel post with white paddle marked "OREGON STATE PARK BOUNDARY DO NOT DISTURB", 2 ft. east of iron pipe.

A nail with rounded head and a 2" dia. shinner in pavement of road N.71°30'E., 178.17 ft.

A Coast Gurard telegraph pole, S.3°30'E., 189.57 ft. to a PK nail on west side of pole, 4 ft. above ground.

8/26/77

19

Center 1/4 Corner for Sec. 13

Found - 6" x 6" concrete post marked "U.S." on the east side.

52", 8 ft. high Spruce stump, S.5°E., 31.3 ft. scribed "BT" on North side. See Ren. #9

Restoration:

Set steel post with white paddle marked "C 1/4 S 13".

16" Fir S.25°W., 21.75 ft. to a Date nail on East side. 4 ft. above ground.

6" Hemlock, N.28°30'W., 9.07 ft. to a Date nail on East side, 2 ft. above ground.

A iron railroad spike, S.89°30'E., ^{29.0}20.9 ft., in pavement, 8 ft. from West edge of road.

8/26/77

20

1/4 Corner for Secs. 13 and 18 of T22-12

Found -40" Spruce stump 6 ft. high with previously chopped out blaze (Orig. BT). See Ren. #3

34" Spruce stump 4 ft. high S.1°30'E., 54.0 ft. with blaze on North side (Line tree).

Set - 5/8" x 30" Iron rod with a 1 1/2" alum. cap marked "OREGON STATE PARKS", S.50°W., 22.0 ft. from found BT.

Steel post with white paddle marked "E 1/4 S13".

BT's - 14" Spruce S.75°45'W., 8.1 ft. scribed "1/4 S13 T22SR13WBT", tagged with a Parks corner tag.

18" Spruce N.22°30'E., 17.1 ft. svribed "1/4 S18 T22S R12W BT RS 691".

8/26/77

21

East 1/4 Corner for Section 36.

*FND. OK (BLM. B.C.) 8/92 R. DODGE
C.S. 63/20*

Found - Orig. Pipe end broken off 10 ft. pipe, straight in ground.

Set - 5/8" Iron rod on west side.

See also Ren. #7

Marked "X" on 20" D. Fir, N.5°E., 38.10 ft.

Nailed 1" diam. round Alum. tag in tree base.

Found - Remaining 10 ft. x 3/4" Pipe bent and loose, S.74°36'10"W., 8.53 ft. Recent logging may have caused displaced pipe.

FND. OK (Baughman) 5/93 M 117-11 1/4/79

22

Section corner for Secs. 13 and 24; and 18 & 19 of T.22-12

Found - unrecorded 5/8" x 41" I.R., 9" out of the ground, S.18°W., 1.15 ft. from 4" x 4" x 8 ft. white post.

Orig. 30" spruce now 36" rotted stump with possible opened face bears N.15°W., 10.6 ft. A small piece of wood with BLM BT tag was lying on stump. See Ren. #2

Orig. 24" spruce now 46" stump with "S19 T" visible in opened blaze bears S.72°E., 44.9 ft.

All other BTs appear to be completely gone.

Set - At the position of the 5/8" I.R. I set brass cap stamped "Douglas Co. Surveyor T22S R13W S13 S24 S18 S19 R12W 1981" 7" above ground. The 5/8" I.R. was set flush with brass cap along its northerly edge.

New BT's- 19" spruce bears S.54°W., 35.4 ft. (to center of tree trunk) scribed "T22S R13W S24 CS BT" in double blaze.

18" spruce bears N.28°W., 30.4 ft. scribed "T22S R13W S13 CS BT" in double blaze.

24" Spruce bears S.8 1/2°E., 71.4 ft. scribed "T22S R12W S19 CS BT" in double blaze.

Center of door of chlorination plant bears S.67°W., approx. 150 ft.

5/19/81

Oregon State Parks Survey for
Umpqua Lighthouse State Park
John E. Hollingsworth
Witnesses: R. Mills; L. Goge; T. DeSouza; E. Woods
August 26, 1977
M 66 - 64 C.S. 58/152

Ronald E. Stuntzner
For: Elmer & Wanda
Honn
Jan. 4, 1979
M 74-78 A & B

Gregory Quibel
Deputy, Doug.
Co. Surveyors
Office.
Stephen Flause
Terrie Plouff
Karen Mosley
May 19, 1981
C.S. 61/24

RE-RENEWED, SEE CORNER NO. #26

RE-RENEWED, SEE CORNER NO. #28

Jan 78

1-79