

Douglas County Surveyor's Record of
Government Corners Renewed

22

T. S.

13

R. W. W. M.

ROCK-CHAPMAN CO., EURENE, ORE. 97501

032

Douglas County
Surveyors Office
Randall Smith &
Stephen Flause
C.S. 64/63-12
5/31/95

SEC. COR OF 18 & 19 OF T22-12; 13 & 24 OF T22-13

MON. FD. - 2 1/2" dia. DCSO Brass cap on a 1 1/2" Iron pipe, protrudes 4" above ground.

5/8" I.R. protrudes 5" above ground along Northwest edge of BC/IP (source unknown).

4"x4" x 8' high white wooden post, bears N.18°E. 1.15'.

Accessories Fd. - Brg. & dist. taken from a position determined from Org. BT's and a Ren # 90 BT.

30" now 36" dia. 4 1/2' high rotted spruce stump, with a possible blaze no scribing found, bears N.15°W., 10.6' to blaze. Center bears N.15°W., 11.8'.

24" now 46" dia. 7' high rotted spruce stump, with an opened blaze and scribing visible "S" and other illegible marks, bears S.72°E., 44.9' to blaze. Center bears S.72°E., 45.9'.

30" now 26" dia. 4 1/2' high rotted spruce stump, no blazes or scribing found, bears S.62 1/2°W., 32.3' to a position that would fit a possible blaze location. Center bears S.62 1/2°W., 33.5'.

19" now 30" dia. spruce, with a fully healed double blaze, bears S.56 1/2°W., 32.1'.

18" spruce now 24" dia. D.Fir, with a fully healed double blaze, bears, N.24°W., 32.9'.

24" now 34" dia. spruce, with a fully healed double blaze, bears S.9 3/4°E., 68.3'.

Mon. Set - A 2 3/8" dia. DCSO Brass cap on 1 3/8" O.D. by 32" long iron pipe. At a position determined from two remaining original bearing trees and a bearing tree marked by Eppstein in ren. #90. BC/IP protrudes 2" above ground.

1981 DCSO Iron pipe bears N.19 1/4°E., 3.5'.

Corner is S.20°W., 4.7' from 4"x4" x 8' high white wooden post.

New Accessories -

4" dia. Cascara, double blazed and scribed "X BT", bears S.88 1/2°W., 9.7'.

7" dia. Alder bark, double blazed and scribed "T22S R13W S24 CS BT", bears S.31 1/2°W., 18.4'. see ren. #22

033