

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 2188F

Vernon "Ray" Tracy
V. Perron April, 1970
C.S. File No. 54/27

L. E. Monrean, Doug. Co. Surveyor's
P. L. Earle
Oct. 21, 1976
C.S. 59/24

Gary Langlitz
Gregory Quibell
Karen Cheney
Co. Surveyors Office
Oct. 21, 1976
C.S. 59/24

Township Corner: T 23 S R 1 W S 36 | S 30³¹ R 1 E
T 24 S S 1 | S 6

Found - 1922 GLO Brass Cap on 3" I. Pipe, out of ground.
Orig. 14", now 22" Fir, alive, N.60°E. 17.8 ft., shows good scar, tagged.
Orig. 36", now 40" Fir, alive, S.40°E. 39.6 ft., shows good scar, tagged.
Orig. 40", now 46" Fir, alive, S.34½°W. 31.0 ft., shows good scar, tagged.
1922-8" Fir, now 8" Snag, N.2°W. 41.6 ft., (Rec. N8W) scribe visible on
unhealed blaze.

Reset - G. L. O. Brass Cap in proper place.
New BT: 28" D. Fir North 44.5 ft., mkd: "T23S R1W S36 DCS BT".
This corner lies approx. 100 ft. W. of access road from China Creek on
very steep, west slope.

4/15/70

Section Corner to Secs. 33 & 34, T23-1W. and Secs. 3 & 4, T24-1W.
Found - No trace of Corner Stone.
Orig. 30" Fir, now decayed stump, N.38°E. 13.9 ft., with scribe visible.
Orig. 30", now 34" Fir, alive, S.27°E. 62.0 ft., shows good scar, we tag.
Orig. 30", now 34" Fir, alive, S.8°W. 23.1 ft. (Rec. 19.8) good scar, we tag.
Orig. 30", now 35" Fir, alive, N.2°W. 19.8 ft. (Rec. 23.1) opened, scribe vis.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R1W S 33 | S 34
Office, 1970 T24S S 4 | S 3

New BT's: 6" D. Fir N.52°E. 21.4 ft. mkd: "S34 CS BT".
13" D. Fir N.62°W. 22.3 ft. mkd: T23S R1W S33 CSBT

This corner lies on very steep, southerly slope approx. 50 ft. from
S. edge of logging access road.

4/16/70

¼ Corner to Sec. 35, T23-1W. & Sec. 2, T24-1W.
Found - Old Corner Stone, as called for, mkd: "¼".
Orig. 7", now 30" Fir, alive, N.75°E. 20.5 ft, injury over the old scar.
We Rescribe "¼ S35 CSBT".
Orig. 8", now 32" Fir, alive, S.44°W. 16.5 ft., shows good scar.
We Rescribe "¼ S 2 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R1W ¼ S 32 | S 5
(Reset old stone alongside) Office, 1970 T24S S 5

This cor. lies 430 ft. E. of top of spur ridge, sloping S.W. &
approx. 1000 ft. W. of the old Bohemia jeep trail, put tag on jeep trail.

4/17/70

Section corner for Secs. 26, 25, 35 and 36.
Found - 1960 GLO brass cap dislodged & laying under down bearing
tree.
Also found 4 orig. BT's. The trees in the SE and SW quads are
now windfalls.
Renewal - I restamp date on brass cap "1976" and place at corner point.
Orig. 10" now 12" Hemlock bears N.20°E., 9.3 ft. (rec. 10.6 ft.)
Tree has well healed blaze facing away from corner approx. 45°.
Orig. 39" now 42" Fir, bears N.65°W., 23.8 ft. (1960 rec. 23.8,
orig. 25.7 ft.) Tree has well healed blaze.
New BT's - An 8" Hemlock, bears S.6 1/2°W., 28.1 ft. Tree blazed and
scribed "S35 CS BT".
A 10" Hemlock, bears S.62 1/2°E., 35.5 ft. Tree double blazed
and scribed "T23S R1W S36 CS BT".
Set - Yew post, squared approx. 2", 5 ft. long, 1 foot in the ground.
Mound stones around base of post. Post bears East, 3 ft.

10/21/76

Section corner for Secs. 35 and 36; and 2 & 1 of T24-1
Found - An orig. 15" now 28" Fir, bears N.58°E., 29.1 ft. Down with
illegible scribe marks in blaze opened by someone prior to this.
An orig. 14" now 34" Fir, bears S.76E., 19.8 ft. (rec. S.81°E., 19.8)
Alive with well healed blaze.
An orig. 13" now 22" Fir, bears N.18°W., 17.8 ft. Alive with well
healed blaze.
We find no sign of corner post.
Set - A 1" x 30" I. Pipe with brass cap attached flush with ground marked:
Douglas Co. Surveyor T 23 S
1976 S 35 | S 36 R 1 W
S 2 | S 1
T 24 S

CONT. NEXT PAGE