

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 2 W. R. W. W. M.

KORR-CHAPMAN CO., EUGENE, ORE. 21881

Weyerhaeuser Co.  
John E. Wilson, Log. Eng.  
October 1964  
C. S. File No. 51/306

Section Corner common to Secs. 32 & 33, T23-2W. & Secs. 4 & 5, T24-2W.  
GLO Survey Record 1894: Basalt Stone 15" x 12" x 5", gone.  
60" Fir N.16 $\frac{1}{2}$ °E. 37 lks., now 60" Fir, bark scribing visible.  
36" Fir S.31 $\frac{1}{2}$ °E. 89 lks., healed faces not chopped open.  
36" Fir, now snag, S.52°W. 35 lks., healed faces not open.  
48" Fir N.19°W. 40 lks., scribing on bark.  
Ref. by Marion Hale (Plates & "W" Nails only) Dec. 20°  
60" Fir N.13°E. 21.5 ft. - 32" Fir S.54°W. 23.6 ft.  
26" Fir S.88°E. 45.4 ft. - 36" Fir N.84° W. 39.5 ft.

$\frac{1}{4}$  Corner common to Sections 32 and 33.  
Found - GLO Record, 1894 - Stone 16" x 10" x 6", gone.  
26" Fir, now 30", S.48°E. 159 lks., opened upper face & found scribing.  
36" Fir, now down 40", S.10°W. 148 lks., 2 healed faces visible.  
Ref. by Glen McChesney (plates & "W" nails only) Decl. 20°  
Set - 1" alum. Pipe and Mound of Stone.  
30" Fir S.48°E. 104.9 ft.  
34" Fir S. 02° E. 119.0 ft.

S. W. Corner of Section 31.  
Found - 16" Cedar N.9°30'E. 27.72 ft., O. K. (Orig. Cedar BT)  
60" Fir S. 57° E. 22.9 ft., now 66" Fir Stump  
No trace of 9" Alder S.35°W. 3.96 ft.  
Pipe  $\frac{5}{8}$ " x 2.8, for Corner  
Pipe 1" x 4' marker.  
BT's: - 66" Fir Stump S.58°E. 22.9 ft. (Orig. BT.) "W" Nail & Plate  
26" Hemlock S.50°W. 18.1 ft. "W" Nail & Plate.

May 1963

$\frac{1}{4}$  Corner to Sec. 32, T23-2W. & Sec. 5, T24-2W.  
Found - 30" Fir S.60°E. 17.82 ft., now 33" Fir Stump, chopped out. (Orig. BT)  
No trace of 5" Vine Maple N.47°E. 10.56 ft.  
Set -  $\frac{5}{8}$ " x 30" Monel Pipe with a 2" x 19.6 ft. Black Iron Pipe  
set 17 ft NE. 3 ft. in the ground.  
BT's: - 42" Fir Stump N.24°E. 28.8 ft., "W" Nail & Plate.  
33" Fir Stump S.60°E. 17.8 ft., "W" Nail & Plate. (Orig. BT)

$\frac{1}{4}$  Corner to Sections 31 and 32.  
Found - 50" Fir S.85°W. 31 lks., face evident, not chopped out, #37  
Doug. Co. Plate, Cruiser's Mark.  
16" Fir N. 2°E. 16 lks., tree rotted off level with ground, found  
scribing on fragments left at stump.  
Set - Vine Maple Stake, Sept. 18, 1957 (Now  $\frac{1}{2}$ " Monel Pipe at cor.)  
BT's: - 54" Orig. Fir BT. N.81°W. 20.1 ft., "W" Nail & Plate.  
46" Fir S.25°E. 22.4 ft., "W" Nail & Plate.  
Found O.K. July 29 V.R.T.

S. E. Corner to Section 31. - Secs. 31 & 32-T23-2W & Secs. 6 & 5, T24-2W.  
Found - 15" x 12" x 5" Basalt Stone, gone. A deep logging skid road  
at point for corner.

1953 survey record:  
36" Fir N.17°W. 19.9 ft., now stump, plate gone, bark gone.  
(Orig. bark scribe present)  
38" Fir S.77°W. 18.1 ft., now stump, no writing on plate  
32" Fir East 26.9 ft., now stump, plate gone.  
30" Fir, now stump, S.45°E. 40.8 ft., no writing on plate.  
Assessor's Added, 1958 - "W" Nails & Plates to all four Fir stumps,  
as shown above.

MICROFILM TO HERE J 10/67

Weyerhaeuser Co.  
1958 & 1963  
C. S. File No. 53/106

RE-RENEWED CORNER NO. 9

RE-RENEWED CORNER NO. 37