

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
July, 1969  
C.S. File No. 54/27

12

$\frac{1}{4}$  Corner to Sections 27 and 28.  
Found - Unrecorded 2" Steel Pipe at corner point.  
Orig. 8", now 16" Hemlock, chopped stump, S.82°E. 5.9 ft.,  
shows scribe. Open lower & find "BT" scribe.  
No trace of other Orig. BT.  
DO NOT SET BRASS CAP.  
New BT's: 22" Hemlock N.70°E. 17.1 ft. mkd: " $\frac{1}{4}$ " S27 DCS BT.  
15" Hemlock S.31°W. 34.6 ft. mkd: " $\frac{1}{4}$ " S28 DCS BT.  
This corner lies on top of N.W.-SE ridge on Lane-Douglas County Line.

13

$\frac{1}{4}$  Corner to Section 36, T23-2W and Sec. 1, T24-2W.  
Found - Stone 20"x12"x7" mkd. " $\frac{1}{4}$ ", tipped out.  
Orig. 12", now 13" Hemlock, alive, N.64°W. 6.6 ft., scribe visible  
on nearly healed blaze. Rescribed " $\frac{1}{4}$ " S36 CS BT".  
Orig. 10", now 11" Hemlock, alive, S.6°W. 16.5 ft., scribe visible on  
previously opened blaze. Rescribed " $\frac{1}{4}$ " S 1 CS BT".  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R2W  $\frac{1}{4}$  S 36  
(Reset Old Corner Stone alongs) Office, 1969 T 24 S S 1  
This corner lies 15 ft. south & 30 ft. east of small creek, flowing SW.  
7/3/69

14

Section Corner to Secs. 35 & 36, T23-2W. and Secs. 1 & 2, T24-2W.  
Found - Orig. 18", now 20" Fir Snag, N.53°E. 13.9 ft., open scribe visible  
Orig. 30", now 40" Fir, alive, S.29°E. 37.6 ft. (Record S.49°E),  
shows good scar.  
Orig. 48", now 58" Fir, alive, S.25°W. 21.1 ft., shows good scar.  
Orig. 30", now 38" Fir, alive, N.28°W. 19.1 ft., shows good scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R2W S 35 | S 36  
Office, 1969 T24S S 2 | S 1  
New BT: 52" D. Fir N. 33° E. 74.4 ft. mkd. "T23S R2W S36 CS BT".  
No smaller trees available. This corner lies on moderate SW.  
slope in old growth timber. 7/8/69

15

$\frac{1}{4}$  Corner to Sections 27 and 34.  
Found - 1 $\frac{1}{2}$ " Aluminum Pipe (unrecorded) at corner & probable corner stone.  
Orig. 36", now 38" Fir, alive, N.47°W. 14.5 ft., shows good scar.  
Orig. 36", now 37" Fir Snag, 20' high, S.35°E. 9.2 ft., we open &  
find " $\frac{1}{4}$ " S" scribe.  
No marks found on corner stone.  
DO NOT SET BRASS CAP.  
New BT's: 10" Hemlock N.42°E. 42.3 ft. mkd: " $\frac{1}{4}$ " S27 CS BT". (This BT lies  
on south bank of creek)  
18" Hemlock S.89°W. 36.1 ft. mkd: " $\frac{1}{4}$ " S34 CS BT".  
This corner lies on steep north slope 50 ft. S. of creek 3 ft. wide.

16

$\frac{1}{4}$  Corner to Sections 26 and 35.  
Found - Orig. Corner Stone, in place & mkd: " $\frac{1}{4}$ ".  
Orig. 36", now 38" Fir, alive, N.42°E. 21.8 ft., shows good scar.  
Orig. 6", now 7" Hemlock Snag, S.45°E. 13.9 ft. open & shows scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 2 W  
Office, 1969  $\frac{1}{4}$  S 26  
S 35  
New BT's: 7" Hemlock N.49°E. 23.0 ft. mkd: " $\frac{1}{4}$ " S26 CS BT".  
11" Hemlock S.39°E. 21.1 ft. mkd: " $\frac{1}{4}$ " S35 CS BT".  
This corner lies on westerly slope about 60 ft. W. of Creek, 4 ft. wide.

17

$\frac{1}{4}$  Corner to Sections 25 and 26.  
Found - Do not find Corner Stone.  
Orig. 40", now 48" Fir, alive, N.63°E. 15.3 ft., shows good scar.  
Orig. 40", now 40" Fir Snag, S.75°W. 13.2 ft., scribe visible on unhealed  
blazes, tree badly decayed.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 2 W  
Office, 1969  $\frac{1}{4}$  S 26 | S 25  
New BT's: 12" Hemlock N.42°E. 19.6 ft. mkd: " $\frac{1}{4}$ " S25 DCS BT".  
12" Hemlock S.40°W. 49.6 ft. mkd: " $\frac{1}{4}$ " S36 DCS BT".  
This corner lies on very steep N.W. slope in Rhododendron Brush.