

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21991

Section Corner to Sections 25 - 26 - 35 - 36. 18
Found - Orig. 50" Fir, now 56" Stump, N.28°E. 9.9 ft., shows scar.
Orig. 20" Cedar, now 22" Snag, S.70°E. 37.6 ft., scribe visible.
Orig. 40" Fir, now 50" shattered stump, S.26°W. 13.2 ft.
No trace of N. W. 4" Hemlock BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 2 W
Office S 26 | S 25
1969 S 35 | S 36

New BT's: 10" Hemlock S.61°W. 29.5 ft. mkd: "T23S R2W S35 CS BT".
18" Hemlock S. 9°E. 38.4 ft. mkd: "T23SR2W S36 CS BT".
8" Hemlock N.16°W. 92.2 ft. mkd: "T23S R2W S26 CS BT".

No tree available in section 25 due to logging.

FD. OK 3/13/79 K. REED - Co. SURV. OFF. - C.S. 60/24 19

$\frac{1}{4}$ Corner to Sec. 33, T23-2W. and Sec. 4, T24-2W.
Found - 12x10x6" Basalt Stone mkd. " $\frac{1}{4}$ " and unrecorded Monel Pipe, bent over.
Orig. 40", now 50" Fir, turned out & 20 ft. downhill, N.50°E. 21.1 ft.,
open and scribe visible.

Orig. 40", now 48" Fir, alive, S.15°E. 17.8 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R2W $\frac{1}{4}$ S 33
Office, 1969 T24S S 4

New BT: 48" D. Fir N.68°W. 24.5 ft. mkd: " $\frac{1}{4}$ S33 C S BT".
No smaller trees available.

Reset Corner Stone & Monel Pipe alongside Brass Cap.
This corner lies on very steep N.W. slope.

$\frac{1}{4}$ Corner to Sections 25 and 36. 20
Found - No trace of corner stone called for.
Orig. 36", now 40" Fir Snag, N.74°E. 31.0 ft., open & find scribe.
Orig. 12", now 24" Cedar, alive, S.60°E. 12.5 ft., shows good scars.
Rescribed: " $\frac{1}{4}$ S36 CS BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 2 W
Office $\frac{1}{4}$ S 25
1969 S 36

New BT: 18" Hemlock N.59°E. 38.1 ft. mkd: " $\frac{1}{4}$ S25 CS BT".
This corner lies at bottom of nearly verticle Rock Bluff 50' high N.E.

$\frac{1}{4}$ Corner to Section 35, T23-2 and Sec. 2, T24-2W. 21
Found - Orig. BT's. as mkd. by Chandler in 1894, resurvey, as follows:
30", now 48" Fir, alive, S.68°E. 35.0 ft., shows good scars.
9", now 14" Fir, alive, N.69°W. 9.9 ft., Open & find scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R2W $\frac{1}{4}$ S 35
Office, 1969 T24S S 2

New BT's: 20" R. Fir N.18°W. 24.2 ft. mkd: " $\frac{1}{4}$ S35 CS BT".
10" R. Fir S.52°E. 36.6 ft. mkd: " $\frac{1}{4}$ S 2 CS BT".

$\frac{1}{4}$ Corner to Sections 33 and 34. 22
Found - Orig. 12", now 30" Hemlock, alive, S.36°E. 21.8 ft., scribe visible
by looking into hole. We Rescribe " $\frac{1}{4}$ S34 CS BT".
Orig. 36", now 46" Fir, alive, N.72°W. 25.1 ft., shows very good
scars.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 2 W
Office, 1969 $\frac{1}{4}$ S 33 | S 34

New BT: 15" Hemlock S.20°W. 46.3 ft. mkd: " $\frac{1}{4}$ S33 CS BT".
This corner lies on very steep westerly slope in old growth timber
and vine maple brush.

$\frac{1}{4}$ Corner to Sections 29 and 30. 23
Found - Orig. 15", now 30" Hemlock, alive, N.57 $\frac{1}{2}$ °E. 21.8 ft., scribe
visible on open blaze. We Rescribe " $\frac{1}{4}$ S29 DCS BT".
No trace of other Orig. BT.

Set - Brass Cap at Cor. Mkd: Doug. Co. Surveyor's T23S R2W
Office, 1969 $\frac{1}{4}$ S 29 | S 30

New BT: 3" Hemlock N.65°W. 44.2 ft. mkd: " $\frac{1}{4}$ S30 DCS BT".
This corner is on E - W Lane - Douglas County Line and on very steep
westerly slope 40 ft. west of 15' high bluff.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
July 1969 ; C. S. File No. 54/27

RE-DEVELOPED, SEE CORNER NO. #41

WRONG LOCATION
RESET BRASS CAP
SEE PEN. #31