

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 23 S. T. S. R. 2 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

(cont.)

Orig. 24", now 28" Fir, alive, N. 46 $\frac{1}{2}$ °W. 25.1 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R2W S 34 | S 35
Office, 1969 T24S S 3 | S 2
New BT: 34" D. Fir N. 66° E. 28.0 ft. mkd: T23S R2W S35 CS BT.
This corner lies on very steep, southerly slope in dense rhododendron-
vinemaple and old growth fir.

7/29/69

Section Corner to Section 27 - 28 - 33 - 34.

30

Found - No trace of Corner Stone.

Orig. 30", now 36" Cedar, Alive, N. 70°W. 15.2 ft., blaze open,
possible fragmentary scribe marks.
Orig. 30", now 36" Hemlock, was S.E., now in creek to N.W. of corner.
scribe visible on open blaze.
Orig. 30", now 32" Cedar, down, N. 20°E. 48.2 ft., scribe visible on
open blaze on under side.

No trace of Orig. S.W. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 2 W
Office S 28 | S 27
1970 S 33 | S 34

New BT's: 48" D. Fir N. 4°E. 57.4 ft. mkd: "T23S R2W S27 CS BT".
10" Hemlock N. 83°E. 40.7 ft. mkd: "T23S R2W S27 CS BT".
10" Hemlock S. 78°E. 51.3 ft. mkd: "T23S R2W S34 CS BT".
Orig. 36" Cedar N. 70°W. 15.2 ft., Rescribe "T23S R2W S28 CS BT".
No tree close in Section 33, Creek 6.0 ft. wide bears
North 17.0 ft., course N.W.

5/19/70

31

$\frac{1}{4}$ Corner to Sections 29 and 30.

Found - 1969 County Surveyor Brass Cap set in wrong position,
See Ren. #23.

15", now 30" Hemlock, S. 57 $\frac{1}{2}$ °E. 21.8 ft., scribe still
visible in hole on S.W. side of Tree.

Reset Brass Cap in proper position from Orig. B.T.

Hemlock BT., from Ren. #23, now destroyed by recent logging.

No trees available, we scribe "W" reference stump, as follows:

28" D. Fir Stump S. 82°W. 37.9 ft., to "W" nail mkd: " $\frac{1}{4}$ S30 DCS BT".

Orig. BT. 30" Hemlock S. 57 $\frac{1}{2}$ °E. 21.8 ft. (21.0 ft.) to "W" nail,
our rescribe on S.W. side O.K. " $\frac{1}{4}$ S29 DCS BT".

Ren. #23. should be disrgarded. also, Orig. BT., uncovered by
recent logging, down & out of position.

10/16/70

MARCH 71

1/4 Corner for Secs. 26 and 25.

Found - Stone, 12" x 8" x 6", badly chipped but probable marks.
40" now 48" x 6 ft. Fir stub bears N. 63°E., 5.3 ft. broken
blowdown, healed over faces still intact.
40" Fir now 40" x 20' Fir snag bears S. 77°W. (rec. S. 75°W.)
12.6 ft. to center, scribing visible.

1969 Douglas Co. Brass cap. Ren. #17

12" now 14" Hemlock, bears N. 42°E., 19.6 ft. to center with
Douglas Co. BT tag.

12" Hemlock bears S. 39°W., (Rec. S. 40°W.) 49.3 ft. to center
(rec. 49.6 ft.) scribed with Douglas Co. BT tag.

Note - A Georgia Pacific survey Sept. 1962 (Lane County Print No. 12714
shows the 2 orig. BT's distances reversed. Their set 1 1/2" I.P.
not found.

New BT's - 42" Fir bears S. 68°E., 6.3 ft. with "W" nail and plate.
58" Fir stump bears S. 23°W., 23.1 ft. with "W" nail and plate.

6/4/76

33

Section corner for Secs. 33 and 34; and Secs. 4 & 3 of T24-2

Found - 1969 Doug. Co. Surveyors brass cap properly marked. Ren. # 28

36" Fir, now 52" bears S. 27°E., 43.0 ft. (Rec. S. 25°E., 46.2 ft.)
Tree has been chopped out visible scribing "T2 S R2W S3 T".

Orig, a root hole with down Fir bears N. 66°W., 36.3 ft. dist. Tree
badly rotted.

Orig., an 18" Hemlock, now down bears N. 11°E., 5.3 ft. dist.

Left Cap in Place.

New BT - A 21" Hemlock scribed T24S R2W S4 CS BT" bears S. 84°W., 51.5 ft.

Corner located at lower center of large rootwad.

Vernon "Ray" Tracy
Vincent Perron
C. S. File No. 54/27

Frank O. William
by Glen McChesney,
For: Weyerhaeuser Co
June 4, 1976
C.S. 58/8

aren Reed
S.J. Flause
Woodral
Doug. Co. Surveyors
Office
July 10, 1979
C.S. 60/34

3-77

Jan 78
1-79