

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

44

$\frac{1}{4}$  Corner to Sections 34 and 35.  
Found - 12" Fir, Mkd.  $\frac{1}{4}$  S on W. face, O. K., not chopped out.  
10" Yew, now 24", S.80°W. 9.9 ft., O.K., scribing weathered off.  
12" Fir, now 16" Fir Snag 30' high, N.30°E. 2.6 ft., scribing  
 $\frac{1}{4}$  on bark.  
1941 Record - Brass Plate on 20" Yew S.80°W. 9.9 ft. BT., plate O.K.  
Brass Plate 16" Fir N.30°E. 2.6 ft. BT., plate O.K.  
BT's: - 60" Fir N.51°E. 52.4 ft. "W" Nail & Plate.  
60" Fir S.86°W. 42.9 ft. "W" " "

Feb. 1958

Sec. Cor. to Sections 26 - 27 - 34 - 35.  
Found - No evidence of 6" Maple N.20°E. 54 lks. - SEE REN #39  
8" Cedar S.60°E. 30 lks, now 16", slow growing, some scribing leg.  
33" Cedar S.85°W. 6 lks., still standing, face evident,  
scribing rotted off.  
36" Cedar N.40°W. 4 lks., still standing, face evident, Scrib. gone.  
Set - 2" x 2" Yew Post, (short)  
BT's: - 24" Cedar S.5°W. 16.0 ft. "W" Nail & Plate.  
26" Cedar N.72 $\frac{1}{2}$ °W. 28.1 ft. "W" " "  
48" Cedar(Orig. BT) N.50°W. 2.9 ft. "W" Nail & Plate.  
46" Cedar(Orig. BT) S.63°W. 3.4 ft. "W" " "

March 1957

$\frac{1}{4}$  Corner to Sections 35 and 36.  
Found - 30" Fir S.40°E. 25 lks., scribed on bark, mostly legible,  
face bears N.70°W.  
24" Fir W. 30 lks, 26" Fir, no scribing visible.  
Set -  $\frac{3}{4}$ " x 30" Monel Pipe.  
48" Fir. Orig. BT., S.70°E. 16.3 ft., "W" Nail & Plate added.  
Fir, possible Orig. BT. N.70°W. 23.7 ft., no marks.  
BT's: - 54" Fir N.88°W. 40.7 ft. Orig. BT. "W" Nail & Plate added.  
(Nov. 1967 - Now logged off, BT's. now stumps & 5' high marker pipe  
C.S. File No. 54/16) alongside corner.)

East  $\frac{1}{4}$  Corner to Section 36.  
Found - Double Fir, N. 8 lks., scribing "BT" barely visible on bark.  
"X" on E. & W. side. No cruiser mark, one name.  
6" Fir S.10°E. 80 lks., axe marks evident, no scribing found.  
Set - Cedar Stake,  $\frac{1}{2}$ " x 2" x 3', Sept. 1957.  
Dbl. Fir, Orig. BT., North 5.1 ft.  
46" Fir, Orig. BT. S.4°W. 41.4 ft.  
BT's: - 70" Double Fir, SE Section - Snag(Orig. BT) N. 4.4 ft. "W" Nail & Plate.  
52" Incense Cedar S.75°E. 39.7 ft. "W" Nail & Plate.

$\frac{1}{4}$  Corner to Sections 27 and 34.  
Found - Post gone, at intersection of E-W & N-S cutting line blazes.  
found 1914-16 blazes, cruiser mark "W" on piece fir bark knocked  
off of 50" Fir Stump, also BLM plate on this piece of bark  
marked S45°W. 29 ft. on slope to S  $\frac{1}{4}$  Cor. Sec. 27-23S-3W.  
Cruiser Mark "LF" on down 14" Maple.  
24" Fir S.45°E. 25 lks., 36" Fir Stump S.47 $\frac{1}{2}$ °E. 1515 ft., fits close to  
evidence, no axe or scribing found,, probably rubbed off.  
36" Fir N.45°E. 4 lks., gone, cat road at this position.  
BT's: - 36" Fir Stump(assumed Orig. BT) S.47 $\frac{1}{2}$ °E. 15.5 ft. "W" Nail & Plate.  
50" Fir Stump N.57 $\frac{1}{2}$ °E. 25.0 ft., "W" Nail & Plate.

Found O.K. Oct. 67 V.R.T. S.S. 54/16 March 1957

Section Corner to Secs. 6 & 7, T23-3W. & Secs. 1 & 12, T23-4W.  
Found - 2"x2" Sq. Post & Orig. 8", now 60" Fir N.32°W. 31.0 ft., shows bark scribe.  
Orig. 20", now 24" Cedar S.28°E. 26.4 ft., down & out of position.  
Orig. 8", now 20" Cedar S.35°W. 35.0 ft., down, find reverse scribe  
No trace N. E. BT. Doug. (prev. remvd. from BT.)  
Set - Brass Cap at Cor. Mkd: CountySurv. T23S R4W S 1 | S 6 R3W  
Office, 1965 S 12 | S 7  
New BT's: 12" D. Fir S.9°W. 10.2 ft. Mkd: T23S R4W S12 DCS BT.  
9" D. Fir S.60°E. 60.0 ft. Mkd: T23S R3W S7 DCS BT.  
16" D. Fir N.28°E. 23.3 ft. Mkd: T23S R3W S6 DCS BT.  
No trees close to N. W. This corner on Land-Doug. Co. Line.

Meyerhaeuser Co.  
1957 thru - 1963  
C. S. File No. 53/107

VERNON R. TRACY  
M. Stone - 11/3/65  
C.S. File 54/16