

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner to Sections 28 and 33.

Found - Old Iron Bar set by Thiel, (see G. Langdon's affidavit in C. S. File No. 53/9) alongside Haines' "T" Iron. 42" D. Fir bears N.15°E. 33.0 ft. renewal scribing visible on badly charred face "S", also fragments of other scribe marks - This Orig. N.E. BT. (see affidavit) #156

No trace of S. E. BT.

Rescribe - 42" D. Fir N.15°E. 33.0 ft. "1/4 S28 CS BT".

No other trees near.

Corner lies in fence corner, fences N., S., and West from corner.

78

Corner to Sections 33 and 34 only.

Found - Haines' "T" Iron & Cap at corner. ^{-Ren. #38} 7" Hemlock N.25°W. 5.5 ft., alive & standing, good condition. N. E. BT. is now down.

New BT: 10" Hemlock N.39°E. 48.0 ft. Mkd: T23S R4W S34 CS BT.

79

Closing Corner Sections 4 and 3, T24-4W.

Found - Brass Cap set by Co. Surveyor in 1959. Orig. SW. BT. - 40" D. Fir S.1°W. 18.5 ft. alive & standing. 6" Cedar S.43°W. 34.5 ft. in good condition. Orig. S.E. BT., now uprooted & down.

New BT: 11" Red Cedar S.69°E. 63.8 ft. Mkd: T24S R4W CC S 3 CS BT.

80

1/4 Corner to Section 34 only. N. Bdry. Sec. 3, T24-4W.

Found - 32" Fir S.42°W. 42.2 ft., has been previously opened, good scribing "1/4 S" visible on old face. Old Fir Stump N. 5°W. 11.9 ft., small portion of old face exposed, good scribing, portion of "4" visible.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W S1/4 S 34 only Office, 1963 T24S R4W

New BT's: 32" Red Cedar N.81°E. 21.0 ft. Mkd: 1/4 S34 CS BT.

24" Hemlock N.77°W. 53.3 ft. Mkd: 1/4 S34 CS BT.

Corner lies in dry draw draining S. W.

81

1/4 Corner to Sec. 19, R4W. & Sec. 24, R5W.

Found - 1 1/4" Iron Pipe, & Uprooted & partly rotted Fir N.20°W. 26.4 ft., Cut open & found good scribing "1/4". Laurel Sprouts, with rotten Laurel Log lying on ground, S.35°E. 6.6 ft. Did not look for scribing in Laurel

DID NOT SET BRASS CAP - Iron Pipe in good condition.

New BT's: 8" D. Fir S.60°W. 13.3 ft. Mkd: 1/4 S24 CS BT.

9" Yew Tree N.12°E. 85.4 ft. Mkd: 1/4 S19 CS BT.

82

Section Corner to Secs. 18 & 19, R4W & Secs. 13 & 24, R5W.

Found - Iron Pipe set in 1954, bent over, broken & buried in ground. 24" W. Fir S.75 1/2°W. 20.4 ft. scribing still visible in partly covered scar. ^{-Ren. #23}

40" D. Fir N.60 1/2°W. 46.2 ft., good bark scribing visible.

Metal disc marked "RE 2741" nailed to tree.

No trace of other bearing trees found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R5W S13 | S18 R4W Office, 1963 S24 | S19

New BT's: 33" D. Fir S.7 1/2°E. 199.3 ft. Mkd: T23S R4W S19 CS BT.

22" I. Cedar N.61°E. 223.6 ft. Mkd: T23S R4W S18 CS BT.

Corner is in fence corner, fences North - South and West.

83

FD 1195
M121-69

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
March and April 1963
C. S. File No. 53/9

SEE THEM'S BOOK 5 Pg 1
RE-OPENED CORNER NO.

RE-OPENED CORNER NO.

111