

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23.S. T.S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

84

Corner to Section 3 and 2 only, T24-4W. - S. Line T23-4W.
Found - The Fir Tree S.47°W. 43.7 ft. is now broken off approximately
25 feet above ground. See Renewal No. 65.
New BT's: 24" D.Fir S.52°W. 92.2 ft. Mkd: T24S R4W S3 CS BT.
Found - Co.Surv. Brass Cap set in 1962, in good condition.

85

Section Corner to Secs. 35 & 36, T23-4W. & Secs. 2 & 1, T24-4W.
Found - G.L.O. Brass Cap in Mound of Rocks. 1957 Survey. ^{FD 3-93 BY PEEL MIT-5}
26" Fir S.28°W. 48.2 ft., shows good scars. Alive & In good condtn.
7" W.Fir N.46°E. 31.0 ft. Alive & good condition. Scars.
45" Cedar N.83°W. 38.9 ft. Has dead top & appears to be dying.
14" Cedar S.48½°E. 49.5 ft. is broken off approx. 15 ft. abv. ground.
Ching. Stump to the N.E. is still in existence.
Fir Snag to the S. E. still stands, old scribing visible.
New BT's: 7" W. Fir S.11°E. 17.8 ft. Mkd: T24S R4W S1 CS BT.
8" Red Cedar N.32½°W. 43.8 ft. Mkd: T23S R4W S3 5 CS BT.

86

¼ Corner to Sec. 35, T23-4W. & Sec. 2, T24-4W.
Found - 48" Dead Fir Snag, S.82°W. 18.5 ft. Cut open & found good
scribing "B" on old face.
No trace of Rock set for Corner nor of N.E. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W ¼ S35
Office, 1963 T24S S 2
Corner lies in bottom of small draw at foot of a very steep
S. E. slope. Area surrounding corner has all been badly burned.
No live trees near corner.
Rescribe(in wood) 48" Fir Snag S.82°W. 18.5 ft. Mkd: ¼ S 2 CS BT.
New BT: 18" D.Fir West 166.5 ft. Mkd: ¼ S34 S 2 CS BT.
No other live trees near.

87

S. W. Corner Sec. 31, T23-3W. S31
Found - Brass Cap set by Price in mound of rocks. 30" Fir Stump, sawed high,
N.21°E. 176.6 ft. All scribing visible. 82" Fir Stump N.63¾°E.
169.6 ft., scribing visible "31 BT".
2 Fir Snags mentioned by Price:
22" Fir Stump S.57¾°W. 24.4 ft., charred face.
50" Fir Snag N.30°W. 59.4 ft., axe scar on bark (charred).
New BT's: 28" D.Fir S.59°W. 55.1 ft. Mkd: T23S R3W S31 CS BT.
7" Ching. N.54°E. 35.8 ft. Mkd: T23S R3W S31 CS BT.
No more suitable trees available to N. E.

July 15, 1963

88

Closing Corner to Sec. 36, T23-4W. & Sec. 1, T24-4W. CC S36 | S31
Found - Brass Cap set by Price in 1950. S 1
9" Cedar Snag N.32¾°W. 66.7 ft. All scribing visible.
36" Sawed Fir Stump S.77¾°W. 120.1 ft. All scribing visible.
New BT's: 6" Hemlock N.61°W. 27.4 ft. Mkd: T23SR4W S 36 CC CS BT.
6" D.Fir S.23°W. 29.2 ft. Mkd: T24S R4W S 1 CC CS BT.
July 15, 1963

FD OK
MIT-5
BY PEEL
3-93

89

Section Corner to Sections 13-14-23-24.
Found - Mound of Stone at Corner.
Cedar BT. (Orig.) N.77°W. 42 lks. down.
No other trees near old enough for Orig. BT's. # 198
Set - 1" x 36" T Iron in Mound of Stone.
New BT's: 24" Fir N.12°E. 37.6 ft. 12" Fir N.72½°W. 8.4 ft.
20" Fir S.58°W. 63.0 ft. 24" Fir S.21°E. 27.9 ft.

REPEL

Milo E. Godfrey, Deputy
Vernon Tracy and Mike Stone
June 1963
C. S. File No. 53/9

Wilford N.
Haines.
June 1963
C. S. 51/247