

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

FD
3-93 B/Peel
4/17-5

30
 $\frac{1}{4}$ Corner to Sec. 36, T23-4W. & Sec. 1, T24-4W.
 Found - 26" Hemlock Stump, dead several years, N.30°E. 9.9 ft.,
 scribing visible in partially opened scar $\frac{1}{4}$ ".
 No trace of S. E. BT., location falls in old cat road.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W $\frac{1}{4}$ S36
 Office, 1963 T24S R4W S1
 New BT's: 11" Yew N.29°E. 6.5 ft. Mkd: $\frac{1}{4}$ S36 CS BT.
 24" Red Cedar S.63°W. 36.3 ft. Mkd: $\frac{1}{4}$ S1 CS BT.
 July 12, 1963

Milo E.
Godfrey &
Crew
C. S. File
No. 53/9

RE-RENEWED SECTION CORNER NO. 117-31
 $\frac{1}{4}$ Section Corner to Sections 7 and 12.
 Found - Northeast Bearing Tree, badly burned.
 Set - 1" x 1" x 36" T. Iron.

32
 Center $\frac{1}{4}$ Corner to Section 7.
 Set - 1" x 1" x 36" T. Iron and
 Scribed - 8" D. Fir S.40°W. 39.4 ft.
 12" D. Fir S.80° E. 74.2 ft.
 Fd. OK 10/19/99 C.S. 6/2/63

33
 Center $\frac{1}{4}$ Corner to Section 8.
 Set - 1" x 1" x 36" T. IRON and
 Scribed - 14" Fir S.04°W. 36.4 ft.

34
 $\frac{1}{4}$ Section Corner to Sections 8 and 17.
 Set - 1" x 1" x 36" T. Iron and
 Scribed - 28" Fir S.32°E. 24.3 ft.
 16" Cedar N.34°W. 22.9 ft.

35
 $\frac{1}{4}$ Corner to Sections 1 and 12.
 Found - Old Square Stake.
 Stump Hole of BT. (now windfall) S. 8°E. 64 lks.
 3 windfalls N.E. but could not determine if one was BT.
 Set - 1" x 1" x 36" T. Iron from which a:
 12" D. Fir with a "W" Spike bears S.16°09'W. 34.1 ft.

36
 $\frac{1}{4}$ Corner to Sec. 12, T23-4W. & Sec. 7, T23-3W.
 Set - 1" x 1" x 36" T. Iron by Prop. Measurement.
 Scribed - 5" D. Fir S.31°E. 6.3 feet.
 6" D. Fir N.15°W. 6.4 feet.

37
 Center $\frac{1}{4}$ Corner of Section 12.
 Set - 1" x 1" x 36" T. Iron.
 Scribed - 14" D. Fir N.66°W. 17.3 feet.
 5" W. Fir N.32°E. 8.2 feet.
 RE-RENEWED SECTION CORNER NO. #167

38
 Sec. Cor. to Secs. 13 & 24, T23-4W. & Secs. 18 & 19, R3W.
 Found - 6" Vine Maple (1882), alive & in fair condition considering
 the number of inscribed cruisers marks. Scribe on
 bark mostly visible.
 48" Fir S.50°E. 12 lks. 7.9 ft., bearing should read N.50°E,
 Now 50" Fir, scribing visible on bark.
 5" Vine Maple S.50°W. 19.8 ft., gone
 6" Vine Maple N.10°W. 16.5 ft., found rotted on ground.
 30" Fir N.65°E. 21.8 ft. (bearing should read S.65°E.), now
 Stump, found some scribing.
 New BT's: 48" Fir S.88°E. 37.2 ft., "W" Nails & Plate
 50" Fir N.48°E. 8.0 ft. " " " (Orig. BT)
 54" Fir N.66°W. 25.9 ft. " " "
 17" Hemlock S.34°W. 32.7 ft. " " "

Wilford N. Haines
For Woolley & Whipple Mill
August 1963
Map File M 26 - 38

Wilford N. Haines
For Woolley, Whipple &
Weyerhaeuser Co.
Nov. 1963
Map File M 26 - 80

Marion D. Hale, Weyerhaeuser
March 14, 1957
Lane County Records
C. S. File No. 53/1

RE-RENEWED SECTION CORNER NO. 139