

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

122

$\frac{1}{4}$ Corner to Sections 11 and 12.
Found - Haines' "T" iron & BT's., as recorded in Ren. #59.
10" Cedar, alive & in good condition, N.40°W. 15.2 ft. Mkd:
" $\frac{1}{4}$ S 11 BT" and Haines' button.
12" Maple, badly injured by fln snag; S. 28° E. 13.7 ft.,
Mkd: " $\frac{1}{4}$ S 12 BT" & Haines' button;
8", now 20" W. Fir N. 38° W. 24.4 ft., down & pushed out of place.
New BT: 11" I. Cedar S. 85 $\frac{1}{2}$ ° E. 61.4 ft. Mkd: $\frac{1}{4}$ S12 CS BT.
Note - This corner lies approximately 100 ft. S. of new access road
and 30 feet N. of creek, course S. W.

123

$\frac{1}{4}$ Corner to Sections 2 and 1.
Found - Haines' "T" Iron & BT's., as recorded in Ren. #58, as follows:
8" Fir N. 7° W. 23.1 ft., dead, scribe visible.
16" I. Cedar N. 64° E. 27.9 ft., 15 ft. Snag, scribe visible.
New BT's: 10" I. Cedar S. 73° W. 7.3 ft. Mkd: $\frac{1}{4}$ S 2 CS BT.
8" I. Cedar N. 69° W. 34.2 ft. Mkd: $\frac{1}{4}$ S2 CS BT.
(As no trees were available in Sec. 1, marked both
trees in Section 2)
Corner lies on West edge of cat. fire trail.

$\frac{1}{4}$ Corner to Sections 1 and 12.
Found - Haines' "T" Iron & BT. as recorded in Ren. #95.
12" D. Fir S. 21° W. 34.1 ft., not scribed, "W" nail at base.
Haines' calls bear. S.16°09'W. We re-scribe this tree,
" $\frac{1}{4}$ S12 CS BT".
New BT: 14" Red Cedar N. 86° E. 70.0 ft. Mkd: $\frac{1}{4}$ S1 CS BT.
Note - This corner lies in small patch of reproduction of D. Fir,
approximately 250.0 ft. S. of edge of big timber.

124

*SEE C.S. 5818
way on Haines' Tract
(1925) Rec'd
6/1/91*

Section Corner to Sections 1 - 2 - 11 - 12.
Found - BT's. as recorded in Ren. #44, as follows:
32" D. Fir S. 69° E. 15.1 ft. to face. Shows scars, alive.
22" D. Fir, alive, S. 50° W. 41.5 ft., to face. shows scars, "W" nail.
36" D. Fir, alive, N. 79° W. 8.7 ft., to face, shows scars, "W" nail.
(Wire fence attached to North side.
N. E. BT. now shattered stump.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W S 2 | S 1
Office, 1965 S 11 | S 12
New BT: 21" R. Cedar N. 55° E. 175 ft. (center) Mkd: T23S R4W S1 CS BT.
Note - This corner lies 2.0 ft. S. of fence, bearing S. 78° E.

125

$\frac{1}{4}$ Corner to Sections 11 and 14.
Found - Haines' "T" Iron & $\frac{3}{4}$ " Iron Pipe, as recorded in Ren. #62.
26" Fir S. 25° W. 26.4 ft., healed scar, alive.
New BT: 6" D. Fir N. 83° W. 11.0 ft. Mkd: $\frac{1}{4}$ S11 CS BT.
Note - This corner lies at fence corner approximately 150 ft.
North of small creek.

126

*FWD OK 6/91
D. PEEL M 113-42
FWD OK 1/197
Roberts M127-75*

$\frac{1}{4}$ Corner to Sections 12 and 13.
Found - Haines' "T" Iron - 1 $\frac{1}{2}$ " I. Pipe & BT's., as recorded Ren. #61.
20", now 28" I. Cedar N. 23° W. 47.4 ft., alive, scribe visible.
26", now 28" Fir S. 11 $\frac{1}{4}$ ° E. 62.1 ft., dead, struck by lightning.
New BT: 8" D. Fir S. 62° W. 38.5 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
Note - This corner lies approximately 30 ft. west of small, marshy
creek, course N. W.

127

FWD OK 12/99 Roberts M127-80

Sec. Cor. to Secs. 1 & 12, T23-4W. & Secs. 6 & 7, T23-3W.
Found - 2"x2" sq. post & BT's. as follows:
Orig. 8" (?), now 60" Fir N. 32° W. 31.0 ft., shows old fragmentary
bark scribe.
Orig. 20", now 24" Cedar S. 28° E. 26.4 ft., down & out of place.
Orig. 8", now 20" Cedar S. 35° W. 35.0 ft., down, find rev. scribe
previously removed from BT. No trace of N. E. BT.

128

(continued over)

Vernon "Ray" Tracy
Mike Stone and Jerry Layne
November 1965
C. S. File No. 54/16