

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

(continued) - Sec. Cor.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W S 1 | S 6 R3W
Office, 1965 S 12 | S 7

New BT's: 12" D.Fir S. 9° W. 10.2 ft. Mkd: T23S R4W S12 DCS BT.
9" D.Fir S. 60° E. 60.0 ft. Mkd: T23S R3W S 7 DCS BT.
16" D.Fir N. 28° E. 23.3 ft. Mkd: T23S R3W S6 DCS BT.
No tree close to N. W.

Note - This corner on Douglas - Lane County Line.

129

1/4 Corner to Sections 27 and 34.

Found - Haines' "T" Iron, as recorded in Ren. No. 41.
All Bearing Trees down and dead.

New BT's: 18" D.Fir N. 3° W. 27.9 ft. Mkd: 1/4 S27 CS BT.
18" Maple S. 29° W. 34.3 ft. Mkd: 1/4 S34 CS BT.

Note - This corner lies on rolling North slope, changing to very steep.

1/4 Corner to Sections 33 and 34.

Found - Bearing Trees recorded in Ren. #47.

Haines' "T" Iron pushed out & Cedar Stump used for Orig. BT. also gone.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965

T23S R4W S 33/S 34

New BT's: 5" now 7" W. Fir S. 40 1/2° E. 79.5 ft., healed blaze. Do not open.
7" now 11" R. Cedar N. 72 1/2° W. 126.0 ft., scribe visible on partially healed blaze.

Note - This corner lies on east edge of road, course N. & S. curving to southwest.

RE-REMOVED

130 #164

Vernon "RAY" Tracy
Mike Stone and J. Layne
November 1965
C. S. File No. 54/16

131

1/4 Corner to Sections 27 and 28.

Found - Orig. 6", now 14" Fir S. 63° W. 31.7 ft., now snag, leaning badly. We fell and open. Find reverse & fragmentary scribe on upper face & axe notch at base of lower face. Ring count approx. 90 years before BT. died.

Orig. 8", now 20" Fir S. 89° E. 31.0 ft., dead, down, badly rotted. No scribe found.

Haines' "T" Iron bears S. 65° W. 29.7 ft. at Fence Corner.

Set Brass Cap Mkd: County Surveyor's Office, 1965

T23S R4W S 28/S 27

New BT's: 33" D.Fir (Dbl. Tree) N. 56° E. 5.2 ft. Mkd: 1/4 S27 CS BT.
15" D.Fir S. 42° W. 9.4 ft. Mkd: 1/4 S28 CS BT.

Note - This corner lies in edge of old growth timber to East. Cut off to West.

132

1/4 Corner to Sections 13 and 24.

Found - Orig 14", now 24" Fir Snag N. 55° E. 15.8 ft., upper face gone. Open lower scar & find "BT" scribe.

S.W. BT. now hole in ground with rotting wood lying around.

Weyerhaeuser BT, now stump & turned out, See C.S. 53/108.

36" D.Fir N. 4° W. 13.0 ft. shows 1/4 S13 BT 363" Bark Scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's 1/4 S 13 T23S R4W
Office, 1965 S 24

New BT's: 21" D.Fir S. 51° E. 51.9 ft. Mkd: 1/4 S24 CS BT.

30" D.Fir N. 21° E. 27.8 ft. Mkd: 1/4 S13 CS BT.

133

Sec. Corner to Sections 10 - 11 - 14 - 15.

Found - Haines' "T" Iron on S. edge of road flush with ground, Ren. #64.

Orig. 10", now 28" W.Oak N. 2° E. 44.9 ft., prev. opened, now healed.

Stump Hole N. 75° W. 29.0 ft.

22" W.Oak N. 88° W. 12.5 ft., mkd: S11 T23S R4W BT & Haines' Button.

(Deep crack through middle of face)

36" W.Oak S. 84° E. 93.6 ft., scribe partially visible on mostly healed face. BT. is 3 forked.

New BT: 14" forked W. Oak N. 77° E. 82.5 ft. mkd: T23S R4W S11 CS BT.
(marked on S. Fork)