

Douglas County Surveyor's Record of  
Government Corners Renewed

23 T. S. 4 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21891

151

1/4 Corner of Sec. 6 and 7

Ren. #28

Found Two iron bars supported in a mound of rock, Located in an old E-W fence.

From which: An 18" now 24" D Fir marked in 1957 by the county surveyor bears S 35°E., 29.8 ft., alive and in good condition.

We find no evidence of any other corner accessories. We Do not set a new monument due to very shallow soil.

We mark the following new bearing tree:

An 11" D. Fir bears N55°E., 26.6 ft., Scribed "1/4 S6 CS BT" on a double blaze. Compass Declination: 20° East

Gary L Langlitz  
Clell E Goodwin  
M. Lenora Ladig  
C.S 57/34  
7/10/75

152

South 1/16, Sections 7 and 8

Found - 1 x 1 x 36" T - Iron set by Haines 1963. See M 26 - 38

An 18" Fir, bears N.62°W., 6.6 ft. Tree has double blaze healed over. I open lower blaze and find scribing "BT".  
SE BT not found.

Set - Brass cap at 1/16 corner stamped: County Surveyors Office 1976  
T 23 S R 4 W  
S 1/16 S7 S8

Set "T" iron beside brass cap.

New BT - 23" D. Fir, bears N.34 1/2°E., 13.5 ft. Tree double blazed and scribed "S 1/16 S8 CS BT".

2/19/76

L.E. Monrean  
J.H. Cook  
Surveyors Office  
Feb. 19, 1976  
C.S. 59/8

Section Corner for Secs. 6, 5, 7 and 8.

FD. OK 8/92 BY NESS  
C.S. 63/144

153

Found - A 1" x 1" x 36" T Iron set by Haines. Ren. #45

A R. Cedar, 21", with previously opened blazes but no visible scribing. It bears S.11°E., 12.0 ft. and is tagged with location poster.

Found no trace of orig. bearing trees.

Set - A 1" x 30" Pipe with brass cap stamped "Douglas Co. Surveyor"  
T 23 S R 4 W  
S 6 S 5  
S 7 S 8  
1976

Replaced "T" iron directly next to brass cap.

New BT's - A 17" Cedar bears N.40°E., 17.0 ft. mkd. "T23S R4W S5 CS BT" in a double blaze.

A 23" Cedar bears N.72°W., 11.0 ft. mkd. "T23S R4W S6 CS BT" in a double blaze.

A 6" Fir bears S.85°W., 67.5 ft. mkd. "T23S R4W S7 CS BT" in a double blaze.

A 7" Cedar bears S.6 1/2°E., 36.0 ft. mkd. "T23S R4W S8 CS BT" in a double blaze.

8/23/76

A. Victor Cangie, Surveyors Office  
Jim Cook  
C.S. 59/18  
Aug. 23, 1976

pd. ok  
10/17/79  
C.S. 62/63

154

1/4 Cor. for Secs. 19 and 30.

Found- 1 1/2" steel shaft, 9" above ground mkd. " " on top. No record.

A 28" D. Fir, bears S.88°W., 16.4 ft. scribing "1/4" visible on badly burned face. Not orig. tree.

A badly burned & hollow Yew stump, no markings, bears approx. bearing and distance for orig. NW BT.

We have no record of any renewal for this corner. A yellow tag on the Fir has the name "L.J. Martin" dated "10-22-54".  
Did not renew corner.

(SEE ALSO THEIL'S NOTES)  
(C.S. 52/115) (ADDED TO RECORDS)  
5/17/63 (3/21/1984 Z.R.)

Milo Godfrey  
V.T. & M.S.  
Co. Surveyor's  
Office  
May 17, 1963  
C.S. 53/9

Section Corner for Secs. 1, 2, 11 and 12.

See Renewals #16, 44, 125

155

Found - A 1"x30" BC and stone. No identifiable marks on stone. Cap is stamped 1965, Douglas County Surveyors Office

From which:

A 32" now 35" D. Fir, bears S.69°E., 15.1 ft. to face, alive & shows scar.

a 22" now 35" D. Fir, bears S.50°W., 41.5 ft. to face, alive & shows

A 36" Fir stump bears N.79°W., 8.7 ft. to face, shows good scar.

A 21" now 26" R. Cedar, bears N.55°E., 175.0 ft. to center. Tree is healthy and shows good scar.

New BT's - A 21" D. Fir, bears N.26 1/2°W., 78.5 ft. to center & mkd. "T23S R4W S2 CS BT" in a double blaze.

Note: Corner lies 2.0 ft. south of fence bearing S.78°E.,. We also stamp "CS 1976" on found brass cap.

11/17/76

A. Victor Cangie  
Mike Tompkins  
Doug. Co. Surveyors  
Nov. 17, 1976  
C.S. 56/26  
scar.

3/77