

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 23 T. S. R 4 R.W.W.M.

KONE-CHAPMAN CO., EUGENE, ORE. 21881

164

Larry E. Monrean
Karen Reed - F.C. Silagy
Doug. Co. Surveyors Office
Sept. 13, 1979
C.S. 61/6

Stephen John Flause
K. Mosely - D. Prado
D. Atterbury
Doug. Co. Surveyors Off. Sept. 13, 1979
Jan. 10, 1980
C.S. 61/6

1/4 Corner for Secs. 33 and 34
(9/13/79)

*FD DC50
BC 7/91
M 110-38
FD 1195
M 121-69*

- Found - A 1" x 36" I.P. with brass cap marked "County Surveyors Office T23S 1/4 S33 S34 R4W 1965. Ren. #130. Cap is located below ground surface.
A buried BLM brass cap bearing S.45°W., approx 3 ft. marked "1/4" S33 S34 T23S R4W 1976.
Haines "T" iron (1960, Ren. #47) not found.
A 7" Cedar now 18" bears N.73 1/2°W., 126.4 ft. (Rec. N.72 1/2°W., 126.6 ft.) with well healed blaze. Ren. #47
A 5" now 10" Fir bears S.41°E., 79.5 ft. (Rec. S.40 1/2°E.) with rotted blaze 2 feet high and well healed blazes above and below rotted blaze. Ren. #47.

Note: These bearings and distances measured from county cap. Corner lies in East edge of road course N-S curving to SW. NOTE: BLM office to remove BLM cap.
(1/10/80)

- Found - A filled in hole with scraps of flagging at S.35°W., approx. 3 ft. distant. We find NO BLM cap.
Find accessories as noted above.

New Accessories:

- A 24" D. Fir, bears N.6 1/2°E., 113.5 ft. with a double blaze marked 1/4 S34 CS BT.
- A 16" D. Fir bears S.75°W., 142.9 ft. with a double blaze marked 1/4 S33 CS BT.

L.E. Monrean, Doug. County Surveyors Office
Karen Reed - Stephen Flause, Deputy
Terrie Plouff, M. Shawn Means, Teresa Buley
December 18, 1979
C.S. 60/34

Section corner for Secs. 7 and 18; and 12 & 13 of T.23-5

165

- Found - A 3/4" Iron rod, protruding 10" above ground. Ren. #22
An orig. 8" Redwood now a 22" diam., 2 ft. stump, bears S.84°W., 12.5 ft.
An orig. 12" Fir, now a 32" diam., stump bears N.65°W., 27.1 ft. I chop out scar to find visible scribed "S12".
An orig. 12" Fir, now a 26" stump, bears N.20°E., 16.5 ft.
An orig. 12" Fir, now tipped out bears S.69°E., 25.1 ft.
A 12" R. Fir, now a 12" diam., 35 ft. high snag, bears N.44°E., 27.7 ft. with visible scribe "23S R4W S7 CS BT" in an unhealed double blaze. Ren. #36
An 11" Cedar, now a 12" diam., 10 ft. high snag, bears N.78 1/2°W., 32.7 ft. with visible scribe "T23S R5W S12 CS BT" in an unhealed double blaze. Ren. #36
(The two BT's from Ren. #36 were rec. as scribed "1/4 S7 CS BT and 1/4 S12 CS BT").
A 7" W. Fir, now 13" with healed over double blaze bears N.33°W., 42.3 ft. Ren. #109
A 7" W. Fir now 15" with healed over double blaze bears S.24°W., 50.3 ft. (Rec. 51.2 ft.) Ren. #109
An 8" Fir, now 12" with well healed double blaze bears S.21°E., 101.6 ft. (Rec. S.22°E., 102.5 ft.) Ren. #109

Set - 1" x 36" R.P. with brass cap marked "Douglas County Surveyor" with 3/4" I.R. inside pipe. At
same position as rod.

	T 23 S		
R	S 12	S 7	R
5	S 13	S 18	4
W	1979		W

New BT - A 7" D. Fir scribed "T23S R4W S7 CS BT" in a double blaze bears N.71 1/2°E., 117.0 ft. dist.

Located at fence corner. Fence S and E.

12/18/79

166

1/4 Corner for Section 4; and Sec.33 of T.22-4

*FDOK
Les Roberts
6/96
See Ren. #48
M 125-29*

- Found - A 1" iron rod
A 31" Fir snag, "1/4S_ visible N.18°08'W., 39.3 ft. (orig. BT, N.18°W., 39.6 ft.)
44" Fir windfall, S.3°W., 50.4 ft. approx.
Haines T iron South 0.1 ft.

- New BT's- 8" W. Fir scribed "BT" at base N.30°W., 15.3 ft.
8" W. Fir S.34°37'E., 18.7 ft. scribed "BT" at base

5/12/80

Robert Dean
For: Don Jackson
May 12, 1980
M 83 - 37
C.S. 58/204 (N)