

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 T. S. R 4 R.W.W.M.

KONE-CHAPMAN CO., EUGENE, ORE. 97501

187

CONT FROM PREV. PG. - - 8" D. fir bears S.55°W., 32.87 ft. to alum. nail breast height
I scribe 1/4 S35 BT, drive 6" spike in face, and tag tree.
Corner lies on a steep West facing side slope 1/2 chain West of bottom of
rock bluff and 2.0 chains below top of rock bluff as described in orig.
notes. A loose 3/4" iron pipe 1/2 ft. in ground with no accessories bears
S74°E., 42.1 ft. Access to corner is 300 ft. South of end of landing on
logging spur road.

Ken Hoffine
For: Lone Rock
Timber Co.
Jan. 1990
M 109-56
C.S. 63/106

188

Center 1/4 Corner for Section 26
Set - 5/8" x 36" iron rod with alum. cap 0.5 ft. above ground and
mark the following accessories:
8" hemlock bears N.11°E., 47.8 ft. to alum. nail in mid-base
I scribe C 1/4 S 26 BT, drive 6" spike in face and tag tree
26" D. fir bears N.50°W., 19.2 ft. to head of 6" spike. I
drive in face. I scribe C 1/4 S 26 BT and tag tree.
32" D. fir stump bears S.39°W., 20.6 ft. to head of 6" spike
in chopped face. I also tag stump.
16" WRC stump bears South 11.1 ft. to head of 6" spike. I
drive in face. I scribe C 1/4 S 26 BT and tag.
Corner lies on 20% east facing slope approx. 500 ft. east of gravel road
with timber to NW quadrant only.

James A. Branch
For: U.S. National
Bank
Sept. 1990
M 110-58
C.S. 63/104

Center 1/4 Corner for Section 33
CORNER REPORT ONLY
Found - Steel fence post (no record)
20" (11") Fir bears N.83°E., 8.3 ft. (not of rec. in DCSO)
9" fir bears S.615W., 8.2 ft. tree is now standing but
is dead. (not of record in DCSO)

189

1/4 Corner for Sections 15 and 22
CORNER REPORT ONLY
Found - Corner is a 3" BLM brass cap 0.2 ft. above ground in good
condition. (1976)
10" D. Fir bears N.45°E., 16.4 ft. well healed face and BT tag.
5" D.F. bears S.70°E., 27.5 ft. well healed face and BT tag.
49" D.F. bears N.5°E., 13.0 ft. with old heavy axe work, and very
old faded BLM BT tag. No record
I painted faces and wrote BT on tree trunks of BTs with flourescent
orange paint. Corner lies on 30% north slope approx. 20.0 ft. east of
fence.

Ken Hoffine
L.S. #2291
For: Lone Rock
Timber Co.
Gary Angiolet,
Witness
June, 1990
C.S. 63/104

6/90

1/4 Corner for Sections 21 and 22
Found - Corner is a brass cap set by Shaner. Cap in good condition.
19" D.F. bears N.58°W., 52.6ft. well healed face and BT tag.
Renewal #149
P.P. & L. power pole #38050 bears S.73°E., 32.8 ft. Ren. #181
P.P. & L. power pole #28043 bears S.66°E., 49.6 ft. Ren. #181

191

New Accessories:
Put up Lone Rock Timber location tag on 8" D.F. bearing
West 4.2 ft.
Painted face and wore BT on tree trunk of BT with flourescent orange paint.
Corner lies on Northwest edge of power utility R/W next to a piece of
broken metal electric insulator approx. 30 ft. south of east-west fence
line.

FD OK 10/27/94 1995-0005 6/90