

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 4 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97501

198

Corner for Sections 13, 14, 23 & 24. CONDITION REPORT ONLY.

Found - BLM Brass cap flush to the ground.
22" D.Fir stump with tin cap bears S.58°W., 63.1 ft. bark
has been removed, no visible face. See renewal # 89.
12" D.Fir stump with tin cap bears N.72½°W., 8.5 ft. bark
has been removed, no face or tag visible.
25" D.Fir stump with tin cap bears S.21°E., 28.0 ft. bark
has been removed, visible scribing, no tag.
21" D.Fir stump with tin cap bears N.12°E., 37.9 ft. bark
has been removed except for the face which has bark
scribing.
2" D.Fir bears N.63°W., 5.8 ft. no scribing, we tagged.

Note - Corner lies in young reprod with mature stand 150 ft. to the south.

1/4 Corner for Sections 13 & 24. CONDITION REPORT ONLY.

199

Found - County Surveyor's Brass cap 0.5 ft. above ground.
32" D.Fir 3 ft. stump bears N.3°06'W., 14.2 ft. (rec.
N.4°W., 14.4 ft.) bark has been removed, chemical treated,
tin cap. See Renewal # 177.
23" D.Fir 6 ft. stump bears N.20°48'E., 27.3 ft. bark has
been removed, chemical treated, tin cap, scribing is
visible.
17" D.Fir 20 ft. tall snag bears N.55°25'E., 16.6 ft. (rec.
N.57°E., 16.4 ft.) chopped out face, scribing visible.
24" D.Fir 4 ft. stump that has been tipped over bears
S.28°43'E., 9.5 ft.
14" Hemlock northeast stem of schoolmarm bears S.21°32'W.,
7.5 ft. (rec.S.24°W., 7.57 ft.) well healed scar.

Note - Corner lies on a gentle westerly slope with young reprod to east and young timber to the west.

END OF 1199, Roberts M127-75

Corner for Sections 28, 29, 32 & 33.

200

Found - Douglas County Brass cap dated 1963. See Ren. # 77.
32" W.Oak, N.9°E., 90.1 ft. - uprooted remains.
record: N.9°E., 90.0 ft. - 1932 Douglas County.
56" Cedar, S.28°E., 240.2 ft.
record: S.28°E., 240.7 ft. - 1932 Douglas County.
19" Ash, S.28°W., 18.0 ft. - closed face.
record: S.28°W., 18.3 ft. - 1963 Douglas County.
18" Fir, S.54°E., 91.6 ft. to "W" nail.
Set - 8" Ash, N.6°W. 16.4 ft. to "W" nail. mkd. "T23S R4W S29 BT"

201

South 1/4 Corner for Section 33 only.

Found - 3¼" U.S.B.L.M. Brass cap dated 1976
24" Fir, N.5°W., 49.5 ft.
record: N.5½°W., 75 lks. - 1976 BLM
23" Maple, S.89°E., 47.0 ft. - closed face - record unknown.

202

Center 1/4 Corner for Section 33.

Set - 2" x 32" iron pipe with 2½" Brass cap marked: "T23S R4W C¼
S33 PLS 1978 1994"
18" Fir, N.87°E., 7.0 ft. to "W" nail -scribed "C¼ S33 BT"
25" Fir, S.14°E., 29.0 ft. to "W" nail -scribed "C¼ S33 BT"
18" Fir, S.83½°W., 12.6 ft. to "W" nail -scribed "C¼ S33 BT"
18" Fir, N.19°W., 22.0 ft. to "W" nail -scribed "C¼ S33 BT"
Found - Metal fence post bears S.73½°E., 3.8 ft. from set corner.
record: 1977 BLM Administrative survey center ¼ monument.
BTs to metal fence post: See renewal #189
record: 20" Fir, N.83°E., 8.3 ft. - 1977 BLM
record: 9" Fir, S.61°W., 8.2 ft. - 1977 BLM, now dead

Ken Hoffine
For: Juniper Properties Ltd.
August 1994
M120-66

Daniel Baker
For: Weyerhaeuser Co.
Sept. 1994
M119-38