

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 5 R. W. W. M.

2/9/16
J. W. Cole
Deputy
H. W. Wilson
Joe Wilson
John Wilson
J. S. Gills
John Wise

c.s. 16/55
Aug. 1940

Ben B. Irving
N. E. Richardson
Loren Weber
Witnesses
V16 E55

9-17-1940

Ben B. Irving
Witnesses
N. E. Richardson
Loren Weber
V16 E55

8-22-1940

Ben B. Irving, County Surveyor
Witnesses
N. E. Richardson
Milo Godfrey
March 28, 1946

SEE ALSO THESE BOOKS #24

Surveyor
Ben B. Irving
Witnesses
Richardson
Daugherty
Carl Johnson
Jan. 20-22, 1940

RE-NEWED CORNER NO. #21
N.W. COR. OF W. WILSON, D.L.C. NO. 45
Renew corner from stumps of original witness trees. Set a
5" x 8" x 12" concrete block 2 ft. in the ground. from which
A Fir 18" diam., bears S.20°W. 46 lks.
A Fir 18" in dia., bears S.48°E. 59 lks.

STANDARD 1/4 SEC. COR. ON NORTH BOUNDARY OF SEC. 1.
Location identified from both original bearing trees. A
28" Black Oak, S.46°E. 100 lks. which I chopped out and
found original scribe marks legible and a 54" Black Oak,
S. 31°E. 65 lks. Drove an iron pipe 1" x 48" x 48" 44" 59
in the ground for corner, from which
A Black Oak 24" in diam., bears S.40°E. 83.2 ft.
marked 1/8 S. 1. C.9. B.T.
A Black Oak 19" in diam., bears S.39°W. 6.9 ft.
marked 1/8 S. 1. C.3. B.T.

RE-NEWED CORNER NO. 96
N.E. CORNER OF LINDSEY APPELATE D.L.C. NO. 42 92.4'
Location identified from original P.T. S.31°W. 96.4 ft.
rotted out, but scribe marks still visible. Original corner
rock lying along side field fence. An Oak S.50°E. 55.3 ft.
bearing scribe marks dead & fallen, reputedly marked by O.P.
Thiel about 30 years ago.
Reset original stone 6" x 8" x 12" 12" under ground and drove a
1" pipe along side. from which 86.5' F.O.K. 10/69 V.R.T. C.S. 54/16
A Oak 28" diam. bears S.50°E. 88.5 ft.

RE-NEWED CORNER NO. 43
SEC. COR. 25-26-35-36
Location identified from part of original P.T. & stump holes
of remainder all which check original field notes
A Fir 14" diam., bears N. 63°E. 66.5 ft. dist. 43
A Fir 12" diam., bears N.63°E. 61.7 ft. dist.
Laurel 14" diam., bears S.56°E. 60.0 ft. dist.
Fir 28" diam., bears S.46°W. 107.7 ft. dist.

RE-NEWED CORNER NO. 42
COR. BETWEEN 34-35
Location identified from testimony of Albert Cockeran, who saw
scribe marks on fir N.26°E. 102 lks. This tree is down and
has been removed. A scribe in fence line check for 42
located on a tree with property lines.
Drove a 1" x 54" iron pipe 48" in ground for corner, from which
Fir 30" diam., bears S.87°W. 120 ft.
Fir 12" diam., bears S.71°E. 59.0 ft.

S. E. CORNER of G. A. BURT D.L.C. # 40.
Location identified from an Original B.T. Oak now 40"
dia. N.45°E. 105 lks. This tree was not chopped out but
scars for upper and lower blazes were plain. Location of
corner fitted old fence line as called for in deed for
East boundary of D. L. C. # 40, center line of county road
which is located along the South boundary of D.L.C. 40
and certain deed descriptions adjoining the S.P.R.R.
Drove a 3/4" x 48" pipe 6" below the surface of the
county road.
Marked new B.T.
Black Oak 30" dia. bears N.86°W. 131.0 ft. marked
S.W. corner of D.L.C. 40, C.S.B.T.

1/4 Sec Cor. between 23-26 Same as Corner #28
Found scribed marks on OBT, a dead Alder bearing N 31° E
22 lks., when chopped out.
Set an Iron Pipe 1" x 48", 46 " in the ground with a
4 x 4 x 60 inch Cedar Post alongside. Scribed 1/4 S 23,
1/4 S 26, from which #28
A Fir 14 ins. diam. bears N 21° W 46.8 ft. dist. mkd.
1/4 S 23 C S B T.
A Fir 20 ins. diam. bears S 22 1/2° E 64.1 ft. dist. mkd.
1/4 S 26 C S B T.