

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

Corner to Sections 5 & 4 only.

Found - Orig. 18", now 38" Fir Stump, previously opened shows good scribing "5".

S.W. BT. gone.

Angle Iron Set by Haines. *see M103 - Ren #31*

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

T22S R5W

S 5/8 S 4 T23S

New BT's: 12" R. Fir bears S.45°E. 89.4 ft. scribed S4 T23S R5W CS BT.

8" R. Fir bears S.19°W. 14.0 ft. scribed S5T23S R5W CS BT.

Note - Corner is at West edge of old Log Road.

54

#100

C.
S.
F
I
L
E
49/42

1/4 Corner to Sections 6 & 7.

Corner Found 1" Iron Pipe 3x3 Post 36 1/2 S

Nemlock 10" S.46°E. 25.9 ft. Mkd: R3 1/2 S BT.

Fir 10" N.21°E. 67.1 ft. 1/4 S B.T.

Sept. 1952

55

Chas. C.
Hayden.
For Reese Lbr.
C.S. File
No. 41/65

1/4 Section Corner to Sections 28 and 29.

Found - Orig. 14", now 40" W. Oak N.30°W. 27.1 ft. I open & find good scribing "1/2 S".

No trace of Orig. N.E. BT. found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

1/4 S29/S28 T23S R5W

Note - Corner in old N. S. Fence Line.

New BT's: Rescribed Orig., now 40", W. Oak N.30°W. 27.7 ft.,

1/4 S29 CS BT.

8" W. Oak bears S.82 1/2°E. 164.0 ft. Scribed 1/4 S28 CS BT.

56

Fd. ok 5/89
D. Benitz
M103-14

1/4 Section Corner to Sections 22 and 23.

Found - Dead rotten Oak Snag, now 42", S.80°E. 52.8 ft., Chopped open & found fragmentary scribing, unreadable but unmistakable.

Bl. Oak, alive & standing) N.53 1/2°W. 427.7 ft., instead of 425.7 ft. Did not open this tree.

At Corner Set Iron Pipe with Brass Cap Mkd. "County Surveyor's Office, 1960, T23S R5W 1/4 S22/S23".

Blaze & Scribe New BT's:

17" D. Fir S.83°E. 24.3 ft. Mkd: "1/4 S23 CS BT."

16" W. Oak S.40 1/2°W. 56.6 ft. Mkd: "1/4 S22 CS BT."

57

10/69 - Fd. O.K.
VRT - C.S. 54/16

James W. Byron, Deputy County Surveyor
Milo Godfrey
Clethe Putnam
January, 1960
C. S. File No. 49/42

Section Corner to Sections 14, 15, 22, & 23.

Found - Orig. 20", now 48" B. Oak S.27 1/2°E. 248.8 ft. I open & find good scribing.

Orig. N.W. & N.E. BT's., now Stump Holes only.

No trace of Orig. S.W. BT. found.

Find 8" x 6" x 12" Stone at Corner which is under N.S. Fence.

Set Brass Cap alongside Corner Stone & Mark, County Surveyor's Office, 1960.

SL5 | SL4
S22 | S23 T23S R5W

10/69 - Fd. O.K.
VRT C.S. 54/16

New BT's: 24" B. Oak bears N.76°E. 33.7 ft. scribed SL4 T23SR5W CS BT.

15" Laurel bears S.26°E. 25.0 ft. scribed S23 T23S R5W CS BT.

27" B. Oak bears S.51°W. 82.5 ft. scribed S22 T23S R5W CS BT.

12" B. Oak bears N.34°W. 84.2 ft. scribed SL5 T23S R5W CS BT.

58

North 1/4 Corner to Section 1 only.

Found - Orig. 28", now 40" B. Oak S.36°W. 36.3 ft. Shows good scars.

Orig. 18" S.46 1/2°E. 66.0 ft. B. Oak. Previously opened. shows good scribing "S1".

Also find 12" B. Oak bears S.39°W. 6.9 ft. shows scribing,

(See BBI renewal, 1940) *Ren #2*

Find 1/4" x 1 1/2" Strap Iron at Corner which is under N.S. Fence.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960,

North 1/4 S1 T23S R5W.

New BT's: 6" R. Fir bears S.15°W. 14.4 ft. scribed N 1/4 S1 CS BT.

1" R. Fir bears S.60°E. 36.7 ft. scribed N 1/4 S1 CS BT.

59

RE-RENEWED, SEE CORNER NO. #120

Fd. ok Bum 1983
Vol. 44 Pg. 17444