

Douglas County Surveyor's Record of  
Government Corners Renewed

T 23 S T. S. R 5 W. R. W. W. M.

KONE-CHAPMAN CO., EUGENE, ORE. 97101

60

$\frac{1}{4}$  Section Corner to Sections 1 and 12.  
Found - Orig. 16", now 46" B.O. S.65°E. 160.4 ft. I open &  
find good scribe marks. This BT. has been rescribed  
about 10 years ago.

SEE THEIL'S  
BOOK 20 P. 25

No trace of Orig. N.W. BT. found.  
Also find 15" x 15" x 12" Stone at Corner.

Set Brass Cap alongside Corner Stone marked County Surveyor's  
Office, 1960  $\frac{1}{4}$  S 1 T23S R5W  
S12

New BT's: 9" R. Fir bears S.43°E. 117.5 ft. scribed  $\frac{1}{4}$  S12 CS BT.  
I find 24" W. Oak bears N. 2°E. 90.5 ft., shows good  
blazed scribed about 10 years ago.

OK 9/93 M119-5

61

Standard Corner to Sec. 1, T23S R5W, Sec. 6, T23S R4W,  
Found - Orig. 14", now 34" W. Oak N.80°W. 1091.0 ft. Theil  
rescribed this BT. years ago. I open back of his  
scribing & find Orig. scribing "WR".

Also find 2" Iron Pipe at corner. Turpin says Theil  
set this pipe for corner.

Closing Corner 4.59 ch. West, Not Found.

New BT: 26" Maple bears N.80 $\frac{1}{2}$ °W. 475.0 ft. scribed S36 T22S R5W CS BT.  
No other Trees near.

$\frac{3}{4}$ " Iron Rod with 4" x 4" White Post bears S.55°E. 88.2 ft.  
Post marked SHRW L PT 722 + 72.44.

62

Section Corner to Sections 15, 16, 21, and 22.

Found - Orig. 18", now 24" Oak, down, N.82 $\frac{1}{2}$ °W. 118.1 ft. I open  
& find good reverse scribing "3 or BT". This BT.  
was cut years ago & is now in ditch line. I do not  
find stump, believe it was in ditch at butt of Tree.

Also find Oak Stump Hole that checks record bearing &  
distance for SW. BT.

Also find 3" x 3" Sq. Oak Stake, old, on ground at  
corner.

No other Orig. BT's. found.

Set Brass Cap at Corner Mkd: S16 | S15 T23S R5W County  
S21 | S22 Surveyor's Office, 1960

New BT's: 8" W. Oak bears N.52°W. 12.4 ft. scribed S16 T23S R5W CS BT.  
10" W. Oak bears N.45°E. 11.8 ft. scribed S15 T23S R5W CS BT.  
7" B. Oak bears S. 5°W. 7.5 ft. scribed S21 T23S R5W CS BT.  
R. Fir bears S.75°E. 74.4 ft. scribed S22 T23S R5W CS BT.

Section Corner to Sections 9, 10, 15, and 16.

Found - One Orig. BT. only, Orig. 14", now 33" B.Oak S.46°E. 83.2 ft.,  
shows parts of good reverse scribing. Also found Stump  
holes that check record for NW & NE BT's.

Note - Johnson renewed this corner. He found same Orig. BT. used  
record bearing but used 71.6 ft. record ~~83.2 ft.~~ I leave Rev. #19  
 $\frac{3}{4}$ " Iron Rod set by Johnson for corner, which is under  
new fence. I destroy scribing on his SW BT.

Set Brass Cap at Corner Mkd: S9 | S10 T23S R5W County Surveyor's  
S16 | S15 Office, 1960

New BT's: 15" R. Fir S.18°W. 27.2 ft. scribed S16 T23S R5W CS BT.  
7" R. Fir S.49°E. 47.9 ft. scribed S15 T23S R5W CS BT.  
4" B.Oak N.83°E. 15.5 ft. (Johnson's BT)  
15" R. Fir N.65°W. 4.4 ft. (Johnson's BT)

RE-RENEWED

Note - Johnson's BT's not rescribed.

63

$\frac{1}{4}$  Section Corner to Section 15 and 16.

Found - Orig. 14", now 34" down Oak N.61°E. 38.3 ft. I open & find  
good scribing " $\frac{1}{4}$ ".

Orig. SW BT. not found.

Also found 8" x 12" x 2" Stone at Corner.

Set Brass Cap alongside Corner Stone Mkd: County Surveyor's Office, 1960  
 $\frac{1}{4}$  S16/S15 T23S R5W.

New BT's: 10" W. Oak bears S.32°W. 15.5 ft. scribed  $\frac{1}{4}$  S16 CS BT.

9" W. Oak bears N.45°E. 4.3 ft. scribed  $\frac{1}{4}$  S15 CS BT.

Note - N. S. Fence 3' South of Corner

64

James W. Byron, Deputy Surveyor  
Milo Godfrey  
Clete Putnam  
January 19, 1960  
C. S. File No. 49/42